

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: DIRTY [x] EXT: CLEAN [x]
Owner :		Mileage :	167572 KM
File nr. :	1416190	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1EYS079 / WAUZZZ8K1DN047065 /		yr of constructionr :	/
E-File nr. :		First registration :	23/04/2013
VFS-nr. :		Color :	GREY
Make + Model :	AUDI / A4	Fuel type :	DIESEL
Object nr. :	9461	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	KUMPEN NV	Co2:	117g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	A4 BER TDi 120PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:	BERLINE	Engine size:	1968
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	4
HP:	120	kW:	88
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:			

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:		Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :	
Warning vest :	OK	[x]	Transport licence :	
Tax certificate :			Navigation CD/SD/DVD	
Fuel card :			Car radio :	OK [x]
Mobile phone kit :			Extinguisher :	OK [x]
First aid kit :	OK	[x]	Warning triangle :	OK [x]
Jack, wheelspanner :	OK	[x]	Oil level :	OK [x]
			Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	[x]	BRIDGESTONE	Tyre :	OK	[x]	4-6/	Rim :	/	Hubcap :	
Wheel RL :	[x]	UNIROYAL	Tyre :	OK	[x]	4-6/	Rim :	/	Hubcap :	
Wheel FR :	[x]	BRIDGESTONE	Tyre :	[x]	OK	[x]	4-6/	Rim :	/	Hubcap :
Wheel RR :	[x]	UNIROYAL	Tyre :	OK	[x]	4-6/	Rim :	/	Hubcap :	
Wheel RES:	[x]	ANDERE	Tyre :	OK	[x]	>6/	Rim :	/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	225	55	R	16	V
Rear tyre	225	55	R	16	V

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR BUMPER/CENTER/RIGHT	SCRATCH WITH PAINT DAMAGE		
[x]	REAR MUDGUARD/LEFT/CENTER	SCRATCH (WITHOUT PAINT DAMAGE)		
[x]	REAR DOOR/RIGHT/REAR	DENT		
[x]	REAR THRESHOLD/RIGHT/REAR	SCRATCH WITH PAINT DAMAGE	SLUITKANT	
[x]	FRONT THRESHOLD/LEFT/REAR	DENT	SLUITKANT	
[x]	FRONT BUMPER/LEFT/CORNER	SCRATCH WITH PAINT DAMAGE		

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	ROOF STYLE/FRONT/LEFT/CENTER	DENT	MET LAKSCHADE			
		Repair paint - LI	New paint - E	Depr.	Total	
2	10 LU =48.00 EUR	220.18 EUR		50 %	268.18 EUR	
[x]	WINDSCREEN/BELOW/LEFT	WINDOW DAMAGE				
		Repair paint - LI	New paint - E	Depr.	Total	
3	25 LU =120.00 EUR	0 EUR		50 %	120.00 EUR	
[x]	BONNET/CENTER/RIGHT	OTHER DAMAGES	SLECHTE HERSTELLING LAKWERK			
	Number	Code	Description	Unit price	Depr.	Total
0	0					

Others

CLEANLINESS INTERIOR

Number	Code	Description	Unit price	Depr.	Total
1	I 3	specifiek-per-kwartier-a-vab-rein-03 CLEANING INTERIOR	14.58 EUR		43.74 EUR

Pieces

Number	Code	Description	Unit price	Depr.	Total
3	1	WIND SCREEN	367.20 EUR	50 %	367.20 EUR

1	2	3	4	5	6	7	8	9	10
43.74	268.18	487.20	0	0	0	0	0	0	0
43.74	134.09	243.60	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
43.74	755.38	0	799.12
HOG: 0	BG: 0		NA Deprec. 421.43
			0.00%
			TOTAL 421.43

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 07/07/2017 Hour : 08:25 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	