

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

| | | | |
|-------------------------------------|-----------------------------------|---------------------------------|-------------------------------|
| Commissionar : | KBC REMARKETING | Cleanliness : | INT: DIRTY [x] EXT: DIRTY [x] |
| Owner : | | Mileage : | 64361 KM |
| File nr. : | 1417540 | Mileage start / arrival: | 0 / 0 |
| Reg number / Chassis / Ref : | | Mileag ref. service : | 0 |
| 1EEW682 / WAUZZZ8U3DR040936 / | | yr of constructionr : | / |
| E-File nr. : | | First registration : | 12/11/2012 |
| VFS-nr. : | | Color : | GREY |
| Make + Model : | AUDI / Q3 | Fuel type : | DIESEL |
| Object nr. : | 64906 | Fuel : | |
| Classification : | | Environment Class: | EURO 5 |
| Customer company : | K.U. LEUVEN - UZ LEUVEN | Co2: | 156g/km |
| Driver : | | Remote controls: | 2 |
| Covering : | LEATHER | Number keys : | 2 [x] |
| Vehicle kind : | VEHICLE | Seats (minivan) : | 0 |
| Vehicle type : | Q3 Quattro S-line S-tr.163PK Aut. | Country registration : | BELGIUM |

| | | | |
|-------------------------------------|-------------------|----------------------------|---------|
| VAT over the margin - car: | | Metallic paint: | Yes |
| Variant car: | SUV | Engine size: | 1968 |
| Gear box : | Automaat algemeen | Number of places: | 5 |
| Number of gears: | | Number of doors: | 5 |
| HP: | 163 | kW: | 120 |
| Fisc HP | | Imported vehicle: | |
| Animals transported: | | Smoked in vehicle: | |
| Due date vehicle inspection: | | Extra set of tires: | |
| | | Use: | Unknown |
| General condition: | | | |

| | | | | |
|------------------------------|----|-----------------------|-------------------------|--------|
| Original registr. number : | OK | Service manual : | OK | [x] |
| Cert. of reg. / Part 1: | | Cert. of conformity : | OK | |
| Cert. of reg. copy / Part 2: | OK | [x] | Insurance certificate : | |
| Warning vest : | OK | [x] | Transport licence : | |
| Tax certificate : | | | Navigation CD/SD/DVD | |
| Fuel card : | | | Car radio : | |
| Mobile phone kit : | | | Extinguisher : | OK [x] |
| First aid kit : | OK | [x] | Warning triangle : | OK [x] |
| Jack, wheelspanner : | OK | [x] | Oil level : | OK [x] |
| | | | Filled up : | 0 |

Wheels and tyres: Summer tires

| | | | | | | | | | |
|------------|-----|-------------|--------|-----|-----|------|-------|--------------------------------|--------------------------------|
| Wheel FL: | [x] | KLÉBER | Tyre : | OK | [x] | 2-4/ | Rim : | / | Hubcap : |
| Wheel RL : | [x] | CONTINENTAL | Tyre : | OK | [x] | 2-4/ | Rim : | / | Hubcap : |
| Wheel FR : | [x] | KLÉBER | Tyre : | [x] | OK | [x] | 2-4/ | Rim : | [x] WHEEL SCRATCHED / Hubcap : |
| Wheel RR : | [x] | CONTINENTAL | Tyre : | OK | [x] | 2-4/ | Rim : | [x] WHEEL SCRATCHED / Hubcap : | |
| Wheel RES: | [x] | | Tyre : | OK | [x] | >6/ | Rim : | / | Hubcap : |

| [x] | Width | Height | Type | Rim | Index |
|------------|-------|--------|------|-----|-------|
| Front tyre | 235 | 50 | R | 18 | V |
| Rear tyre | 235 | 50 | R | 18 | V |

Remark :

Wheels and tyres:

| | | | | | | | |
|------------|--|--------|----|---|-------|---|----------|
| Wheel FL: | | Tyre : | OK | / | Rim : | / | Hubcap : |
| Wheel RL : | | Tyre : | OK | / | Rim : | / | Hubcap : |
| Wheel FR : | | Tyre : | OK | / | Rim : | / | Hubcap : |
| Wheel RR : | | Tyre : | OK | / | Rim : | / | Hubcap : |
| Wheel RES: | | Tyre : | OK | / | Rim : | / | Hubcap : |

| [x] | Width | Height | Type | Rim | Index |
|------------|-------|--------|------|-----|-------|
| Front tyre | 0 | 0 | R | 0 | |
| Rear tyre | 0 | 0 | R | 0 | |

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

| | | |
|-----|---------------------------|---------------------------|
| [x] | REAR MUDGUARD/LEFT/CENTER | SCRATCH WITH PAINT DAMAGE |
| [x] | FRONT DOOR/LEFT/REAR | DENT |
| [x] | FRONT DOOR/RIGHT/CENTER | SCRATCH WITH PAINT DAMAGE |

STATUS: NOT ACCEPTABLE

Bodywork \& windows

| | | | | | |
|-----|---------------------------|--------------------------------|----------------------|--------------|--------------|
| [x] | REAR BUMPER/CENTER/LEFT | SCRATCH WITH PAINT DAMAGE | | | |
| | | Repair paint - LI | New paint - E | Depr. | Total |
| 5 | 0 LU =0.00 EUR | 211.80 EUR | | 50 % | 211.80 EUR |
| [x] | REAR MUDGUARD/LEFT/FRONT | SCRATCH (WITHOUT PAINT DAMAGE) | | | |
| | | Repair paint - LI | New paint - E | Depr. | Total |
| 4 | 5 LU =24.00 EUR | 0 EUR | | 50 % | 24.00 EUR |
| [x] | REAR MUDGUARD/RIGHT/REAR | SCRATCH WITH PAINT DAMAGE | | + DEUK | |
| | | Repair paint - LI | New paint - E | Depr. | Total |
| 6 | 10 LU =48.00 EUR | 308.20 EUR | | 50 % | 356.20 EUR |
| [x] | REAR DOOR/LEFT/REAR | SCRATCH WITH PAINT DAMAGE | | + DEUK | |
| | | Repair paint - LI | New paint - E | Depr. | Total |
| 3 | 15 LU =72.00 EUR | 318.35 EUR | | 50 % | 390.35 EUR |
| [x] | REAR THRESHOLD/RIGHT/REAR | SCRATCH WITH PAINT DAMAGE | | BINNENSTIJL | |
| | | Repair paint - LI | New paint - E | Depr. | Total |
| 8 | 0 LU =0.00 EUR | 310.50 EUR | | 50 % | 310.50 EUR |
| [x] | FRONT BUMPER/RIGHT/SIDE | SCRATCH (WITHOUT PAINT DAMAGE) | | | |
| | | Repair paint - LI | New paint - E | Depr. | Total |
| 2 | 0 LU =0.00 EUR | 0 EUR | | 50 % | |
| | | Repair paint - LI | New paint - E | Depr. | Total |
| 2 | 5 LU =24.00 EUR | 0 EUR | | 50 % | 24.00 EUR |

Others

CLEANLINESS INTERIOR

| Number | Code | Description | Unit price | Depr. | Total |
|--------|------|-----------------------------|-------------------|-----------|-----------|
| 1 | I 4 | personenwagen-a-vab-rein-02 | CLEANING INTERIOR | 11.47 EUR | 45.88 EUR |

RIM FRONT RIGHT

| Number | Code | Description | Unit price | Depr. | Total |
|--------|------|-------------------|--------------------|-----------|-----------|
| 7 | I 1 | i-vab-herstalu-02 | REPAIR ALLOY WHEEL | 95.00 EUR | 95.00 EUR |

Pieces

| Number | Code | Description | Unit price | Depr. | Total |
|--------|------|--------------------|------------|-------|-----------|
| 2 | 1 | HALF FRONT SPOILER | 30.00 EUR | 50 % | 30.00 EUR |

| Number | Code | Description | Unit price | Depr. | Total |
|--------|------|-------------|------------|-------|-----------|
| 4 | 1 | WHEEL HUL | 60.00 EUR | 50 % | 60.00 EUR |

| 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 |
|-------|-------|--------|-------|--------|--------|-------|--------|---|----|
| 45.88 | 54.00 | 390.35 | 84.00 | 211.80 | 356.20 | 95.00 | 310.50 | 0 | 0 |
| 45.88 | 27.00 | 195.18 | 42.00 | 105.90 | 178.10 | 95.00 | 155.25 | 0 | 0 |

| INNOVATIVE | TRADITIONAL | GENERAL | |
|------------|-------------|---------|---------------------|
| 140.88 | 1406.85 | 0 | 1547.73 |
| HOG: 0 | BG: 0 | | NA Deprec. 844.30 |
| | | | 0.00% |
| | | | TOTAL 844.30 |

[x] = Status Modification


Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

| | | |
|---|--|---|
| Extra Time : 0 min | Waiting time : 0 min Reason : | Towing time : 0 min Reason : |
| NOT EXECUTED : No Reason : | | |
| Remark : | | |

Prices in EUR without VAT

| | |
|---|--------------------------------|
| Authorized by customer : Remark authorized customer : Date : 11/07/2017 Hour : 11:53 Company : Executed by VAB Fleet Services E-Mail : @ | Executed by VAB Fleet Services |
| Signature authorized by customer  | |