

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: DIRTY [x] EXT: CLEAN [x]
Owner :		Mileage :	91745 KM
File nr. :	1417047	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1FGZ617 / WAUZZZ8U1ER007001 /		yr of constructionr :	/
E-File nr. :		First registration :	26/06/2013
VFS-nr. :		Color :	GREY
Make + Model :	AUDI / Q3	Fuel type :	DIESEL
Object nr. :	47065	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	BAXTER BELGIUM SPRL	Co2:	137g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	Q3 136PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:	SUV	Engine size:	1968
Gear box :	5-speed manual gearbox	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	136	kW:	100
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	
Due date vehicle inspection:		Extra set of tires:	
		Use:	Unknown
General condition:			

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:		Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :	
Warning vest :	OK	[x]	Transport licence :	
Tax certificate :			Navigation CD/SD/DVD	
Fuel card :			Car radio :	
Mobile phone kit :			Extinguisher :	OK [x]
First aid kit :	OK	[x]	Warning triangle :	OK [x]
Jack, wheelspanner :	OK	[x]	Oil level :	OK [x]
			Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	[x]	PIRELLI	Tyre :	OK	[x]	4-6/	Rim :	/	Hubcap :	
Wheel RL :	[x]	PIRELLI	Tyre :	OK	[x]	4-6/	Rim :	/	Hubcap :	
Wheel FR :	[x]	PIRELLI	Tyre :	[x]	OK	[x]	4-6/	Rim :	/	Hubcap :
Wheel RR :	[x]	PIRELLI	Tyre :	OK	[x]	4-6/	Rim :	/	Hubcap :	
Wheel RES:	[x]		Tyre :	OK	[x]	>6/	Rim :	/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	235	55	R	17	Y
Rear tyre	235	55	R	17	Y

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR DOOR/LEFT/REAR	DENT
[x]	REAR DOOR/RIGHT/CENTER	SCRATCH (WITHOUT PAINT DAMAGE)
[x]	FRONT DOOR/LEFT/REAR	SCRATCH WITH PAINT DAMAGE
[x]	BONNET/CENTER/LEFT/FRONT	SCRATCH (WITHOUT PAINT DAMAGE)
[x]	FRONT BUMPER/CENTER/LEFT	CHIPS

Interior

[x]	DOOR IN REAR RIGHT	CARVED
[x]	BOOT LID IN	CARVED
[x]	BOOT IN L	CARVED
[x]	BOOT IN R	CARVED

Accessories and others

[x]	OUTSIDE MIRROR LEFTHAND SIDE	SCRATCH WITH PAINT DAMAGE
-----	------------------------------	---------------------------

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR BUMPER/CENTER/LEFT	SCRATCH WITH PAINT DAMAGE				
			Repair paint - LI	New paint - E	Depr.	Total
2	0 LU =0.00 EUR	211.80 EUR			50 %	211.80 EUR

[x]	REAR DOOR/CENTER/LEFT	DENT						
			Number	Code	Description	Unit price	Depr.	Total
3	I 1	i-vab-uitd-01			BEAT OUT DENT	63.00 EUR		63.00 EUR

[x]	FRONT DOOR/RIGHT/REAR	DENT						
			Number	Code	Description	Unit price	Depr.	Total
4	I 1	i-vab-uitd-01			BEAT OUT DENT	63.00 EUR		63.00 EUR

Others

CLEANLINESS INTERIOR

			Number	Code	Description	Unit price	Depr.	Total
1	I 5	personenwagen-a-vab-rein-02			CLEANING INTERIOR	11.47 EUR		57.35 EUR

1	2	3	4	5	6	7	8	9	10
57.35	211.80	63.00	63.00	0	0	0	0	0	0
57.35	105.90	63.00	63.00	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
183.35	211.80	0	395.15
HOG: 0	BG: 0		NA Deprec. 289.25
			0.00%
			TOTAL 289.25

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 11/07/2017 Hour : 08:58 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	