

BXJH97

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: DIRTY [x]
Owner :		Mileage :	61837 KM
File nr. :	1418992	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
MC0810 / WAUZZZ8U3ER077552 /		yr of constructionr :	/
E-File nr. :		First registration :	13/06/2014
VFS-nr. :		Color :	BLACK
Make + Model :	AUDI / Q3	Fuel type :	DIESEL
Object nr. :	ONBEKEND	Fuel :	
Classification :		Environment Class:	
Customer company :	ONBEKEND	Co2:	g/km
Driver :		Remote controls:	2
Covering :	PARTIAL LEATHER	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :		Country registration :	LUXEMBOURG

VAT over the margin - car:		Metallic paint:	Yes
Variant car:		Engine size:	
Gear box :	Automaat algemeen	Number of places:	5
Number of gears:		Number of doors:	5
HP:		kW:	
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	
Due date vehicle inspection:		Extra set of tires:	
		Use:	Unknown
General condition:			

Original registr. number :		Service manual :	OK	[x]
Cert. of reg. / Part 1:		Cert. of conformity :		
Cert. of reg. copy / Part 2:		Insurance certificate :		
Warning vest :	OK	Transport licence :		
Tax certificate :		Navigation CD/SD/DVD		
Fuel card :		Car radio :		
Mobile phone kit :		Extinguisher :	OK	[x]
		Warning triangle :	OK	[x]
First aid kit :	OK	Oil level :	OK	[x]
Jack, wheelspanner :	OK	Filled up :	0	

Wheels and tyres: Summer tires

Wheel FL:	[x]	PIRELLI	Tyre :	OK	[x]	2-4/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :
Wheel RL :	[x]	PIRELLI	Tyre :	OK	[x]	4-6/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :
Wheel FR :	[x]	PIRELLI	Tyre :	[x]	OK	[x]	2-4/	Rim :		/	Hubcap :
Wheel RR :	[x]	PIRELLI	Tyre :	OK	[x]	4-6/	Rim :			/	Hubcap :
Wheel RES:	[x]	CONTINENTAL	Tyre :	OK	[x]	>6/	Rim :			/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	255	40	R	19	Y
Rear tyre	255	40	R	19	Y

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :		/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR DOOR/CENTER/LEFT	CHIPS
[x]	REAR DOOR/RIGHT/FRONT	SCRATCH (WITHOUT PAINT DAMAGE)
[x]	FRONT DOOR/LEFT/REAR	SCRATCH WITH PAINT DAMAGE
[x]	FRONT DOOR/LEFT/FRONT	DENT
[x]	FRONT DOOR/RIGHT/FRONT	SCRATCH (WITHOUT PAINT DAMAGE)
[x]	BONNET/CENTER/LEFT/FRONT	CHIPS
[x]	FRONT BUMPER/CENTER/LEFT	CHIPS

Interior

[x]	BOOT LID IN	CARVED
-----	-------------	--------

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR BUMPER/CENTER/LEFT	SCRATCH WITH PAINT DAMAGE		
	Repair paint - LI	New paint - E	Depr.	Total
2	0 LU =0.00 EUR	211.80 EUR	50 %	211.80 EUR

Others

RIM REAR LEFT

Number	Code	Description	Unit price	Depr.	Total
3	I 1 i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

1	2	3	4	5	6	7	8	9	10
0	211.80	95.00	0	0	0	0	0	0	0
0	105.90	95.00	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
95.00	211.80	0	306.80
HOG: 0	BG: 0		NA Deprec. 200.90
			0.00%
			TOTAL 200.90

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark : DOCUMENTEN WORDEN NAGESTUURD [x]		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 11/07/2017 Hour : 13:15 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	