

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: DIRTY [x]
Owner :		Mileage :	77216 KM
File nr. :	1416115	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1DPH055 / WAUZZZ8R4CA082489 /		yr of constructionr :	/
E-File nr. :		First registration :	12/07/2012
VFS-nr. :		Color :	GREY
Make + Model :	AUDI / Q5	Fuel type :	DIESEL
Object nr. :	76721	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	UZ BRUSSEL	Co2:	184g/km
Driver :		Remote controls:	2
Covering :	LEATHER	Number keys :	2 [x]
Vehicle kind :		Seats (minivan) :	0
Vehicle type :	Q5 S Tronic DPF 163PK aut	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:	SUV	Engine size:	1968
Gear box :	Automaat algemeen	Number of places:	5
Number of gears:		Number of doors:	5
HP:	163	kW:	120
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:			

Original registr. number : OK	Service manual : OK [x]
Cert. of reg. / Part 1:	Cert. of conformity : OK
Cert. of reg. copy / Part 2: OK [x]	Insurance certificate :
Warning vest :	Transport licence :
Tax certificate :	Navigation CD/SD/DVD
Fuel card :	Car radio : OK [x]
Mobile phone kit :	Extinguisher :
First aid kit :	Warning triangle : OK [x]
Jack, wheelspanner : OK [x]	Oil level : OK [x]
	Filled up : 0

Wheels and tyres: Winter tires

Wheel FL: [x] PIRELLI Tyre : OK [x] 4-6/ Rim : / Hubcap :
Wheel RL : [x] SEMPERIT Tyre : OK [x] 4-6/ Rim : / Hubcap :
Wheel FR : [x] PIRELLI Tyre : [x] OK [x] 4-6/ Rim : / Hubcap :
Wheel RR : [x] SEMPERIT Tyre : OK [x] 4-6/ Rim : / Hubcap :
Wheel RES: [x] PIRELLI Tyre : OK [x] >6/ Rim : / Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	235	60	R	18	M+S
Rear tyre	235	60	R	18	M+S

Remark :

Wheels and tyres:

Wheel FL: Tyre : OK / Rim : / Hubcap :
Wheel RL : Tyre : OK / Rim : / Hubcap :
Wheel FR : Tyre : OK / Rim : / Hubcap :
Wheel RR : Tyre : OK / Rim : / Hubcap :
Wheel RES: Tyre : OK / Rim : / Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

Conclusion

Bodywork \& windows

[x] WINDSCREEN/BELOW/LEFT CHIPS

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x] REAR DOOR/LEFT/CENTER SCRATCH (WITHOUT PAINT DAMAGE)

[x] BONNET/CENTER/RIGHT DENT

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x] REAR BUMPER/CENTER/LEFT DENT

	Repair paint - LI	New paint - E	Depr.	Total
2 0 LU =0.00 EUR	254.16 EUR		50 %	254.16 EUR

[x] ROOF/CENTER/RIGHT SCRATCH WITH PAINT DAMAGE DEGATS CHIMIQUE

	Repair paint - LI	New paint - E	Depr.	Total
4 0 LU =0.00 EUR	577.80 EUR		50 %	577.80 EUR

[x] REAR DOOR/RIGHT/REAR SCRATCH WITH PAINT DAMAGE MEERDERE

	Repair paint - LI	New paint - E	Depr.	Total
3 0 LU =0.00 EUR	382.02 EUR		50 %	382.02 EUR

[x] FRONT DOOR/RIGHT/REAR DENT

	Repair paint - LI	New paint - E	Depr.	Total
3 0 LU =0.00 EUR	382.02 EUR		50 %	382.02 EUR

[x] FRONT BUMPER/LEFT SCRATCH WITH PAINT DAMAGE

Number	Code	Description	Unit price	Depr.	Total
1	I 1 i-vab-sp-01	SPOTREPAIR	115.56 EUR		115.56 EUR

[x] FRONT BUMPER/CENTER/LEFT HOLE/CRACK/TORN

	Repair paint - LI	New paint - E	Depr.	Total
1 5 LU =24.00 EUR	0 EUR		50 %	24.00 EUR

Pieces

Number	Code	Description	Unit price	Depr.	Total
1	1	KLIEPJE SPROEIRS	100.00 EUR	50 %	100.00 EUR

1	2	3	4	5	6	7	8	9	10
239.56	254.16	764.04	577.80	0	0	0	0	0	0
177.56	127.08	382.02	288.90	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
115.56	1720.00	0	1835.56
HOG: 0	BG: 2		NA Deprec. 975.56
			0.00%
			TOTAL 975.56

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

UNDER CONDITION - DUSTY VEHICLE

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 04/07/2017 Hour : 15:27 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	