

EFFECTIVE     NOT EXECUTED                       COLLECTION                       DELIVERY

[x] = Status Modification

<b>Commissionar :</b>	KBC REMARKETING	<b>Cleanliness :</b>	INT: CLEAN [x] EXT: CLEAN [x]
<b>Owner :</b>		<b>Mileage :</b>	81541 KM
<b>File nr. :</b>	1418125	<b>Mileage start / arrival:</b>	0 / 0
<b>Reg number / Chassis / Ref :</b>		<b>Mileag ref. service :</b>	0
1EGD432 / WAUZZZ8R9DA027828 /		<b>yr of constructionr :</b>	/
<b>E-File nr. :</b>		<b>First registration :</b>	22/11/2012
<b>VFS-nr. :</b>		<b>Color :</b>	GREY
<b>Make + Model :</b>	AUDI / Q5	<b>Fuel type :</b>	DIESEL
<b>Object nr. :</b>	68944	<b>Fuel :</b>	
<b>Classification :</b>		<b>Environment Class:</b>	EURO 5
<b>Customer company :</b>	Nyrstar nv	<b>Co2:</b>	139g/km
<b>Driver :</b>		<b>Remote controls:</b>	2
<b>Covering :</b>	LEATHER	<b>Number keys :</b>	2 [x]
<b>Vehicle kind :</b>	VEHICLE	<b>Seats (minivan) :</b>	0
<b>Vehicle type :</b>	Q5 136PK	<b>Country registration :</b>	BELGIUM

<b>VAT over the margin - car:</b>		<b>Metallic paint:</b>	Yes
<b>Variant car:</b>	SUV	<b>Engine size:</b>	1968
<b>Gear box :</b>	Manueel	<b>Number of places:</b>	5
<b>Number of gears:</b>	6	<b>Number of doors:</b>	5
<b>HP:</b>	136	<b>kW:</b>	100
<b>Fisc HP</b>		<b>Imported vehicle:</b>	
<b>Animals transported:</b>		<b>Smoked in vehicle:</b>	
<b>Due date vehicle inspection:</b>		<b>Extra set of tires:</b>	
		<b>Use:</b>	Unknown
<b>General condition:</b>			

Original registr. number :	OK	Service manual :	OK
Cert. of reg. / Part 1:	OK	Cert. of conformity :	OK
Cert. of reg. copy / Part 2:		Insurance certificate :	
Warning vest :		Transport licence :	
Tax certificate :		Navigation CD/SD/DVD	
Fuel card :		Car radio :	OK
Mobile phone kit :		Extinguisher :	OK
First aid kit :	OK	Warning triangle :	OK
Jack, wheelspanner :	OK	Oil level :	OK
		Filled up :	0

## Wheels and tyres: Summer tires

Wheel FL:	DUNLOP	Tyre :	OK	4-6/	Rim :	/	Hubcap :
Wheel RL :	DUNLOP	Tyre :	OK	4-6/	Rim :	/	Hubcap :
Wheel FR :	DUNLOP	Tyre :	OK	4-6/	Rim :	/	Hubcap :
Wheel RR :	DUNLOP	Tyre :	OK	4-6/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

  

	Width	Height	Type	Rim	Index
Front tyre	235	65	R	17	V
Rear tyre	235	65	R	17	V

Remark :

## Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

  

	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

## STATUS: ACCEPTABLE / USAGE DAMAGE

### Bodywork \& windows

- [x] FRONT DOOR/LEFT/FRONT DENT
- [x] FRONT DOOR/RIGHT/REAR SCRATCH WITH PAINT DAMAGE
- [x] BONNET/CENTER/RIGHT SCRATCH WITH PAINT DAMAGE
- [x] BONNET/CENTER/LEFT/FRONT SCRATCH WITH PAINT DAMAGE

## STATUS: NOT ACCEPTABLE

### Bodywork \& windows

[x]	REAR BUMPER/CENTER/LEFT		HOLE/CRACK/TORN					
		<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>			
3	5 LU =24.00 EUR	254.16 EUR		50 %	278.16 EUR			
[x]	REAR DOOR/RIGHT/REAR		SCRATCH WITH PAINT DAMAGE					
		<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>			
4	0 LU =0.00 EUR	382.02 EUR		50 %	382.02 EUR			
[x]	FRONT MUDGUARD/RIGHT/FRONT		DENT					
		<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>			
5	25 LU =120.00 EUR	0 EUR	284.66 EUR	50 %	404.66 EUR			
[x]	FRONT BUMPER/RIGHT/SIDE		SCRATCH WITH PAINT DAMAGE					
		<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>			
2	0 LU =0.00 EUR	254.16 EUR		50 %	254.16 EUR			

### Pieces

Number	Code	Description	Unit price	Depr.	Total
3	1	REFLECTOR	90.00 EUR	50 %	90.00 EUR
Number	Code	Description	Unit price	Depr.	Total
5	1	FENDER FR	207.36 EUR	50 %	207.36 EUR

1	2	3	4	5	6	7	8	9	10
0	254.16	368.16	382.02	612.02	0	0	0	0	0
0	127.08	184.08	191.01	306.01	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
0	1616.36	0	<b>1616.36</b>
HOG: 0	BG: 2		NA Deprec. 808.18
			0.00%
			<b>TOTAL 808.18</b>

[x] = Status Modification

Pictures : No

## CIRCUMSTANCES

<b>Extra Time :</b> 0 min	<b>Waiting time :</b> 0 min <b>Reason :</b>	<b>Towing time :</b> 0 min <b>Reason :</b>
<b>NOT EXECUTED :</b> No <b>Reason :</b>		
<b>Remark :</b>		

## Prices in EUR without VAT

<b>Authorized by customer :</b>  <b>Remark authorized customer :</b>  <b>Date :</b> 13/07/2017 <b>Hour :</b> 13:52 <b>Company :</b> Executed by VAB Fleet Services <b>E-Mail :</b> @	Executed by VAB Fleet Services
Signature authorized by customer 	