

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	68742 KM
File nr. :	1417216	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1HRT574 / WBA1C91010P695740 /		yr of constructionr :	/
E-File nr. :		First registration :	16/09/2014
VFS-nr. :		Color :	BLUE
Make + Model :	BMW / 1 HATCH	Fuel type :	DIESEL
Object nr. :	32539	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	ERNST & YOUNG ACCOUNTANTS CVBA	Co2:	99g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :		Country registration :	BELGIUM

VAT over the margin - car:		Metallic paint:	Yes
Variant car:		Engine size:	1598
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	116	kW:	85
Fisc HP		Imported vehicle:	No
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:			

Original registr. number :	OK	Service manual :	
Cert. of reg. / Part 1:	OK [x]	Cert. of conformity :	OK
Cert. of reg. copy / Part 2:		Insurance certificate :	
Warning vest :	OK [x]	Transport licence :	
Tax certificate :		Navigation CD/SD/DVD	
Fuel card :		Car radio :	OK [x]
Mobile phone kit :		Extinguisher :	OK [x]
First aid kit :	OK [x]	Warning triangle :	OK [x]
Jack, wheelspanner :		Oil level :	OK [x]
		Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	[x]	GOODYEAR	Tyre :	OK [x]	>6/	Rim :	/	Hubcap :	[x]	SCRATCHED
Wheel RL :	[x]	GOODYEAR	Tyre :	OK [x]	2-4/	Rim :	/	Hubcap :	[x]	SCRATCHED
Wheel FR :	[x]	GOODYEAR	Tyre :	[x] OK [x]	>6/	Rim :	/	Hubcap :		
Wheel RR :	[x]	GOODYEAR	Tyre :	OK [x]	2-4/	Rim :	/	Hubcap :	[x]	SCRATCHED
Wheel RES:	[x]		Tyre :	OK	/	Rim :	/	Hubcap :		

[x]	Width	Height	Type	Rim	Index
Front tyre	205	55	R	16	T
Rear tyre	205	55	R	16	T

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x] FRONT DOOR/RIGHT/CENTER DENT

STATUS: NOT ACCEPTABLE

Others

HUB CAP FL

	Repair paint - LI	New paint - E	Depr.	Total
1 0 LU =0.00 EUR			50 %	

HUB CAP REAR L

	Repair paint - LI	New paint - E	Depr.	Total
1 0 LU =0.00 EUR			50 %	

HUB CAP REAR RIGHT

	Repair paint - LI	New paint - E	Depr.	Total
1 0 LU =0.00 EUR			50 %	

Pieces

Number	Code	Description	Unit price	Depr.	Total
1	1	WHEEL CAP	36.00 EUR	50 %	36.00 EUR

Number	Code	Description	Unit price	Depr.	Total
1	1	WHEEL CAP	36.00 EUR	50 %	36.00 EUR

Number	Code	Description	Unit price	Depr.	Total
1	1	WHEEL CAP	36.00 EUR	50 %	36.00 EUR

1	2	3	4	5	6	7	8	9	10
108.00	0	0	0	0	0	0	0	0	0
54.00	0	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
0	108.00	0	108.00
HOG: 0	BG: 2		NA Deprec. 54.00
			0.00%
			TOTAL 54.00

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 07/07/2017 Hour : 15:18 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	