

EFFECTIVE     NOT EXECUTED                       COLLECTION                       DELIVERY

[x] = Status Modification

<b>Commissionar :</b>	KBC REMARKETING	<b>Cleanliness :</b>	INT: CLEAN [x] EXT: CLEAN [x]
<b>Owner :</b>		<b>Mileage :</b>	108054 KM
<b>File nr. :</b>	1414028	<b>Mileage start / arrival:</b>	0 / 0
<b>Reg number / Chassis / Ref :</b>		<b>Mileag ref. service :</b>	0
1FFD382 / WBA3K91060F930957 /		<b>yr of constructionr :</b>	/
<b>E-File nr. :</b>		<b>First registration :</b>	12/06/2013
<b>VFS-nr. :</b>		<b>Color :</b>	BLACK
<b>Make + Model :</b>	BMW / 3	<b>Fuel type :</b>	DIESEL
<b>Object nr. :</b>		<b>Fuel :</b>	
<b>Classification :</b>		<b>Environment Class:</b>	EURO 5
<b>Customer company :</b>	KINEPOLIS GROUP NV (GROUP)	<b>Co2:</b>	119g/km
<b>Driver :</b>		<b>Remote controls:</b>	2
<b>Covering :</b>	IMITATION LEATHER	<b>Number keys :</b>	2 [x]
<b>Vehicle kind :</b>	VEHICLE	<b>Seats (minivan) :</b>	0
<b>Vehicle type :</b>	3 TOURING 316d 116PK	<b>Country registration :</b>	BELGIUM

<b>VAT over the margin - car:</b>	No	<b>Metallic paint:</b>	
<b>Variant car:</b>	BREAK	<b>Engine size:</b>	1995
<b>Gear box :</b>	Manueel	<b>Number of places:</b>	5
<b>Number of gears:</b>	6	<b>Number of doors:</b>	5
<b>HP:</b>	116	<b>kW:</b>	85
<b>Fisc HP</b>		<b>Imported vehicle:</b>	No
<b>Animals transported:</b>	No	<b>Smoked in vehicle:</b>	No
<b>Due date vehicle inspection:</b>		<b>Extra set of tires:</b>	No
		<b>Use:</b>	Unknown
<b>General condition:</b>			

Original registr. number : OK	Service manual :
Cert. of reg. / Part 1:	Cert. of conformity : OK
Cert. of reg. copy / Part 2: OK	Insurance certificate :
Warning vest : OK	Transport licence :
Tax certificate :	Navigation CD/SD/DVD
Fuel card :	Car radio : OK
Mobile phone kit :	Extinguisher : OK
First aid kit : OK	Warning triangle : OK
Jack, wheelspanner : OK	Oil level : OK
	Filled up : 0

## Wheels and tyres: Summer tires

Wheel FL:	MICHELIN	Tyre :	OK	2-4/	Rim :	/	Hubcap :	[x] SCRATCHED
Wheel RL :	MICHELIN	Tyre :	OK	2-4/	Rim :	/	Hubcap :	
Wheel FR :	MICHELIN	Tyre :	OK	2-4/	Rim :	/	Hubcap :	SCRATCHED
Wheel RR :	MICHELIN	Tyre :	OK	2-4/	Rim :	/	Hubcap :	SCRATCHED
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :	

  

	Width	Height	Type	Rim	Index
Front tyre	205	60	R	16	V
Rear tyre	205	60	R	16	V

Remark :

## Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :	

  

	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

## STATUS: ACCEPTABLE / USAGE DAMAGE

### Bodywork \& windows

REAR BUMPER/LEFT/LEFT	SCRATCH (WITHOUT PAINT DAMAGE)
REAR MUDGUARD/LEFT/FRONT	DENT
REAR DOOR/LEFT/CENTER	DENT
REAR DOOR/LEFT/FRONT	DENT
REAR DOOR/RIGHT/CENTER	DENT
FRONT DOOR/LEFT/REAR	DENT
WINDSCREEN/CENTER/LEFT	CHIPS
BONNET/CENTER/LEFT/FRONT	CHIPS

## STATUS: NOT ACCEPTABLE

### Bodywork \& windows

[x]	FRONT DOOR/RIGHT/CENTER	DENT		DIV DEUKEN		
	<b>Number</b>	<b>Code</b>	<b>Description</b>	<b>Unit price</b>	<b>Depr.</b>	<b>Total</b>
2	I 1	i-vab-uitd-01	BEAT OUT DENT	63.00 EUR		63.00 EUR
	<b>Number</b>	<b>Code</b>	<b>Description</b>	<b>Unit price</b>	<b>Depr.</b>	<b>Total</b>
2	I 1	i-vab-uitd-02	BEAT OUT DENT SUPPL	19.80 EUR		19.80 EUR
[x]	FRONT BUMPER/CENTER/LEFT	DENT		+KRASSEN		
		<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>	
1	20 LU =96.00 EUR	0 EUR	235.80 EUR	50 %	331.80 EUR	

### Others

HUB CAP FR					
		<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>
3	0 LU =0.00 EUR			50 %	

### Pieces

	<b>Number</b>	<b>Code</b>	<b>Description</b>	<b>Unit price</b>	<b>Depr.</b>	<b>Total</b>
1	1		FRONT BUMPER	403.20 EUR	50 %	403.20 EUR
	<b>Number</b>	<b>Code</b>	<b>Description</b>	<b>Unit price</b>	<b>Depr.</b>	<b>Total</b>
3	1		WHEEL CAP	30.00 EUR	50 %	30.00 EUR

1	2	3	4	5	6	7	8	9	10
735.00	82.80	30.00	0	0	0	0	0	0	0
367.50	82.80	15.00	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
82.80	765.00	0	<b>847.80</b>
HOG: 0	BG: 0		NA Deprec. 465.30
			0.00%
			<b>TOTAL 465.30</b>

[x] = Status Modification

Pictures : No

## CIRCUMSTANCES

NORMAL CONCLUSION

<b>Extra Time :</b> 0 min	<b>Waiting time :</b> 0 min <b>Reason :</b>	<b>Towing time :</b> 0 min <b>Reason :</b>
<b>NOT EXECUTED :</b> No <b>Reason :</b>		
<b>Remark :</b>		

## Prices in EUR without VAT

<b>Authorized by customer :</b>  <b>Remark authorized customer :</b>  <b>Date :</b> 29/06/2017 <b>Hour :</b> 09:38 <b>Company :</b> Executed by VAB Fleet Services <b>E-Mail :</b> @	Executed by VAB Fleet Services
Signature authorized by customer 	