

BRYGKR

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: DIRTY [x] EXT: CLEAN [x]
Owner :		Mileage :	177671 KM
File nr. :	1414594	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1DMF980 / WBA3E11090F297900 /		yr of constructionr :	/
E-File nr. :		First registration :	21/06/2012
VFS-nr. :		Color :	RED
Make + Model :	BMW / 3	Fuel type :	DIESEL
Object nr. :	46166	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	HOSPITAL LOGISTICS NV	Co2:	1098g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	3 BER 320d Eff.Dynamics Ed.163PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:	BERLINE	Engine size:	1995
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	4
HP:	163	kW:	120
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown

General condition:

Original registr. number : OK	Service manual :
Cert. of reg. / Part 1:	Cert. of conformity : OK
Cert. of reg. copy / Part 2: OK	Insurance certificate : OK
Warning vest : OK	Transport licence :
Tax certificate :	Navigation CD/SD/DVD
Fuel card :	Car radio : OK
Mobile phone kit :	Extinguisher : OK
First aid kit : OK	Warning triangle : OK
Jack, wheelspanner :	Oil level : OK
	Filled up : 0

Wheels and tyres: Summer tires

Wheel FL:	MICHELIN	Tyre :	OK	[x]	1.6-2/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :
Wheel RL :	MICHELIN	Tyre :	OK	[x]	2-4/	Rim :			/	Hubcap :
Wheel FR :	MICHELIN	Tyre :	[x]	OK	[x]	1.6-2/	Rim :		/	Hubcap :
Wheel RR :	MICHELIN	Tyre :	OK	[x]	2-4/	Rim :			/	Hubcap :
Wheel RES:		Tyre :	OK		/	Rim :			/	Hubcap :

	Width	Height	Type	Rim	Index
Front tyre	205	60	R	15	W
Rear tyre	205	60	R	15	W

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :		/	Hubcap :

	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	FRONT DOOR/LEFT/CENTER	DENT
[x]	ROOF/FRONT/CENTER/RIGHT	DENT
[x]	FRONT MUDGUARD/LEFT/FRONT	CHIPS

Accessories and others

OUTSIDE MIRROR LEFTHAND SIDE	CHIPS
------------------------------	-------

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	WINDSCREEN/CENTER/LEFT	WINDOW DAMAGE			
		Repair paint - LI New paint - E Depr. Total			
3	25 LU =120.00 EUR	0 EUR	50 %	120.00 EUR	
[x]	BONNET/CENTER/RIGHT/FRONT	DENT			
		Number Code Description Unit price Depr. Total			
2	1 1 i-vab-uitd-01	BEAT OUT DENT	63.00 EUR		63.00 EUR

Interior

[x]	DOOR IN REAR L	CARVED		
		Repair paint - LI New paint - E Depr. Total		
1	5 LU =24.00 EUR	0 EUR	50 %	24.00 EUR

Others

CLEANLINESS INTERIOR					
	Number Code Description Unit price Depr. Total				
1	1 5 specifiek-per-kwartier-a-vab-rein-03	CLEANING INTERIOR	14.58 EUR		72.90 EUR

Pieces

	Number Code Description Unit price Depr. Total				
1	1 UPHOLSTERY DOOR		90.00 EUR	50 %	90.00 EUR
	Number Code Description Unit price Depr. Total				
3	1 WIND SCREEN		367.20 EUR	50 %	367.20 EUR

1	2	3	4	5	6	7	8	9	10
186.90	63.00	487.20	0	0	0	0	0	0	0
129.90	63.00	243.60	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
135.90	601.20	0	737.10
HOG: 0	BG: 0		NA Deprec. 436.50
			0.00%
			TOTAL 436.50

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark : CARNETENTRETIEN ELECTRONIQUE		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 07/07/2017 Hour : 13:48 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	