

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	134617 KM
File nr. :	1417543	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1FEM504 / WBA3D91030F405462 /		yr of constructionr :	/
E-File nr. :		First registration :	07/06/2013
VFS-nr. :		Color :	GREY
Make + Model :	BMW / 3	Fuel type :	DIESEL
Object nr. :	43279	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	BELGACOM INS/FLEET NV	Co2:	114g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	3 BER 316d 116PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	
Variant car:	BERLINE	Engine size:	1995
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	4
HP:	116	kW:	85
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:			

Original registr. number :	OK	Service manual :	NOK [x] MISSING/INCOMPLETE
Cert. of reg. / Part 1:	OK	Cert. of conformity :	OK
Cert. of reg. copy / Part 2:		Insurance certificate :	OK
Warning vest :	OK [x]	Transport licence :	
Tax certificate :		Navigation CD/SD/DVD	
Fuel card :		Car radio :	OK
Mobile phone kit :		Extinguisher :	OK
First aid kit :	OK	Warning triangle :	OK
Jack, wheelspanner :		Oil level :	OK
		Filled up :	0

Wheels and tyres: Winter tires

Wheel FL:	GOODYEAR	Tyre :	OK [x] 1.6-2/	Rim :	/	Hubcap :	SCRATCHED
Wheel RL :	GOODYEAR	Tyre :	OK [x] 2-4/	Rim :	/	Hubcap :	SCRATCHED
Wheel FR :	GOODYEAR	Tyre :	[x] OK [x] 1.6-2/	Rim :	/	Hubcap :	SCRATCHED
Wheel RR :	GOODYEAR	Tyre :	OK [x] 2-4/	Rim :	/	Hubcap :	SCRATCHED
Wheel RES:		Tyre :	OK /	Rim :	MISSING/INCOMPLETE	Hubcap :	

	Width	Height	Type	Rim	Index
Front tyre	205	60	R	16	WINTER H
Rear tyre	205	60	R	16	WINTER H

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK /	Rim :	/	Hubcap :	
Wheel RL :		Tyre :	OK /	Rim :	/	Hubcap :	
Wheel FR :		Tyre :	OK /	Rim :	/	Hubcap :	
Wheel RR :		Tyre :	OK /	Rim :	/	Hubcap :	
Wheel RES:		Tyre :	OK /	Rim :	/	Hubcap :	

	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR DOOR/CENTER/RIGHT	SCRATCH (WITHOUT PAINT DAMAGE)	
[x]	REAR MUDGUARD/LEFT/CENTER	SCRATCH (WITHOUT PAINT DAMAGE)	
[x]	REAR MUDGUARD/RIGHT/FRONT	DENT	X2
[x]	REAR DOOR/LEFT/REAR	SCRATCH WITH PAINT DAMAGE	
[x]	ROOF/REAR/LEFT	SCRATCH (WITHOUT PAINT DAMAGE)	
[x]	ROOF/CENTER/RIGHT	SCRATCH WITH PAINT DAMAGE	
[x]	ROOF STYLE/CENTER/RECHTS	SCRATCH (WITHOUT PAINT DAMAGE)	
[x]	ROOF /FRONT/LEFT/CENTER	DENT	
[x]	FRONT DOOR/RIGHT/FRONT	DENT	
[x]	FRONT MUDGUARD/LEFT/CENTER	SCRATCH WITH PAINT DAMAGE	
[x]	REAR DOOR/LEFT/LEFT	SCRATCH (WITHOUT PAINT DAMAGE)	

Interior

SEAT FR	STAIN
---------	-------

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR DOOR/RIGHT/CENTER	SCRATCH WITH PAINT DAMAGE	+DEUK	
		Repair paint - LI	New paint - E	Depr.
	2	0 LU =0.00 EUR	318.35 EUR	50 %
				Total
				318.35 EUR
[x]	BONNET/CENTER/LEFT	OTHER DAMAGES	MARTERSCHADE	
		Repair paint - LI	New paint - E	Depr.
	3	5 LU =24.00 EUR	0 EUR	50 %
				Total
				24.00 EUR

Interior

FLOOR FL BURNT

Number	Code	Description	Unit price	Depr.	Total
1	I 1	i-vab-inttap-01	CARPET REPAIR (MAX 3CM LENGTH OR DIAMETER)	43.92 EUR	43.92 EUR
1	I 1	i-vab-inttap-02	SUPPL REPAIR CARPET	18.00 EUR	18.00 EUR

Accessories and others

[x] OUTSIDE MIRROR LEFTHAND SIDE BROKEN / CRACKED

Number	Code	Description	Unit price	Depr.	Total
0	0				

Others

HUB CAP REAR RIGHT

	Repair paint - LI	New paint - E	Depr.	Total
4 0 LU =0.00 EUR			50 %	

HUB CAP FR

	Repair paint - LI	New paint - E	Depr.	Total
4 0 LU =0.00 EUR			50 %	

Pieces

Number	Code	Description	Unit price	Depr.	Total
3	1	ISOLATIE	40.00 EUR	50 %	40.00 EUR
4	1	WHEEL CAP	30.00 EUR	50 %	30.00 EUR
4	1	WHEEL CAP	30.00 EUR	50 %	30.00 EUR

1	2	3	4	5	6	7	8	9	10
61.92	318.35	64.00	60.00	0	0	0	0	0	0
61.92	159.18	32.00	30.00	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
61.92	442.35	0	504.27
HOG: 0	BG: 0		NA Deprec. 283.10
			0.00%
			TOTAL 283.10

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark : SCHADE AAN SPIEGEL IS TRANSPORTSCHADE [x]		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 10/07/2017 Hour : 15:52 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	