

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	175715 KM
File nr. :	1413023	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
HG7616 / WBA5C310X0D049614 /		yr of constructionr :	/
E-File nr. :		First registration :	19/06/2014
VFS-nr. :		Color :	GREY
Make + Model :	BMW / 5	Fuel type :	DIESEL
Object nr. :	ONBEKEND	Fuel :	
Classification :	L	Environment Class:	
Customer company :	ONBEKEND	Co2:	g/km
Driver :		Remote controls:	2
Covering :	LEATHER	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :		Country registration :	BELGIUM

VAT over the margin - car:		Metallic paint:	Yes
Variant car:	BERLINE	Engine size:	1995
Gear box :	Automatic clutch	Number of places:	5
Number of gears:		Number of doors:	4
HP:	184	kW:	135
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	
Due date vehicle inspection:		Extra set of tires:	
		Use:	Unknown
General condition:			

Original registr. number :	Service manual :
Cert. of reg. / Part 1:	Cert. of conformity :
Cert. of reg. copy / Part 2:	Insurance certificate :
Warning vest :	Transport licence :
Tax certificate :	Navigation CD/SD/DVD
Fuel card :	Car radio : OK [x]
Mobile phone kit :	Extinguisher :
First aid kit :	Warning triangle : OK [x]
Jack, wheelspanner :	Oil level : OK [x]
	Filled up : 0

Wheels and tyres: Summer tires

Wheel FL:	[x] PIRELLI	Tyre :	OK [x] 4-6/	Rim :	/	Hubcap :
Wheel RL :	[x] PIRELLI	Tyre :	OK [x] 4-6/	Rim :	/	Hubcap :
Wheel FR :	[x] PIRELLI	Tyre :	[x] OK [x] 4-6/	Rim :	/	Hubcap :
Wheel RR :	[x] PIRELLI	Tyre :	OK [x] 4-6/	Rim :	/	Hubcap :
Wheel RES:	[x] PIRELLI	Tyre :	OK /	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	225	55	R	17	V
Rear tyre	225	55	R	17	V

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK /	Rim :	/	Hubcap :
Wheel RL :		Tyre :	OK /	Rim :	/	Hubcap :
Wheel FR :		Tyre :	OK /	Rim :	/	Hubcap :
Wheel RR :		Tyre :	OK /	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK /	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR MUDGUARD/LEFT/CENTER	DENT
[x]	REAR MUDGUARD/RIGHT/REAR	DENT
[x]	REAR DOOR/LEFT/CENTER	SCRATCH (WITHOUT PAINT DAMAGE)
[x]	REAR DOOR/RIGHT/REAR	DENT
[x]	FRONT DOOR/LEFT/CENTER	SCRATCH (WITHOUT PAINT DAMAGE)
[x]	FRONT DOOR/RIGHT/REAR	SCRATCH (WITHOUT PAINT DAMAGE)

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR MUDGUARD/RIGHT/CENTER	DENT			
	Number Code	Description	Unit price	Depr.	Total
2	I 1 i-vab-uitd-01	BEAT OUT DENT	63.00 EUR		63.00 EUR
[x]	REAR THRESHOLD/LEFT/REAR	SCRATCH WITH PAINT DAMAGE			
		Repair paint - LI	New paint - E	Depr.	Total
3	0 LU =0.00 EUR	372.60 EUR		50 %	372.60 EUR
[x]	WINDSCREEN/CENTER/RIGHT	WINDOW DAMAGE		2	
	Number Code	Description	Unit price	Depr.	Total
4	I 1 i-vab-herstr-01	WINDOW REPAIR	58.80 EUR		58.80 EUR
	Number Code	Description	Unit price	Depr.	Total
4	I 1 i-vab-herstr-02	SUPPL WINDOW REPAIR	29.40 EUR		29.40 EUR
[x]	FRONT BUMPER/CENTER/RIGHT	DENT			
		Repair paint - LI	New paint - E	Depr.	Total
1	0 LU =0.00 EUR	254.16 EUR		50 %	254.16 EUR

1	2	3	4	5	6	7	8	9	10
254.16	63.00	372.60	88.20	0	0	0	0	0	0
127.08	63.00	186.30	88.20	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
151.20	626.76	0	777.96
HOG: 0	BG: 2		NA Deprec. 464.58
			0.00%
			TOTAL 464.58

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 05/07/2017 Hour : 11:17 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	