

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

| | | | |
|-------------------------------------|-------------------------------|---------------------------------|-------------------------------|
| Commissionar : | KBC REMARKETING | Cleanliness : | INT: CLEAN [x] EXT: CLEAN [x] |
| Owner : | | Mileage : | 163176 KM |
| File nr. : | 1409665 | Mileage start / arrival: | 0 / 0 |
| Reg number / Chassis / Ref : | | Mileag ref. service : | 0 |
| 1FHG490 / WBAXA51050DW58409 / | | yr of constructionr : | / |
| E-File nr. : | | First registration : | 05/07/2012 |
| VFS-nr. : | | Color : | SILVER |
| Make + Model : | BMW / 5 | Fuel type : | DIESEL |
| Object nr. : | 74419 | Fuel : | |
| Classification : | | Environment Class: | EURO 5 |
| Customer company : | BRUSSELS AIRPORT COMPANY NV | Co2: | 139g/km |
| Driver : | | Remote controls: | 2 |
| Covering : | LEATHER | Number keys : | 2 [x] |
| Vehicle kind : | VEHICLE | Seats (minivan) : | 0 |
| Vehicle type : | 5 BER 530dAS St/St 258PK Aut. | Country registration : | BELGIUM |

| | | | |
|-------------------------------------|-------------------|----------------------------|---------|
| VAT over the margin - car: | No | Metallic paint: | Yes |
| Variant car: | BERLINE | Engine size: | 2993 |
| Gear box : | Automaat algemeen | Number of places: | 5 |
| Number of gears: | | Number of doors: | 4 |
| HP: | 258 | kW: | 190 |
| Fisc HP | | Imported vehicle: | |
| Animals transported: | No | Smoked in vehicle: | No |
| Due date vehicle inspection: | | Extra set of tires: | No |
| | | Use: | Unknown |

General condition:

| | | | | |
|------------------------------|----|------------------|-------------------------|-----|
| Original registr. number : | OK | Service manual : | OK | [x] |
| Cert. of reg. / Part 1: | OK | [x] | Cert. of conformity : | OK |
| Cert. of reg. copy / Part 2: | | [x] | Insurance certificate : | |
| Warning vest : | OK | [x] | Transport licence : | |
| Tax certificate : | | | Navigation CD/SD/DVD | |
| Fuel card : | | | Car radio : | OK |
| Mobile phone kit : | | | Extinguisher : | OK |
| | | | Warning triangle : | OK |
| First aid kit : | OK | [x] | Oil level : | OK |
| Jack, wheelspanner : | | [x] | Filled up : | 0 |

Wheels and tyres: Summer tires

| | | | | | | | | | | | |
|------------|-----|---------|--------|----|-----|--------|-------|-----|-----------------|---|----------|
| Wheel FL: | [x] | PIRELLI | Tyre : | OK | [x] | 2-4/ | Rim : | [x] | WHEEL SCRATCHED | / | Hubcap : |
| Wheel RL : | [x] | PIRELLI | Tyre : | OK | [x] | 0-1.6/ | Rim : | [x] | WHEEL SCRATCHED | / | Hubcap : |
| Wheel FR : | [x] | PIRELLI | Tyre : | OK | | / | Rim : | [x] | WHEEL SCRATCHED | / | Hubcap : |
| Wheel RR : | [x] | PIRELLI | Tyre : | OK | [x] | 0-1.6/ | Rim : | [x] | WHEEL SCRATCHED | / | Hubcap : |
| Wheel RES: | [x] | | Tyre : | OK | [x] | 2-4/ | Rim : | | | / | Hubcap : |

| [x] | Width | Height | Type | Rim | Index |
|------------|-------|--------|------|-----|-------|
| Front tyre | 225 | 55 | R | 17 | Y |
| Rear tyre | 225 | 55 | R | 17 | W |

Remark :

Wheels and tyres:

| | | | | | | | | |
|------------|--|--------|----|---|-------|--|---|----------|
| Wheel FL: | | Tyre : | OK | / | Rim : | | / | Hubcap : |
| Wheel RL : | | Tyre : | OK | / | Rim : | | / | Hubcap : |
| Wheel FR : | | Tyre : | OK | / | Rim : | | / | Hubcap : |
| Wheel RR : | | Tyre : | OK | / | Rim : | | / | Hubcap : |
| Wheel RES: | | Tyre : | OK | / | Rim : | | / | Hubcap : |

| [x] | Width | Height | Type | Rim | Index |
|------------|-------|--------|------|-----|-------|
| Front tyre | 0 | 0 | R | 0 | |
| Rear tyre | 0 | 0 | R | 0 | |

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

| | | | | |
|-----|----------------------------|---------------------------|----------------------|--|
| [x] | REAR MUDGUARD/LEFT/FRONT | DENT | | |
| [x] | REAR MUDGUARD/RIGHT/CENTER | OTHER DAMAGES | LAKWERK TE POLIJSTEN | |
| [x] | WINDSCREEN/CENTER/RIGHT | CHIPS | | |
| [x] | FRONT BUMPER/LEFT/CORNER | SCRATCH WITH PAINT DAMAGE | | |
| [x] | BONNET/CENTER/RIGHT/FRONT | CHIPS | | |

STATUS: NOT ACCEPTABLE

Bodywork \& windows

| | | | | | | |
|-----|------------------------|--------------------------|----------------------|-------------------|--------------|--------------|
| [x] | REAR BUMPER/LEFT/LEFT | DENT | | | | |
| | | Repair paint - LI | New paint - E | Depr. | Total | |
| 4 | 10 LU =48.00 EUR | 254.16 EUR | | 50 % | 302.16 EUR | |
| [x] | REAR DOOR/RIGHT/FRONT | DENT | | | | |
| | Number | Code | Description | Unit price | Depr. | Total |
| 2 | 11 | i-vab-uitd-01 | BEAT OUT DENT | 63.00 EUR | | 63.00 EUR |
| [x] | FRONT DOOR/RIGHT/FRONT | DENT | | + LAKSCHADE | | |
| | | Repair paint - LI | New paint - E | Depr. | Total | |
| 3 | 10 LU =48.00 EUR | 382.02 EUR | | 50 % | 430.02 EUR | |
| [x] | BONNET/CENTER/LEFT | OTHER DAMAGES | | ISOLATIE | | |
| | | Repair paint - LI | New paint - E | Depr. | Total | |
| 1 | 5 LU =24.00 EUR | 0 EUR | | 50 % | 24.00 EUR | |

Others

RIM REAR RIGHT

| Number | Code | Description | Unit price | Depr. | Total |
|--------|------|-------------------|--------------------|-----------|-----------|
| 5 | I 1 | i-vab-herstalu-02 | REPAIR ALLOY WHEEL | 95.00 EUR | 95.00 EUR |

RIM FRONT RIGHT

| Number | Code | Description | Unit price | Depr. | Total |
|--------|------|-------------------|--------------------|-----------|-----------|
| 5 | I 1 | i-vab-herstalu-02 | REPAIR ALLOY WHEEL | 95.00 EUR | 95.00 EUR |

| |
|---------------|
| Pieces |
|---------------|

| Number | Code | Description | Unit price | Depr. | Total |
|--------|------|-------------|------------|-------|-----------|
| 1 | 1 | ISOLATIE | 40.00 EUR | 50 % | 40.00 EUR |

| 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 |
|-------|-------|--------|--------|--------|---|---|---|---|----|
| 64.00 | 63.00 | 430.02 | 302.16 | 190.00 | 0 | 0 | 0 | 0 | 0 |
| 32.00 | 63.00 | 215.01 | 151.08 | 190.00 | 0 | 0 | 0 | 0 | 0 |

| INNOVATIVE | TRADITIONAL | GENERAL | |
|------------|-------------|---------|---------------------|
| 253.00 | 796.18 | 0 | 1049.18 |
| HOG: 0 | BG: 2 | | NA Deprec. 651.09 |
| | | | 0.00% |
| | | | TOTAL 651.09 |

[x] = Status Modification


Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

| | | |
|---------------------------|--|---|
| Extra Time : 0 min | Waiting time : 0 min Reason : | Towing time : 0 min Reason : |
| NOT EXECUTED : No | | |
| Reason : | | |
| Remark : | | |

Prices in EUR without VAT

| | |
|---|--------------------------------|
| Authorized by customer : Remark authorized customer : Date : 22/06/2017 Hour : 09:19 Company : Executed by VAB Fleet Services E-Mail : @ | Executed by VAB Fleet Services |
| Signature authorized by customer  | |