

BX5WUN

EFFECTIVE     NOT EXECUTED     COLLECTION     DELIVERY

[x] = Status Modification

|                                     |                 |                                 |                               |
|-------------------------------------|-----------------|---------------------------------|-------------------------------|
| <b>Commissionar :</b>               | KBC REMARKETING | <b>Cleanliness :</b>            | INT: CLEAN [x] EXT: CLEAN [x] |
| <b>Owner :</b>                      |                 | <b>Mileage :</b>                | 186833 KM                     |
| <b>File nr. :</b>                   | 1418660         | <b>Mileage start / arrival:</b> | 0 / 0                         |
| <b>Reg number / Chassis / Ref :</b> |                 | <b>Mileag ref. service :</b>    | 0                             |
| 1HHP646 / WBA5J31090D955730 /       |                 | <b>yr of constructionr :</b>    | /                             |
| <b>E-File nr. :</b>                 |                 | <b>First registration :</b>     | 25/07/2014                    |
| <b>VFS-nr. :</b>                    |                 | <b>Color :</b>                  | BROWN                         |
| <b>Make + Model :</b>               | BMW / 5 TOURING | <b>Fuel type :</b>              | DIESEL                        |
| <b>Object nr. :</b>                 | 53223           | <b>Fuel :</b>                   |                               |
| <b>Classification :</b>             | L               | <b>Environment Class:</b>       | EURO 5                        |
| <b>Customer company :</b>           | LUCIAD NV       | <b>Co2:</b>                     | 129g/km                       |
| <b>Driver :</b>                     |                 | <b>Remote controls:</b>         | 2                             |
| <b>Covering :</b>                   | LEATHER         | <b>Number keys :</b>            | 2 [x]                         |
| <b>Vehicle kind :</b>               | VEHICLE         | <b>Seats (minivan) :</b>        | 0                             |
| <b>Vehicle type :</b>               |                 | <b>Country registration :</b>   | BELGIUM                       |

|                                     |                   |                            |         |
|-------------------------------------|-------------------|----------------------------|---------|
| <b>VAT over the margin - car:</b>   |                   | <b>Metallic paint:</b>     | Yes     |
| <b>Variant car:</b>                 | BREAK             | <b>Engine size:</b>        | 1995    |
| <b>Gear box :</b>                   | Automaat algemeen | <b>Number of places:</b>   | 5       |
| <b>Number of gears:</b>             |                   | <b>Number of doors:</b>    | 5       |
| <b>HP:</b>                          | 163               | <b>kW:</b>                 | 120     |
| <b>Fisc HP</b>                      |                   | <b>Imported vehicle:</b>   |         |
| <b>Animals transported:</b>         | No                | <b>Smoked in vehicle:</b>  | No      |
| <b>Due date vehicle inspection:</b> |                   | <b>Extra set of tires:</b> | No      |
|                                     |                   | <b>Use:</b>                | Unknown |

**General condition:**

|   |                                  |
|---|----------------------------------|
| <b>Original registr. number :</b> OK    | <b>Service manual :</b>          |
| <b>Cert. of reg. / Part 1:</b> OK [x]   | <b>Cert. of conformity :</b> OK  |
| <b>Cert. of reg. copy / Part 2:</b> [x] | <b>Insurance certificate :</b>   |
| <b>Warning vest :</b> OK [x]            | <b>Transport licence :</b>       |
| <b>Tax certificate :</b>                | <b>Navigation CD/SD/DVD</b>      |
| <b>Fuel card :</b>                      | <b>Car radio :</b> OK [x]        |
| <b>Mobile phone kit :</b>               | <b>Extinguisher :</b> OK [x]     |
| <b>First aid kit :</b> OK [x]           | <b>Warning triangle :</b> OK [x] |
| <b>Jack, wheelspanner :</b> OK [x]      | <b>Oil level :</b> OK [x]        |
|   | <b>Filled up :</b> 0             |

## Wheels and tyres: Summer tires

|   |
|---|
| <b>Wheel FL:</b> [x] BRIDGESTONE Tyre : OK [x] 2-4/ Rim : [x] WHEEL SCRATCHED / Hubcap :      |
| <b>Wheel RL :</b> [x] BRIDGESTONE Tyre : OK [x] 2-4/ Rim : [x] WHEEL SCRATCHED / Hubcap :     |
| <b>Wheel FR :</b> [x] BRIDGESTONE Tyre : [x] OK [x] 2-4/ Rim : [x] WHEEL SCRATCHED / Hubcap : |
| <b>Wheel RR :</b> [x] BRIDGESTONE Tyre : OK [x] 2-4/ Rim : [x] WHEEL SCRATCHED / Hubcap :     |
| <b>Wheel RES:</b> [x] Tyre : OK / Rim : / Hubcap :  |

| [x]        | Width | Height | Type | Rim | Index |
|------------|-------|--------|------|-----|-------|
| Front tyre | 225   | 55     | R    | 17  | W     |
| Rear tyre  | 225   | 55     | R    | 17  | W     |

Remark :

## Wheels and tyres:

|  |
|--|
| <b>Wheel FL:</b> Tyre : OK / Rim : / Hubcap :  |
| <b>Wheel RL :</b> Tyre : OK / Rim : / Hubcap : |
| <b>Wheel FR :</b> Tyre : OK / Rim : / Hubcap : |
| <b>Wheel RR :</b> Tyre : OK / Rim : / Hubcap : |
| <b>Wheel RES:</b> Tyre : OK / Rim : / Hubcap : |

| [x]        | Width | Height | Type | Rim | Index |
|------------|-------|--------|------|-----|-------|
| Front tyre | 0     | 0      | R    | 0   |       |
| Rear tyre  | 0     | 0      | R    | 0   |       |

Remark :

## STATUS: ACCEPTABLE / USAGE DAMAGE

### Bodywork \& windows

[x] FRONT DOOR/RIGHT/REAR SCRATCH WITH PAINT DAMAGE

### Interior

[x] SEAT FL OTHER DAMAGES

### Accessories and others

[x] OUTSIDE MIRROR RIGHTHAND SIDE SCRATCH WITH PAINT DAMAGE

## STATUS: NOT ACCEPTABLE

### Bodywork \& windows

[x] REAR BUMPER/LEFT/LEFT SCRATCH WITH PAINT DAMAGE

|                  | Repair paint - LI | New paint - E | Depr. | Total      |
|------------------|-------------------|---------------|-------|------------|
| 3 0 LU =0.00 EUR | 254.16 EUR        |               | 50 %  | 254.16 EUR |

[x] REAR MUDGUARD/RIGHT/CENTER

DENT

| Number | Code              | Description   | Unit price | Depr. | Total     |
|--------|-------------------|---------------|------------|-------|-----------|
| 2      | I 1 i-vab-uitd-01 | BEAT OUT DENT | 63.00 EUR  |       | 63.00 EUR |

[x] REAR DOOR/RIGHT/CENTER

DENT

+KRAS

|                  | Repair paint - LI | New paint - E | Depr. | Total      |
|------------------|-------------------|---------------|-------|------------|
| 5 0 LU =0.00 EUR | 382.02 EUR        |               | 50 %  | 382.02 EUR |

[x] FRONT BUMPER/LEFT

SCRATCH WITH PAINT DAMAGE

|                  | Repair paint - LI | New paint - E | Depr. | Total      |
|------------------|-------------------|---------------|-------|------------|
| 1 0 LU =0.00 EUR | 254.16 EUR        |               | 50 %  | 254.16 EUR |

[x] ROOF/CENTER/LEFT

DENT

|                  | Repair paint - LI | New paint - E | Depr. | Total      |
|------------------|-------------------|---------------|-------|------------|
| 4 0 LU =0.00 EUR | 577.80 EUR        |               | 50 %  | 577.80 EUR |

### Others

RIM REAR RIGHT

| Number | Code                  | Description        | Unit price | Depr. | Total     |
|--------|-----------------------|--------------------|------------|-------|-----------|
| 6      | I 1 i-vab-herstalu-02 | REPAIR ALLOY WHEEL | 95.00 EUR  |       | 95.00 EUR |

| 1      | 2     | 3      | 4      | 5      | 6     | 7 | 8 | 9 | 10 |
|--------|-------|--------|--------|--------|-------|---|---|---|----|
| 254.16 | 63.00 | 254.16 | 577.80 | 382.02 | 95.00 | 0 | 0 | 0 | 0  |
| 127.08 | 63.00 | 127.08 | 288.90 | 191.01 | 95.00 | 0 | 0 | 0 | 0  |

| INNOVATIVE | TRADITIONAL | GENERAL |                     |
|------------|-------------|---------|---------------------|
| 158.00     | 1468.14     | 0       | <b>1626.14</b>      |
| HOG: 0     | BG: 2       |         | NA Deprec. 892.07   |
|            |             |         | 0.00%               |
|            |             |         | <b>TOTAL 892.07</b> |

[x] = Status Modification


Pictures : No

## CIRCUMSTANCES

NORMAL CONCLUSION

|   |  |   |
|---|--|---|
| <b>Extra Time :</b> 0 min                   | <b>Waiting time :</b> 0 min<br><b>Reason :</b> | <b>Towing time :</b> 0 min<br><b>Reason :</b> |
| <b>NOT EXECUTED :</b> No<br><b>Reason :</b> |  |   |
| <b>Remark :</b>                             |  |   |

## Prices in EUR without VAT

|   |                                |
|---|--------------------------------|
| <b>Authorized by customer :</b><br><br><b>Remark authorized customer :</b><br><br><b>Date :</b> 13/07/2017 <b>Hour :</b> 13:20<br><b>Company :</b><br>Executed by VAB Fleet Services<br><b>E-Mail :</b> @ | Executed by VAB Fleet Services |
| Signature authorized by customer<br>   |                                |