

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	193708 KM
File nr. :	1416708	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1PEU422 / WBA3L11020F280460 /		yr of constructionr :	/
E-File nr. :		First registration :	14/06/2013
VFS-nr. :		Color :	BLACK
Make + Model :	BMW / 3 TOURING	Fuel type :	DIESEL
Object nr. :	702832	Fuel :	
Classification :	F	Environment Class:	EURO 5
Customer company :	ELEMENTIS SERVICES GMBH	Co2:	112g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :		Country registration :	BELGIUM

VAT over the margin - car:		Metallic paint:	Yes
Variant car:	BREAK	Engine size:	1995
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	163	kW:	120
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	
		Use:	Unknown

General condition:

Original registr. number :	OK	Service manual :	OK	[x]		
Cert. of reg. / Part 1:	OK	[x]	Cert. of conformity :	NOK	[x]	MISSING/INCOMPLETE
Cert. of reg. copy / Part 2:		Insurance certificate :				
Warning vest :	OK	[x]	Transport licence :			
Tax certificate :		Navigation CD/SD/DVD				
Fuel card :		Car radio :	OK	[x]		
Mobile phone kit :		Extinguisher :	OK	[x]		
First aid kit :	OK	[x]	Warning triangle :	OK	[x]	
Jack, wheelspanner :	OK	[x]	Oil level :	OK	[x]	
		Filled up :	0			

Wheels and tyres: Summer tires

Wheel FL:	[x]	GOODYEAR	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :			
Wheel RL :	[x]	GOODYEAR	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :			
Wheel FR :	[x]	GOODYEAR	Tyre :	[x]	OK	[x]	2-4/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :
Wheel RR :	[x]	GOODYEAR	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :			
Wheel RES:	[x]		Tyre :	OK	/		Rim :	/	Hubcap :			

[x]	Width	Height	Type	Rim	Index
Front tyre	205	60	R	16	V
Rear tyre	205	60	R	16	V

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

- [x] REAR MUDGUARD/RIGHT/REAR SCRATCH WITH PAINT DAMAGE
- [x] BONNET/CENTER/RIGHT DENT

Interior

- [x] DOOR IN REAR L CARVED

STATUS: NOT ACCEPTABLE

Bodywork \& windows

- [x] REAR BUMPER/RIGHT/RIGHT SCRATCH WITH PAINT DAMAGE

	Repair paint - LI	New paint - E	Depr.	Total
2 0 LU =0.00 EUR	211.80 EUR		50 %	211.80 EUR

- [x] REAR DOOR/RIGHT/FRONT DENT

Number	Code	Description	Unit price	Depr.	Total
3	I 1 i-vab-uitd-01	BEAT OUT DENT	63.00 EUR		63.00 EUR

- [x] FRONT BUMPER/RIGHT SCRATCH WITH PAINT DAMAGE

	Repair paint - LI	New paint - E	Depr.	Total
1 0 LU =0.00 EUR	211.80 EUR		50 %	211.80 EUR

Others

RIM FRONT RIGHT

Number	Code	Description	Unit price	Depr.	Total
4	I 1 i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

1	2	3	4	5	6	7	8	9	10
211.80	211.80	63.00	95.00	0	0	0	0	0	0
105.90	105.90	63.00	95.00	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
158.00	423.60	0	581.60
HOG: 0	BG: 0		NA Deprec. 369.80
			0.00%
			TOTAL 369.80

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

UNDER CONDITION - VEHICLE WET

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 12/07/2017 Hour : 09:07 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	