

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	149468 KM
File nr. :	1415247	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1EPG405 / WF0UXXTPUCS04466 /		yr of constructionr :	2013 / 00
E-File nr. :		First registration :	13/02/2013
VFS-nr. :		Color :	WHITE
Make + Model :	FORD / TRANSIT CONNECT	Fuel type :	DIESEL
Object nr. :	8676	Fuel :	
Classification :	DELIVERY VAN B	Environment Class:	EURO 5
Customer company :	G4S SECURITY SYSTEMS NV	Co2:	162g/km
Driver :		Remote controls:	1
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	TRUCK, LORRY	Seats (minivan) :	0
Vehicle type :		Country registration :	BELGIUM

VAT over the margin - car:		Metallic paint:	No
Variant car:	BESTELWAGEN	Engine size:	1753
Gear box :	Manueel	Number of places:	2
Number of gears:	5	Number of doors:	5
HP:	90	kW:	66
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	
Due date vehicle inspection:		Extra set of tires:	
		Use:	Unknown
General condition:			

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:		Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :	
Warning vest :		Transport licence :		
Tax certificate :		Navigation CD/SD/DVD		
Fuel card :		Car radio :	OK	[x]
Mobile phone kit :		Extinguisher :	OK	[x]
First aid kit :	OK	[x]	Warning triangle :	OK
Jack, wheelspanner :	OK	[x]	Oil level :	OK
			Filled up :	0

Wheels and tyres: Winter tires

Wheel FL:	[x]	UNIROYAL	Tyre :	OK	[x]	1.6-2/	Rim :	/	Hubcap :
Wheel RL :	[x]	MICHELIN	Tyre :	OK	[x]	1.6-2/	Rim :	/	Hubcap :
Wheel FR :	[x]	UNIROYAL	Tyre :	[x]	OK	[x]	1.6-2/	Rim :	/
Wheel RR :	[x]	MICHELIN	Tyre :	OK	[x]	1.6-2/	Rim :	/	Hubcap :
Wheel RES:	[x]		Tyre :	OK		/	Rim :	/	Hubcap :
	[x]								[x] SCRATCHED
									[x] SCRATCHED

[x]	Width	Height	Type	Rim	Index
Front tyre	195	65	R	15	M+S
Rear tyre	195	65	R	15	M+S

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR BUMPER/CENTER/RIGHT	SCRATCH WITH PAINT DAMAGE
[x]	REAR MUDGUARD/RIGHT/CENTER	DENT
[x]	ROOF STYLE/CENTER/RIGHT	DENT
[x]	BONNET/CENTER/LEFT/FRONT	CHIPS
[x]	BONNET/CENTER/RIGHT/FRONT	CHIPS

Interior

[x]	DASHBORD	CARVED
[x]	FLOOR BOOT	HOLE

Accessories and others

[x]	VEH COVERED WITH STICKERS	STICKER(S)
[x]	ANTENNA	BROKEN / CRACKED

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR MUDGUARD/LEFT/REAR	DENT				
			Repair paint - LI	New paint - E	Depr.	Total
4	0 LU =0.00 EUR		231.15 EUR		50 %	231.15 EUR
[x]	ROOF STYLE/CENTER/LEFT	DENT				
	Number	Code	Description	Unit price	Depr.	Total
3	I 1	i-vab-uitd-01	BEAT OUT DENT	63.00 EUR		63.00 EUR
	Number	Code	Description	Unit price	Depr.	Total
3	I 2	i-vab-uitd-02	BEAT OUT DENT SUPPL	19.80 EUR		39.60 EUR
[x]	WINDSCREEN/CENTER/LEFT	WINDOW DAMAGE			2X	
	Number	Code	Description	Unit price	Depr.	Total
2	I 1	i-vab-herstr-01	WINDOW REPAIR	58.80 EUR		58.80 EUR
[x]	FRONT BUMPER/RIGHT	DENT				
			Repair paint - LI	New paint - E	Depr.	Total
1	0 LU =0.00 EUR		158.85 EUR		50 %	158.85 EUR

1	2	3	4	5	6	7	8	9	10
158.85	58.80	102.60	231.15	0	0	0	0	0	0
79.42	58.80	102.60	115.58	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
161.40	390.00	0	551.40
HOG: 0	BG: 3		NA Deprec. 356.40
			0.00%
			TOTAL 356.40

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 08/07/2017 Hour : 11:09 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	