

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: DIRTY [x] EXT: CLEAN [x]
Owner :		Mileage :	271636 KM
File nr. :	1413600	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1CWE582 / ZCFC40A5005903554 /		yr of constructionr :	/
E-File nr. :		First registration :	12/03/2012
VFS-nr. :		Color :	WHITE
Make + Model :	IVECO / DAILY	Fuel type :	DIESEL
Object nr. :	62822	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	Sodraep SA	Co2:	g/km
Driver :		Remote controls:	1
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	TRUCK, LORRY	Seats (minivan) :	0
Vehicle type :	DAILY PU2C 40C15 146PK 3500KG	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	
Variant car:	BESTELWAGEN	Engine size:	2998
Gear box :	Manueel	Number of places:	7
Number of gears:	6	Number of doors:	4
HP:	146	kW:	107
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	
Due date vehicle inspection:		Extra set of tires:	
		Use:	Unknown

General condition:

Original registr. number : OK	Service manual :
Cert. of reg. / Part 1:	Cert. of conformity : OK
Cert. of reg. copy / Part 2: OK [x]	Insurance certificate :
Warning vest :	Transport licence :
Tax certificate :	Navigation CD/SD/DVD
Fuel card :	Car radio : OK [x]
Mobile phone kit :	Extinguisher : OK [x]
First aid kit : OK [x]	Warning triangle : OK [x]
Jack, wheelspanner :	Oil level : OK [x]
	Filled up : 0

Wheels and tyres: Summer tires

Wheel FL: [x] MICHELIN Tyre : OK [x] 2-4/ Rim : / Hubcap :
Wheel RL : [x] MICHELIN Tyre : OK [x] 2-4/ Rim : / Hubcap :
Wheel FR : [x] MICHELIN Tyre : [x] OK [x] 2-4/ Rim : / Hubcap :
Wheel RR : [x] MICHELIN Tyre : OK [x] 2-4/ Rim : / Hubcap :
Wheel RES: [x] MICHELIN Tyre : OK / Rim : / Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	195	75	R	16	T
Rear tyre	195	75	R	16	T

Remark :

Wheels and tyres:

Wheel FL: Tyre : OK / Rim : / Hubcap :
Wheel RL : Tyre : OK / Rim : / Hubcap :
Wheel FR : Tyre : OK / Rim : / Hubcap :
Wheel RR : Tyre : OK / Rim : / Hubcap :
Wheel RES: Tyre : OK / Rim : / Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

Conclusion

Bodywork \& windows

- [x] REAR MUDGUARD/LEFT/CENTER SCRATCH WITH PAINT DAMAGE
- [x] FRONT DOOR/RIGHT/REAR DENT

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

- [x] REAR MUDGUARD/RIGHT/CENTER SCRATCH WITH PAINT DAMAGE
- [x] REAR DOOR/LEFT/FRONT SCRATCH (WITHOUT PAINT DAMAGE)
- [x] REAR DOOR/RIGHT/FRONT SCRATCH (WITHOUT PAINT DAMAGE)
- [x] FRONT DOOR/LEFT/REAR DENT
- [x] BONNET/CENTER/RIGHT/FRONT DENT

STATUS: NOT ACCEPTABLE

Bodywork \& windows

- [x] THRESHOLD FRONT/LEFT/CENTER SCRATCH WITH PAINT DAMAGE

Number	Code	Description	Unit price	Depr.	Total
3	I 1	i-vab-sp-01 SPOTREPAIR	115.56 EUR		115.56 EUR

- [x] FRONT THRESHOLD/RIGHT/CENTER SCRATCH WITH PAINT DAMAGE

Number	Code	Description	Unit price	Depr.	Total
2	I 1	i-vab-sp-01 SPOTREPAIR	115.56 EUR		115.56 EUR

Interior

- [x] DASHBORD HOLE

Number	Code	Description	Unit price	Depr.	Total
1	I 2	i-vab-intdash-01 PLASTICS REPAIR INTERIRO	110.64 EUR		221.28 EUR

Others

CLEANLINESS INTERIOR

Number	Code	Description	Unit price	Depr.	Total
1	I 1	specifiek-per-kwartier-a-vab-rein-03 CLEANING INTERIOR	14.58 EUR		14.58 EUR

1	2	3	4	5	6	7	8	9	10
235.86	115.56	115.56	0	0	0	0	0	0	0
235.86	115.56	115.56	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
466.98	0	0	466.98
HOG: 0	BG: 3		NA Deprec. 466.98
			0.00%
			TOTAL 466.98

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 07/07/2017 Hour : Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	