

EFFECTIVE     NOT EXECUTED                       COLLECTION                       DELIVERY

[x] = Status Modification

<b>Commissionar :</b>	KBC REMARKETING	<b>Cleanliness :</b>	INT: DIRTY [x] EXT: CLEAN [x]
<b>Owner :</b>		<b>Mileage :</b>	97821 KM
<b>File nr. :</b>	1416244	<b>Mileage start / arrival:</b>	0 / 0
<b>Reg number / Chassis / Ref :</b>		<b>Mileag ref. service :</b>	0
1GDC571 / WF0UXXTTPUDR80551 /		<b>yr of constructionr :</b>	/
<b>E-File nr. :</b>		<b>First registration :</b>	06/01/2014
<b>VFS-nr. :</b>		<b>Color :</b>	BLACK
<b>Make + Model :</b>	FORD / TRANSIT CONNECT	<b>Fuel type :</b>	DIESEL
<b>Object nr. :</b>	59040	<b>Fuel :</b>	
<b>Classification :</b>		<b>Environment Class:</b>	EURO 5
<b>Customer company :</b>	TECH MAHINDRA NETWORK SERVICES	<b>Co2:</b>	162g/km
<b>Driver :</b>		<b>Remote controls:</b>	1
<b>Covering :</b>	TISSUE	<b>Number keys :</b>	2 [x]
<b>Vehicle kind :</b>	TRUCK, LORRY	<b>Seats (minivan) :</b>	0
<b>Vehicle type :</b>		<b>Country registration :</b>	BELGIUM

<b>VAT over the margin - car:</b>		<b>Metallic paint:</b>	Yes
<b>Variant car:</b>	BESTELWAGEN	<b>Engine size:</b>	1753
<b>Gear box :</b>	Manueel	<b>Number of places:</b>	2
<b>Number of gears:</b>	5	<b>Number of doors:</b>	5
<b>HP:</b>	90	<b>kW:</b>	66
<b>Fisc HP</b>		<b>Imported vehicle:</b>	No
<b>Animals transported:</b>	No	<b>Smoked in vehicle:</b>	No
<b>Due date vehicle inspection:</b>		<b>Extra set of tires:</b>	No
		<b>Use:</b>	Unknown
<b>General condition:</b>			

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:	OK	[x]	Cert. of conformity :	OK
Cert. of reg. copy / Part 2:		Insurance certificate :		[x]
Warning vest :	OK	[x]	Transport licence :	
Tax certificate :		Navigation CD/SD/DVD		
Fuel card :		Car radio :	OK	[x]
Mobile phone kit :		Extinguisher :	OK	[x]
First aid kit :	OK	[x]	Warning triangle :	OK
Jack, wheelspanner :		Oil level :	OK	[x]
		Filled up :	0	

## Wheels and tyres: Summer tires

Wheel FL:	[x]	CONTINENTAL	Tyre :	OK	[x]	>6/	Rim :	/	Hubcap :	[x]	SCRATCHED	
Wheel RL :	[x]	CONTINENTAL	Tyre :	OK	[x]	>6/	Rim :	/	Hubcap :	[x]	SCRATCHED	
Wheel FR :	[x]	CONTINENTAL	Tyre :	[x]	OK	[x]	>6/	Rim :	/	Hubcap :	[x]	SCRATCHED
Wheel RR :	[x]	CONTINENTAL	Tyre :	OK	[x]	>6/	Rim :	/	Hubcap :	[x]	SCRATCHED	
Wheel RES:	[x]		Tyre :	OK		/	Rim :	/	Hubcap :			

  

[x]	Width	Height	Type	Rim	Index
Front tyre	195	65	R	15	
Rear tyre	195	65	R	15	

Remark :

## Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :	

  

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

## STATUS: ACCEPTABLE / USAGE DAMAGE

### Bodywork \& windows

[x]	REAR MUDGUARD/RIGHT/CENTER	DENT
[x]	REAR DOOR/RIGHT/CENTER	DENT
[x]	BONNET/CENTER/LEFT	SCRATCH WITH PAINT DAMAGE

## STATUS: NOT ACCEPTABLE

### Bodywork \& windows

[x]	REAR BUMPER/CENTER/LEFT	SCRATCH WITH PAINT DAMAGE	+DEUKEN		
		<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>
4	0 LU =0.00 EUR	158.85 EUR		50 %	158.85 EUR
[x]	REAR MUDGUARD/LEFT/CENTER	DENT		MEERDERE	
		<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>
3	0 LU =0.00 EUR	231.15 EUR		50 %	231.15 EUR
[x]	FRONT BUMPER/RIGHT/CORNER	OTHER DAMAGES			
		<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>
5	5 LU =24.00 EUR	0 EUR		50 %	24.00 EUR

### Others

CLEANLINESS INTERIOR

Number	Code	Description	Unit price	Depr.	Total
1	I 2	specifiek-per-kwartier-a-vab-rein-03	CLEANING INTERIOR	14.58 EUR	29.16 EUR
HUB CAP FL					
		<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>
2	0 LU =0.00 EUR			50 %	
HUB CAP REAR L					
		<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>
2	0 LU =0.00 EUR			50 %	
HUB CAP REAR RIGHT					
		<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>
2	0 LU =0.00 EUR			50 %	

HUB CAP FR

	Repair paint - LI	New paint - E	Depr.	Total
2 0 LU =0.00 EUR			50 %	

**Pieces**

Number	Code	Description	Unit price	Depr.	Total
2	1	WHEEL CAP	22.50 EUR	50 %	22.50 EUR
Number	Code	Description	Unit price	Depr.	Total
2	1	WHEEL CAP	22.50 EUR	50 %	22.50 EUR
Number	Code	Description	Unit price	Depr.	Total
2	1	WHEEL CAP	22.50 EUR	50 %	22.50 EUR
Number	Code	Description	Unit price	Depr.	Total
2	1	WHEEL CAP	22.50 EUR	50 %	22.50 EUR

1	2	3	4	5	6	7	8	9	10
29.16	90.00	231.15	158.85	24.00	0	0	0	0	0
29.16	45.00	115.58	79.42	12.00	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
29.16	504.00	0	<b>533.16</b>
HOG: 0	BG: 3		NA Deprec. 281.16
			0.00%
			<b>TOTAL 281.16</b>

[x] = Status Modification

Pictures : No

## CIRCUMSTANCES

NORMAL CONCLUSION

<b>Extra Time :</b> 0 min	<b>Waiting time :</b> 0 min <b>Reason :</b>	<b>Towing time :</b> 0 min <b>Reason :</b>
<b>NOT EXECUTED :</b> No <b>Reason :</b>		
<b>Remark :</b>		

## Prices in EUR without VAT

<b>Authorized by customer :</b>  <b>Remark authorized customer :</b>  <b>Date :</b> 06/07/2017 <b>Hour :</b> 16:00 <b>Company :</b> Executed by VAB Fleet Services <b>E-Mail :</b> @	Executed by VAB Fleet Services
Signature authorized by customer 	