

EFFECTIVE     NOT EXECUTED     COLLECTION     DELIVERY

[x] = Status Modification

<b>Commissionar :</b>	KBC REMARKETING	<b>Cleanliness :</b>	INT: DIRTY [x] EXT: CLEAN [x]
<b>Owner :</b>		<b>Mileage :</b>	57577 KM
<b>File nr. :</b>	1415377	<b>Mileage start / arrival:</b>	0 / 0
<b>Reg number / Chassis / Ref :</b>		<b>Mileag ref. service :</b>	0
1JPJ469 / VF37B9HF0EJ861511 /		<b>yr of constructionr :</b>	/
<b>E-File nr. :</b>		<b>First registration :</b>	01/01/1918
<b>VFS-nr. :</b>		<b>Color :</b>	GREY
<b>Make + Model :</b>	PEUGEOT / PARTNER	<b>Fuel type :</b>	DIESEL
<b>Object nr. :</b>	ONBEKEND	<b>Fuel :</b>	
<b>Classification :</b>	DELIVERY VAN A	<b>Environment Class:</b>	
<b>Customer company :</b>	ONBEKEND	<b>Co2:</b>	g/km
<b>Driver :</b>		<b>Remote controls:</b>	0
<b>Covering :</b>	TISSUE	<b>Number keys :</b>	1 [x]
<b>Vehicle kind :</b>	TRUCK, LORRY	<b>Seats (minivan) :</b>	0
<b>Vehicle type :</b>		<b>Country registration :</b>	BELGIUM

<b>VAT over the margin - car:</b>		<b>Metallic paint:</b>	
<b>Variant car:</b>	BESTELWAGEN	<b>Engine size:</b>	1560
<b>Gear box :</b>	Manueel	<b>Number of places:</b>	3
<b>Number of gears:</b>	5	<b>Number of doors:</b>	5
<b>HP:</b>	90	<b>kW:</b>	66
<b>Fisc HP</b>		<b>Imported vehicle:</b>	No
<b>Animals transported:</b>	No	<b>Smoked in vehicle:</b>	No
<b>Due date vehicle inspection:</b>		<b>Extra set of tires:</b>	No
		<b>Use:</b>	Unknown
<b>General condition:</b>			

Original registr. number :		Service manual :	OK	[x]
Cert. of reg. / Part 1:		Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:		Insurance certificate :		
Warning vest :	OK	Transport licence :		
Tax certificate :		Navigation CD/SD/DVD		[x]
Fuel card :		Car radio :	OK	[x]
Mobile phone kit :		Extinguisher :	OK	[x]
First aid kit :	OK	Warning triangle :	OK	[x]
Jack, wheelspanner :	OK	Oil level :	OK	[x]
		Filled up :	0	

## Wheels and tyres: Summer tires

Wheel FL:	[x]	ANDERE	Tyre :	OK	[x]	2-4/	Rim :		/	Hubcap :
Wheel RL :	[x]	ANDERE	Tyre :	OK	[x]	2-4/	Rim :		/	Hubcap :
Wheel FR :	[x]	ANDERE	Tyre :	[x]	OK	[x]	2-4/	Rim :		Hubcap :
Wheel RR :	[x]	ANDERE	Tyre :	OK	[x]	2-4/	Rim :		/	Hubcap :
Wheel RES:	[x]	ANDERE	Tyre :	OK	[x]	>6/	Rim :		/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	195	60	R	15	T
Rear tyre	195	60	R	15	T

Remark :

## Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :		/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

## STATUS: NOT ACCEPTABLE

### Bodywork \& windows

[x]	REAR BUMPER/CENTER/LEFT	OTHER DAMAGES			
		Repair paint - LI	New paint - E	Depr.	Total
2	0 LU =0.00 EUR	158.85 EUR		50 %	158.85 EUR
[x]	REAR DOOR/LEFT/CENTER	OTHER DAMAGES			
		Repair paint - LI	New paint - E	Depr.	Total
1	0 LU =0.00 EUR	0 EUR		50 %	
[x]	FRONT DOOR/LEFT/CENTER	OTHER DAMAGES			
		Repair paint - LI	New paint - E	Depr.	Total
1	0 LU =0.00 EUR	0 EUR		50 %	

### Others

CLEANLINESS INTERIOR

Number	Code	Description	Unit price	Depr.	Total
3	I 4	specifiek-per-kwartier-a-vab-rein-03	CLEANING INTERIOR	14.58 EUR	58.32 EUR

### Pieces

Number	Code	Description	Unit price	Depr.	Total
1	1	SIDE PROTECTION	10.80 EUR	50 %	10.80 EUR
Number	Code	Description	Unit price	Depr.	Total
1	1	SIDE PROTECTION	10.80 EUR	50 %	10.80 EUR

1	2	3	4	5	6	7	8	9	10
21.60	158.85	58.32	0	0	0	0	0	0	0
10.80	79.42	58.32	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
58.32	180.45	0	238.77
HOG: 0	BG: 3		NA Deprec. 148.54
			0.00%
			TOTAL 148.54

[x] = Status Modification

Pictures : No

## CIRCUMSTANCES

NORMAL CONCLUSION

<b>Extra Time :</b> 0 min	<b>Waiting time :</b> 0 min <b>Reason :</b>	<b>Towing time :</b> 0 min <b>Reason :</b>
<b>NOT EXECUTED :</b> No <b>Reason :</b>		
<b>Remark :</b> WAGEN INGESCHREVEN OP 1 SSF 534 / GEEN IB [x]		

## Prices in EUR without VAT

<b>Authorized by customer :</b>  <b>Remark authorized customer :</b>  <b>Date :</b> 08/07/2017 <b>Hour :</b> 11:34 <b>Company :</b> Executed by VAB Fleet Services <b>E-Mail :</b> @	Executed by VAB Fleet Services
Signature authorized by customer  	