

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: DIRTY [x] EXT: DIRTY [x]
Owner :		Mileage :	187241 KM
File nr. :	1417322	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1GSM462 / VF1BR1G0H40845948 /		yr of constructionr :	/
E-File nr. :		First registration :	16/04/2014
VFS-nr. :		Color :	RED
Make + Model :	RENAULT / CLIO	Fuel type :	DIESEL
Object nr. :	ONBEKEND	Fuel :	
Classification :		Environment Class:	EURO 4
Customer company :	ONBEKEND	Co2:	123g/km
Driver :		Remote controls:	1
Covering :	TISSUE	Number keys :	1 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :		Country registration :	BELGIUM

VAT over the margin - car:		Metallic paint:	Yes
Variant car:	COMPACT	Engine size:	1461
Gear box :	Manueel	Number of places:	5
Number of gears:	5	Number of doors:	5
HP:	68	kW:	50
Fisc HP		Imported vehicle:	No
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown

General condition:

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:	OK	[x]	Cert. of conformity :	OK
Cert. of reg. copy / Part 2:		Insurance certificate :		
Warning vest :	OK	[x]	Transport licence :	
Tax certificate :		Navigation CD/SD/DVD		
Fuel card :		Car radio :	OK	[x]
Mobile phone kit :		Extinguisher :	OK	[x]
First aid kit :	OK	[x]	Warning triangle :	OK
Jack, wheelspanner :		Oil level :	OK	[x]
		Filled up :	0	

Wheels and tyres: Summer tires

Wheel FL:	Tyre :	OK	/	Rim :	/	Hubcap :	[x] SCRATCHED
Wheel RL :	Tyre :	OK	/	Rim :	/	Hubcap :	[x] SCRATCHED
Wheel FR :	Tyre :	OK	/	Rim :	/	Hubcap :	[x] MISSING/INCOMPLETE
Wheel RR :	Tyre :	OK	/	Rim :	/	Hubcap :	[x] SCRATCHED
Wheel RES:	Tyre :	OK	/	Rim :	/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	185	60	R	16	H
Rear tyre	185	60	R	16	H

Remark :

Wheels and tyres:

Wheel FL:	Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RL :	Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel FR :	Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RR :	Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RES:	Tyre :	OK	/	Rim :	/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

- [x] FRONT DOOR/RIGHT/CENTER SCRATCH (WITHOUT PAINT DAMAGE)
- [x] FRONT MUDGUARD/RIGHT/FRONT SCRATCH (WITHOUT PAINT DAMAGE) POLIEREN

Interior

- [x] SEAT FL OTHER DAMAGES

STATUS: NOT ACCEPTABLE

Bodywork \& windows

		Repair paint - LI	New paint - E	Depr.	Total
[x]	REAR MUDGUARD/RIGHT/FRONT				
2	0 LU =0.00 EUR	246.56 EUR		50 %	246.56 EUR
[x]	REAR DOOR/RIGHT/CENTER				
3	0 LU =0.00 EUR	254.68 EUR		50 %	254.68 EUR

Others

CLEANLINESS INTERIOR

Number	Code	Description	Unit price	Depr.	Total
1	I 4	specifiek-per-kwartier-a-vab-rein-03	CLEANING INTERIOR	14.58 EUR	58.32 EUR

HUB CAP REAR L

		Repair paint - LI	New paint - E	Depr.	Total
1	0 LU =0.00 EUR			50 %	

HUB CAP REAR RIGHT

		Repair paint - LI	New paint - E	Depr.	Total
1	0 LU =0.00 EUR			50 %	

HUB CAP FR

		Repair paint - LI	New paint - E	Depr.	Total
1	0 LU =0.00 EUR			50 %	

Pieces

Number	Code	Description	Unit price	Depr.	Total
1	1	WHEEL CAP	24.00 EUR	50 %	24.00 EUR
Number	Code	Description	Unit price	Depr.	Total
1	1	WHEEL CAP	24.00 EUR	50 %	24.00 EUR
Number	Code	Description	Unit price	Depr.	Total
1	1	WHEEL CAP	24.00 EUR	50 %	24.00 EUR

1	2	3	4	5	6	7	8	9	10
130.32	246.56	254.68	0	0	0	0	0	0	0
94.32	123.28	127.34	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
58.32	573.24	0	631.56
HOG: 0	BG: 1		NA Deprec. 344.94
			0.00%
			TOTAL 344.94

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 10/07/2017 Hour : 08:10 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	