

EFFECTIVE     NOT EXECUTED                       COLLECTION                       DELIVERY

[x] = Status Modification

|                                     |                                    |                                 |                               |
|-------------------------------------|------------------------------------|---------------------------------|-------------------------------|
| <b>Commissionar :</b>               | KBC REMARKETING                    | <b>Cleanliness :</b>            | INT: CLEAN [x] EXT: DIRTY [x] |
| <b>Owner :</b>                      |                                    | <b>Mileage :</b>                | 184244 KM                     |
| <b>File nr. :</b>                   | 1416137                            | <b>Mileage start / arrival:</b> | 0 / 0                         |
| <b>Reg number / Chassis / Ref :</b> |                                    | <b>Mileag ref. service :</b>    | 0                             |
| 1FEB452 / VF38E9HD8DL026508 /       |                                    | <b>yr of constructionr :</b>    | /                             |
| <b>E-File nr. :</b>                 |                                    | <b>First registration :</b>     | 04/06/2013                    |
| <b>VFS-nr. :</b>                    |                                    | <b>Color :</b>                  | GREY                          |
| <b>Make + Model :</b>               | PEUGEOT / 508                      | <b>Fuel type :</b>              | DIESEL                        |
| <b>Object nr. :</b>                 | 39305                              | <b>Fuel :</b>                   |                               |
| <b>Classification :</b>             |                                    | <b>Environment Class:</b>       | EURO 5                        |
| <b>Customer company :</b>           | F.T.O. NV                          | <b>Co2:</b>                     | 105g/km                       |
| <b>Driver :</b>                     |                                    | <b>Remote controls:</b>         | 1                             |
| <b>Covering :</b>                   | TISSUE-LEATHER                     | <b>Number keys :</b>            | 2 [x]                         |
| <b>Vehicle kind :</b>               | VEHICLE                            | <b>Seats (minivan) :</b>        | 0                             |
| <b>Vehicle type :</b>               | 508 SW e-HDi Active BMP 115PK Aut. | <b>Country registration :</b>   | BELGIUM                       |

|                                     |                   |                            |         |
|-------------------------------------|-------------------|----------------------------|---------|
| <b>VAT over the margin - car:</b>   |                   | <b>Metallic paint:</b>     | Yes     |
| <b>Variant car:</b>                 | BREAK             | <b>Engine size:</b>        | 1560    |
| <b>Gear box :</b>                   | Automaat algemeen | <b>Number of places:</b>   | 5       |
| <b>Number of gears:</b>             |                   | <b>Number of doors:</b>    | 5       |
| <b>HP:</b>                          | 114               | <b>kW:</b>                 | 84      |
| <b>Fisc HP</b>                      |                   | <b>Imported vehicle:</b>   |         |
| <b>Animals transported:</b>         |                   | <b>Smoked in vehicle:</b>  |         |
| <b>Due date vehicle inspection:</b> |                   | <b>Extra set of tires:</b> |         |
|                                     |                   | <b>Use:</b>                | Unknown |
| <b>General condition:</b>           |                   |                            |         |

|                              |    |                       |                         |        |
|------------------------------|----|-----------------------|-------------------------|--------|
| Original registr. number :   | OK | Service manual :      | OK                      | [x]    |
| Cert. of reg. / Part 1:      |    | Cert. of conformity : | OK                      |        |
| Cert. of reg. copy / Part 2: | OK | [x]                   | Insurance certificate : |        |
| Warning vest :               | OK | [x]                   | Transport licence :     |        |
| Tax certificate :            |    |                       | Navigation CD/SD/DVD    |        |
| Fuel card :                  |    |                       | Car radio :             |        |
| Mobile phone kit :           |    |                       | Extinguisher :          | OK [x] |
| First aid kit :              | OK | [x]                   | Warning triangle :      | OK [x] |
| Jack, wheelspanner :         | OK | [x]                   | Oil level :             | OK [x] |
|                              |    |                       | Filled up :             | 0      |

## Wheels and tyres: Summer tires

|            |     |             |        |     |     |      |       |       |                 |                 |          |          |
|------------|-----|-------------|--------|-----|-----|------|-------|-------|-----------------|-----------------|----------|----------|
| Wheel FL:  | [x] | BRIDGESTONE | Tyre : | OK  | [x] | 4-6/ | Rim : | [x]   | WHEEL SCRATCHED | /               | Hubcap : |          |
| Wheel RL : | [x] | BRIDGESTONE | Tyre : | OK  | [x] | 4-6/ | Rim : |       |                 | /               | Hubcap : |          |
| Wheel FR : | [x] | BRIDGESTONE | Tyre : | [x] | OK  | [x]  | 4-6/  | Rim : | [x]             | WHEEL SCRATCHED | /        | Hubcap : |
| Wheel RR : | [x] | BRIDGESTONE | Tyre : | OK  | [x] | 4-6/ | Rim : |       |                 | /               | Hubcap : |          |
| Wheel RES: | [x] |             | Tyre : | OK  | [x] | >6/  | Rim : |       |                 | /               | Hubcap : |          |

| [x]        | Width | Height | Type | Rim | Index |
|------------|-------|--------|------|-----|-------|
| Front tyre | 215   | 60     | R    | 16  | V     |
| Rear tyre  | 215   | 60     | R    | 16  | V     |

Remark :

## Wheels and tyres:

|            |  |        |    |   |       |  |   |          |
|------------|--|--------|----|---|-------|--|---|----------|
| Wheel FL:  |  | Tyre : | OK | / | Rim : |  | / | Hubcap : |
| Wheel RL : |  | Tyre : | OK | / | Rim : |  | / | Hubcap : |
| Wheel FR : |  | Tyre : | OK | / | Rim : |  | / | Hubcap : |
| Wheel RR : |  | Tyre : | OK | / | Rim : |  | / | Hubcap : |
| Wheel RES: |  | Tyre : | OK | / | Rim : |  | / | Hubcap : |

| [x]        | Width | Height | Type | Rim | Index |
|------------|-------|--------|------|-----|-------|
| Front tyre | 0     | 0      | R    | 0   |       |
| Rear tyre  | 0     | 0      | R    | 0   |       |

Remark :

## STATUS: ACCEPTABLE / USAGE DAMAGE

### Bodywork \& windows

|     |                            |                                |
|-----|----------------------------|--------------------------------|
| [x] | REAR BUMPER/CENTER/LEFT    | SCRATCH WITH PAINT DAMAGE      |
| [x] | REAR MUDGUARD/RIGHT/FRONT  | DENT                           |
| [x] | REAR DOOR/LEFT/FRONT       | SCRATCH (WITHOUT PAINT DAMAGE) |
| [x] | FRONT THRESHOLD/RIGHT/REAR | SCRATCH (WITHOUT PAINT DAMAGE) |
| [x] | BONNET/CENTER/LEFT/FRONT   | CHIPS                          |
| [x] | FRONT BUMPER/CENTER/RIGHT  | CHIPS                          |

### Interior

|     |             |        |
|-----|-------------|--------|
| [x] | BOOT LID IN | CARVED |
| [x] | BOOT IN L   | CARVED |
| [x] | BOOT IN R   | CARVED |

## STATUS: NOT ACCEPTABLE

### Bodywork \& windows

|     |                            |                     |                          |                      |              |              |
|-----|----------------------------|---------------------|--------------------------|----------------------|--------------|--------------|
| [x] | REAR MUDGUARD/LEFT/FRONT   | DENT                |                          |                      |              |              |
|     | <b>Number</b>              | <b>Code</b>         | <b>Description</b>       | <b>Unit price</b>    | <b>Depr.</b> | <b>Total</b> |
|     | 4                          | I 1 i-vab-uitd-01   | BEAT OUT DENT            | 63.00 EUR            |              | 63.00 EUR    |
| [x] | REAR THRESHOLD/RIGHT/FRONT | DENT                |                          |                      |              |              |
|     |                            |                     | <b>Repair paint - LI</b> | <b>New paint - E</b> | <b>Depr.</b> | <b>Total</b> |
|     | 5                          | 0 LU =0.00 EUR      | 0 EUR                    |                      | 50 %         |              |
|     |                            |                     | <b>Repair paint - LI</b> | <b>New paint - E</b> | <b>Depr.</b> | <b>Total</b> |
|     | 5                          | 40 LU =192.00 EUR   | 0 EUR                    | 414.00 EUR           | 50 %         | 606.00 EUR   |
| [x] | FRONT DOOR/LEFT/CENTER     | DENT                |                          |                      |              |              |
|     |                            |                     | <b>Repair paint - LI</b> | <b>New paint - E</b> | <b>Depr.</b> | <b>Total</b> |
|     | 3                          | 15 LU =72.00 EUR    | 318.35 EUR               |                      | 50 %         | 390.35 EUR   |
| [x] | WINDSCREEN/CENTER/RIGHT    | WINDOW DAMAGE       |                          |                      |              |              |
|     | <b>Number</b>              | <b>Code</b>         | <b>Description</b>       | <b>Unit price</b>    | <b>Depr.</b> | <b>Total</b> |
|     | 2                          | I 1 i-vab-herstr-01 | WINDOW REPAIR            | 58.80 EUR            |              | 58.80 EUR    |

## Others

RIM FRONT LEFT

| Number | Code                  | Description        | Unit price | Depr. | Total     |
|--------|-----------------------|--------------------|------------|-------|-----------|
| 6      | I 1 i-vab-herstalu-02 | REPAIR ALLOY WHEEL | 95.00 EUR  |       | 95.00 EUR |

## Pieces

| Number | Code | Description | Unit price | Depr. | Total      |
|--------|------|-------------|------------|-------|------------|
| 5      | 1    | DOORSTEP    | 250.00 EUR | 50 %  | 250.00 EUR |

| 1 | 2     | 3      | 4     | 5      | 6     | 7 | 8 | 9 | 10 |
|---|-------|--------|-------|--------|-------|---|---|---|----|
| 0 | 58.80 | 390.35 | 63.00 | 856.00 | 95.00 | 0 | 0 | 0 | 0  |
| 0 | 58.80 | 195.18 | 63.00 | 428.00 | 95.00 | 0 | 0 | 0 | 0  |

| INNOVATIVE | TRADITIONAL | GENERAL |                     |
|------------|-------------|---------|---------------------|
| 216.80     | 1246.35     | 0       | <b>1463.15</b>      |
| HOG: 0     | BG: 0       |         | NA Deprec. 839.98   |
|            |             |         | 0.00%               |
|            |             |         | <b>TOTAL 839.98</b> |

[x] = Status Modification


Pictures : No

## CIRCUMSTANCES

NORMAL CONCLUSION

|                           |  |   |
|---------------------------|--|---|
| <b>Extra Time :</b> 0 min | <b>Waiting time :</b> 0 min<br><b>Reason :</b> | <b>Towing time :</b> 0 min<br><b>Reason :</b> |
| <b>NOT EXECUTED :</b> No  |  |   |
| <b>Reason :</b>           |  |   |
| <b>Remark :</b>           |  |   |

## Prices in EUR without VAT

|   |                                |
|---|--------------------------------|
| <b>Authorized by customer :</b><br><br><b>Remark authorized customer :</b><br><br><b>Date :</b> 11/07/2017 <b>Hour :</b> 15:03<br><b>Company :</b><br>Executed by VAB Fleet Services<br><b>E-Mail :</b> @ | Executed by VAB Fleet Services |
| Signature authorized by customer<br><br>  |                                |