

www.vabfleetservices.be Date: 11/07/2017 1/6

BV9CN8

[ ] NOT EXECUTED [X] COLLECTION [X] EFFECTIVE [ ] DELIVERY

[x] = Status Modification

Commissionar: **KBC REMARKETING** Cleanliness: INT: CLEAN [x] EXT: DIRTY [x]

Owner: Mileage : 89337 KM

File nr. : Mileage start / arrival: 0 / 01417174

Reg number / Chassis / Ref: Mileag ref. service : 0 yr of constructionr: 1FFG580 / VF37A9HN0DN515574 /

E-File nr. : First registration: 13/06/2013

VFS-nr.: Color: **BLACK** 

Make + Model : Fuel type : PEUGEOT / PARTNER **DIESEL** 

Object nr. : Fuel: 50292

Classification: **Environment Class:** 

EURO 5 Customer company: Co2: EGEMIN NV

133g/km Driver : Remote controls:

TISSUE Covering: Number keys : 2[x]

Vehicle kind: TRUCK, LORRY Seats (minivan): 0

Vehicle type: PARTNER B/F L1H1 Conf.120 75PK Country registration: **BELGIUM** 

Metallic paint: VAT over the margin - car: No No

**BESTELWAGEN** 1560 Variant car: Engine size:

Gear box : Number of places: 2 Manueel

Number of gears: 5 Number of doors: 5

HP: 75 kW: 55

Animals transported: No Smoked in vehicle: No

Use: Unknown

Imported vehicle:

Extra set of tires:

No

General condition:

Fisc HP

Due date vehicle inspection:



www.vabfleetservices.be Date: 11/07/2017 2/6

Original registr. number :	OK		Service manual :	NOK	[x]
Cert. of reg. / Part 1:			Cert. of conformity:	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :		
Warning vest :	OK	[x]	Transport licence :		
Tax certificate :			Navigation CD/SD/DVD		
Fuel card :			Car radio :	OK	[x]
Mobile phone kit :			Extinguisher :	OK	[x]
			Warning triangle :	OK	[x]
First aid kit :	OK	[x]	Oil level :	OK	[x]
Jack, wheelspanner :	OK	[x]	Filled up :	0	

#### Wheels and tyres: Winter tires

		[x]	Width	1	Height			Туре		Rim	Index
Wheel RES:	[x]	MICHELIN	Tyre:	Ol		/	Rim:		/	Hubcap:	
Wheel RR:	[x]	MICHELIN	Tyre:	Ol	. [	[x] 2-4/	Rim:		/	Hubcap:	
Wheel FR:	[x]	MICHELIN	Tyre:	[x] Ol	[	[x] 2-4/	Rim:		/	<b>Hubcap</b> : [x	] SCRATCHED
Wheel RL:	[x]	MICHELIN	Tyre:	Ol	[	[x] 2-4/	Rim:		/	Hubcap:	
Wheel FL:	[x]	MICHELIN	Tyre:	Ol	. [	[x] 2-4/	Rim:		/	Hubcap: [x	] SCRATCHED

[x]	Width	Height	Type	Rim	Index
Front tyre	195	65	R	15	M+S
Rear tyre	195	65	R	15	M+S

Remark:

#### Wheels and tyres:

Wheel FL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel FR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RES:	Tyre:	OK	/	Rim:	/ Hubcap:
i					

_	[x]	Width	Height	Туре	Rim	Index
	Front tyre	0	0	R	0	
	Rear tyre	0	0	R	0	

Remark:



www.vabfleetservices.be Date: 11/07/2017 3/6



Number Code

WHEEL CAP

## **APPRAISAL**

11/07/2017 Date: www.vabfleetservices.be 4/6

ST	ATUS: ACCEPTABLE /	USAGE DAMAG	E			
Во	dywork \& windows					
[x]	REAR BUMPER/CENTER/RIGHT		SCRATCH WITH PAIR	NT DAMAGE		
[x]	REAR MUDGUARD/RIGHT/CENTER		SCRATCH (WITHOUT	Γ PAINT DAMAGE	(i)	
[x]	BONNET/CENTER/RIGHT/FRONT		SCRATCH WITH PAI	NT DAMAGE		
[x]	ROOF/CENTER/LEFT		DENT			
Ac	cessories and others					
[x]	VEH COVERED WITH STICKERS		STICKER(S)			
ST	ATUS: NOT ACCEPTAB	SLE				
Во	dywork \& windows					
[x]	FRONT BUMPER/RIGHT		SCRATCH WITH PAIR	NT DAMAGE		
		Repair paint - LI	New paint - E		Depr.	Total
	2 0 LU =0.00 EUR	158.85 EUR	1		50 %	158.85 EUR
	Number Code	Description		Unit price	Depr.	Total
	2 I 1 i-vab-kunst-01	PLASTICS REPAIR		110.64 EUR	1	110.64 EUR
Inte	erior					
[x]	SEAT FL		HOLE			
	Number Code	Description		Unit price	Depr.	Total
	1 I 1 i-vab-intvlr-01	VELOURS REPAIR (MA DIAMATER)	X 3CM LENGTH OR	64.32 EUR		64.32 EUR
Oth	ners					
	HUB CAP FL					
		Repair paint - LI	New paint - E		Depr.	Total
	3 0 LU =0.00 EUR				50 %	
	HUB CAP FR					
		Repair paint - LI	New paint - E		Depr.	Total
	3 0 LU =0.00 EUR		_		50 %	,
Pie	ces					
_	Number Code	Description		Unit price	Depr.	Total
	3 1 WHEEL CAP			22.50 EUR	50 %	22.50 EUR
					_	

Unit price

22.50 EUR

Depr.

50 %

Total

22.50 EUR

Description



www.vabfleetservices.be Date: 11/07/2017 5/6

1	2	3	4	5	6	7	8	9	10
64.32	269.49	45.00	0	0	0	0	0	0	0
64.32	190.06	22.50	0	0	0	0	0	0	0

		GENERAL	TRADITIONAL	INNOVATIVE
378.81		0	203.85	174.96
276.88	NA Deprec.		BG: 3	HOG: 0
	0.00%			
276.88	TOTAL			



Date: 11/07/2017 www.vabfleetservices.be 6/6

[x] = Status Modification

Pictures: No

CIRCUMSTANCES			UNDER CONDITION - DUSTY VEHICLE					
Extra Time :	0 min	Waiting time: 0 m Reason:	in	Towing time : Reason :	0 min			
NOT EXECUTED Reason :	: No	<b>I</b>						
Remark :								
Prices in EUR	without VAT							
Authorized by customer:			Executed by VAB Fleet	Services				
Remark authorized	d customer :							
Date :	11/07/2017	<b>Hour:</b> 15:36						
Company:								
Executed by VAB I Services	Fleet							
E-Mail :	@							
Signature authorized	l by customer							