

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	175009 KM
File nr. :	1419712	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
QL4116 / VF15RFL0H50283252 /		yr of constructionr :	/
E-File nr. :		First registration :	03/02/2014
VFS-nr. :		Color :	GREY
Make + Model :	RENAULT / CLIO	Fuel type :	DIESEL
Object nr. :		Fuel :	
Classification :		Environment Class:	
Customer company :	SOLUDEC	Co2:	g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	1 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	CLIO IV BER Expression St&St 90PK	Country registration :	LUXEMBOURG

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:	COMPACT	Engine size:	1461
Gear box :	Manueel	Number of places:	5
Number of gears:	5	Number of doors:	5
HP:	90	kW:	66
Fisc HP		Imported vehicle:	No
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown

General condition:

Original registr. number : OK	Service manual : OK [x]
Cert. of reg. / Part 1:	Cert. of conformity :
Cert. of reg. copy / Part 2:	Insurance certificate :
Warning vest : OK [x]	Transport licence :
Tax certificate :	Navigation CD/SD/DVD
Fuel card :	Car radio : OK [x]
Mobile phone kit :	Extinguisher : OK [x]
First aid kit : OK [x]	Warning triangle : OK [x]
Jack, wheelspanner :	Oil level : OK [x]
	Filled up : 0

Wheels and tyres: Summer tires

Wheel FL: [x] MICHELIN Tyre : OK [x] >6/ Rim : / Hubcap : [x] SCRATCHED
Wheel RL : [x] GOODYEAR Tyre : OK [x] 4-6/ Rim : / Hubcap : [x] SCRATCHED
Wheel FR : [x] MICHELIN Tyre : [x] OK [x] >6/ Rim : / Hubcap : [x] SCRATCHED
Wheel RR : [x] GOODYEAR Tyre : OK [x] 4-6/ Rim : / Hubcap : [x] SCRATCHED
Wheel RES: [x] Tyre : OK / Rim : / Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	185	65	R	15	T
Rear tyre	185	65	R	15	T

Remark :

Wheels and tyres:

Wheel FL: Tyre : OK / Rim : / Hubcap :
Wheel RL : Tyre : OK / Rim : / Hubcap :
Wheel FR : Tyre : OK / Rim : / Hubcap :
Wheel RR : Tyre : OK / Rim : / Hubcap :
Wheel RES: Tyre : OK / Rim : / Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	FRONT THRESHOLD/LEFT/REAR	SCRATCH WITH PAINT DAMAGE	+DEUKEN BINNENIN		
		Repair paint - LI	New paint - E	Depr.	Total
2	0 LU =0.00 EUR	248.40 EUR		50 %	248.40 EUR

Others

HUB CAP FL					
		Repair paint - LI	New paint - E	Depr.	Total
1	0 LU =0.00 EUR			50 %	
HUB CAP REAR RIGHT					
		Repair paint - LI	New paint - E	Depr.	Total
1	0 LU =0.00 EUR			50 %	
HUB CAP FR					
		Repair paint - LI	New paint - E	Depr.	Total
1	0 LU =0.00 EUR			50 %	

Pieces

Number	Code	Description	Unit price	Depr.	Total
1	1	WHEEL CAP	24.00 EUR	50 %	24.00 EUR
Number	Code	Description	Unit price	Depr.	Total
1	1	WHEEL CAP	24.00 EUR	50 %	24.00 EUR
Number	Code	Description	Unit price	Depr.	Total
1	1	WHEEL CAP	24.00 EUR	50 %	24.00 EUR

1	2	3	4	5	6	7	8	9	10
72.00	248.40	0	0	0	0	0	0	0	0
36.00	124.20	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
0	320.40	0	320.40
HOG: 0	BG: 1		NA Deprec. 160.20
			0.00%
			TOTAL 160.20

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 13/07/2017 Hour : 08:55 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	