

BWQB3X

☒ EFFECTIVE
 ☐ NOT EXECUTED
 ☒ COLLECTION
 ☐ DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: DIRTY [x] EXT: CLEAN [x]
Owner :		Mileage :	82064 KM
File nr. :	1418301	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1EJU145 / VF1JZ14B648036568 /		yr of constructionr :	/
E-File nr. :		First registration :	02/01/2013
VFS-nr. :		Color :	GREY
Make + Model :	RENAULT / GRAND SCENIC	Fuel type :	DIESEL
Object nr. :	6276	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	LMS INTERNATIONAL NV	Co2:	105g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	7 [x]
Vehicle type :	GR.SCENIC Energ.Business 7pl.FAP 110PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:	MONOVOLUME	Engine size:	1461
Gear box :	Manueel	Number of places:	7
Number of gears:	6	Number of doors:	5
HP:	110	kW:	81
Fisc HP		Imported vehicle:	No
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown

General condition:	
--------------------	--

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:		Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :	
Warning vest :	OK	[x]	Transport licence :	
Tax certificate :			Navigation CD/SD/DVD	
Fuel card :			Car radio :	OK [x]
Mobile phone kit :			Extinguisher :	OK [x]
			Warning triangle :	OK [x]
First aid kit :	OK	[x]	Oil level :	OK [x]
Jack, wheelspanner :			Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	[x]	PIRELLI	Tyre :	OK	[x]	4-6 /	Rim :		/	Hubcap :
Wheel RL :	[x]	MICHELIN	Tyre :	OK	[x]	4-6 /	Rim :	[x]	WHEEL SCRATCHED	/ Hubcap :
Wheel FR :	[x]	PIRELLI	Tyre :	[x]	OK	[x]	4-6 /	Rim :	[x]	WHEEL SCRATCHED / Hubcap :
Wheel RR :	[x]	MICHELIN	Tyre :	OK	[x]	4-6 /	Rim :		/	Hubcap :
Wheel RES:	[x]		Tyre :	OK		/	Rim :		/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	205	60	R	16	V
Rear tyre	205	60	R	16	V

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :		/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x] REAR DOOR/LEFT/CENTER DENT

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	FRONT DOOR/LEFT/CENTER	SCRATCH WITH PAINT DAMAGE	+DEUKEN		
		Repair paint - LI	New paint - E	Depr.	Total
3	0 LU =0.00 EUR	318.35 EUR		50 %	318.35 EUR
[x]	FRONT DOOR/RIGHT/CENTER	SCRATCH WITH PAINT DAMAGE	+DEUKEN		
		Repair paint - LI	New paint - E	Depr.	Total
4	0 LU =0.00 EUR	318.35 EUR		50 %	318.35 EUR

Others

CLEANLINESS INTERIOR

Number	Code	Description	Unit price	Depr.	Total
1	I 2	specifiek-per-kwartier-a-vab-rein-03	CLEANING INTERIOR	14.58 EUR	29.16 EUR

RIM REAR LEFT

Number	Code	Description	Unit price	Depr.	Total
2	I 1	i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR	95.00 EUR

RIM FRONT RIGHT

Number	Code	Description	Unit price	Depr.	Total
2	I 1	i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR	95.00 EUR

1	2	3	4	5	6	7	8	9	10
29.16	190.00	318.35	318.35	0	0	0	0	0	0
29.16	190.00	159.18	159.18	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
219.16	636.70	0	855.86
HOG: 0	BG: 0		NA Deprec. 537.51
			0.00%
			TOTAL 537.51

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

UNDER CONDITION - VEHICLE WET

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 12/07/2017 Hour : 12:59 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	