

www.vabfleetservices.be Date: 11/07/2017 1/4

BTJT3W

[X] EFFECTIVE [] NOT EXECUTED [X] COLLECTION [] DELIVERY

[x] = Status Modification

Animals transported:

Commissionar: KBC REMARKETING Cleanliness: INT: CLEAN [x] EXT: CLEAN [x]

Owner: 129969 KM

File nr.: 1415892 Mileage start / arrival: 0 / 0

Reg number / Chassis / Ref : Mileag ref. service : 0

1ETI436 / VF1JZ00BD48592715 / yr of constructionr : /

E-File nr.: First registration: 15/03/2013

VFS-nr.: Color: BURGUNDY

Make + Model: RENAULT / GRAND SCENIC Fuel type: DIESEL

Object nr.: Fuel:

Classification: Environment Class: EURO 5

Customer company: BELGACOM INS/FLEET NV Co2: 114g/km

Driver: Remote controls: 2

Covering: PARTIAL LEATHER Number keys: 2[x]Vehicle kind: VEHICLE Seats (minivan): 7[x]

 Vehicle type :
 GR.SCENIC Energ.Privilege 7pl.FAP 130PK
 Country registration :
 BELGIUM

Metallic paint: VAT over the margin - car: No Yes MONOVOLUME 1598 Variant car: Engine size: Gear box : Number of places: 7 Manueel Number of gears: 6 Number of doors: 5

Smoked in vehicle:

HP: 131 kW: 96

Fisc HP Imported vehicle:

Due date vehicle inspection: Extra set of tires: No

Use: Unknown

General condition:



11/07/2017 Date: www.vabfleetservices.be 2/4

Original registr. number :	OK		Service manual :	OK	[x]
Cert. of reg. / Part 1:	OK	[x]	Cert. of conformity:	OK	
Cert. of reg. copy / Part 2:			Insurance certificate :		
Warning vest :	OK	[x]	Transport licence :		
Tax certificate :			Navigation CD/SD/DVD		
Fuel card :			Car radio :	OK	[x]
Mobile phone kit :			Extinguisher :	OK	[x]
			Warning triangle :	OK	[x]
First aid kit :	OK	[x]	Oil level :		
Jack, wheelspanner :	OK	[x]	Filled up :	0	

Wheels and tyres: Summer tires

Fron	t tyre		2	05			4	55			R		17		V]
		[x]	Wi	dth			He	ight			Type		Rim	I	ndex]
Wheel RES:	[x]	AND	DERE	Tyre:		OK		/	Rim:				Hubcap:			
Wheel RR:	[x]	CON	TINENTAL	Tyre:		OK	[x]	2-4 /	Rim:	[x]	WHEEL SCRATCHED)	Hubcap:			
Wheel FR:	[x]	MIC	HELIN	Tyre:	[x]	OK	[x]	2-4 /	Rim:	[x]	WHEEL SCRATCHED)	Hubcap:			
Wheel RL:	[x]	CON	TINENTAL	Tyre:		OK	[x]	2-4 /	Rim:				Hubcap:			
Wheel FL:	[x]	MIC	HELIN	Tyre:		OK	[x]	2-4 /	Rim:				Hubcap:			

[x]	Width	Height	Туре	Rim	Index
Front tyre	205	55	R	17	V
Rear tyre	205	55	R	17	V

Remark:

Wheels and tyres:

Wheel FL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RL:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel FR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RR:	Tyre:	OK	/	Rim:	/ Hubcap:
Wheel RES:	Tyre:	OK	/	Rim:	/ Hubcap:

[x]	Width	Height	Туре	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark:



www.vabfleetservices.be Date: 11/07/2017 3/4

STATUS: ACCEPTABLE / USAGE DAMAGE

FRONT BUMPER/RIGHT/CORNER

[x]

Bodywork \& windows [x] REAR BUMPER/CENTER/RIGHT SCRATCH WITH PAINT DAMAGE REAR MUDGUARD/LEFT/FRONT DENT [x] REAR MUDGUARD/RIGHT/CENTER DENT [x] REAR MUDGUARD/RIGHT/FRONT SCRATCH (WITHOUT PAINT DAMAGE) [x] REAR DOOR/LEFT/CORNER/BELOW SCRATCH WITH PAINT DAMAGE INSTAP [x] [x] FRONT DOOR/LEFT/CENTER DENT FRONT DOOR/RIGHT/REAR SCRATCH WITH PAINT DAMAGE [x] FRONT MUDGUARD/RIGHT/FRONT SCRATCH WITH PAINT DAMAGE [x] BONNET/CENTER/LEFT/FRONT **CHIPS** [x]

1	2	3	4	5	6	7	8	9	10
0	0	0	0	0	0	0	0	0	0
0	0	0	0	0	0	0	0	0	0

SCRATCH WITH PAINT DAMAGE

INNOVATIVE	TRADITIONAL	GENERAL		
0	0	0		0
HOG: 0	BG: 0		NA Deprec.	0
			0.00%	
			TOTAL	0



4/4

11/07/2017 www.vabfleetservices.be Date: [x] = Status Modification **Pictures:** No **CIRCUMSTANCES** NORMAL CONCLUSION Extra Time : $0 \min$ Waiting time: 0 min Towing time : $0 \min$ Reason: Reason: NOT EXECUTED: No Reason: Remark: Prices in EUR without VAT Authorized by Executed by VAB Fleet Services customer : Remark authorized customer : Date: 11/07/2017 Hour: 15:29 Company: Executed by VAB Fleet Services E-Mail: Signature authorized by customer