

BUFY1R

☒ EFFECTIVE ☐ NOT EXECUTED ☒ COLLECTION ☐ DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: DIRTY [x] EXT: CLEAN [x]
Owner :		Mileage :	93232
File nr. :	1416584	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1DEJ489 / VF1JZ14B647129489 /		yr of constructionr :	/
E-File nr. :		First registration :	23/04/2012
VFS-nr. :		Color :	BROWN
Make + Model :	RENAULT / GRAND SCENIC	Fuel type :	DIESEL
Object nr. :	11327	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	KBC BANK NV	Co2:	105g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	7 [x]
Vehicle type :	GR.SCENIC Energ.Business 7pl.FAP 110PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:	MONOVOLUME	Engine size:	1461
Gear box :	Manueel	Number of places:	7
Number of gears:	6	Number of doors:	5
HP:	110	kW:	81
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown

General condition:

Original registr. number :	OK			Service manual :	OK	[x]	
Cert. of reg. / Part 1:				Cert. of conformity :	OK		
Cert. of reg. copy / Part 2:	OK	[x]		Insurance certificate :			
Warning vest :	OK	[x]		Transport licence :			
Tax certificate :				Navigation CD/SD/DVD	OK	[x]	
Fuel card :				Car radio :	OK	[x]	
Mobile phone kit :				Extinguisher :	OK	[x]	
				Warning triangle :	OK	[x]	
First aid kit :	OK	[x]		Oil level :	OK	[x]	
Jack, wheelspanner :	OK	[x]		Filled up :	0		

Wheels and tyres: Summer tires

Wheel FL:	[x]	MICHELIN	Tyre :	OK	[x]	0-1.6 /	Rim :	/	Hubcap :	[x]	SCRATCHED	
Wheel RL :	[x]	MICHELIN	Tyre :	OK	[x]	2-4 /	Rim :	/	Hubcap :			
Wheel FR :	[x]	MICHELIN	Tyre :	[x]	OK	[x]	0-1.6 /	Rim :	/	Hubcap :	[x]	SCRATCHED
Wheel RR :	[x]	MICHELIN	Tyre :	OK	[x]	2-4 /	Rim :	/	Hubcap :	[x]	SCRATCHED	
Wheel RES:	[x]	ANDERE	Tyre :	OK	[x]	>6 /	Rim :	/	Hubcap :			

	[x]	Width	Height	Type	Rim	Index
Front tyre		205	60	R	16	H
Rear tyre		205	60	R	16	H

Remark :

Wheels and tyres:

Wheel FL:	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:	Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR BUMPER /LEFT/CORNER	SCRATCH WITH PAINT DAMAGE
[x]	REAR DOOR/RIGHT/FRONT	SCRATCH WITH PAINT DAMAGE
[x]	WINDSCREEN/CENTER/RIGHT	CHIPS

Interior

[x]	BOOT LID IN	SCRATCHED
-----	-------------	-----------

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR MUDGUARD/RIGHT/CENTER	DENT			
		Repair paint - LI	New paint - E	Depr.	Total
2	20 LU =96.00 EUR	308.20 EUR		50 %	404.20 EUR

Others

CLEANLINESS INTERIOR

Number	Code	Description	Unit price	Depr.	Total
1	I 4	specifiek-per-kwartier-a-vab-rein-03	CLEANING INTERIOR	14.58 EUR	58.32 EUR

1	2	3	4	5	6	7	8	9	10
58.32	404.20	0	0	0	0	0	0	0	0
58.32	202.10	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
58.32	404.20	0	462.52
HOG: 0	BG: 0		NA Deprec. 260.42
			0.00%
			TOTAL 260.42

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

UNDER CONDITION - VEHICLE WET

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 06/07/2017 Hour : 15:11 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	