

BRRPY1

☒ EFFECTIVE ☐ NOT EXECUTED ☒ COLLECTION ☐ DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	181656 KM
File nr. :	1414439	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1GHQ058 / VF1KZ140650240078 /		yr of constructionr :	/
E-File nr. :		First registration :	11/02/2014
VFS-nr. :		Color :	GREY
Make + Model :	RENAULT / MEGANE BREAK	Fuel type :	DIESEL
Object nr. :	12290	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	BROUWERIJEN ALKEN-MAES	Co2:	90g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :		Country registration :	BELGIUM

VAT over the margin - car:		Metallic paint:	Yes
Variant car:	BREAK	Engine size:	1461
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	110	kW:	81
Fisc HP		Imported vehicle:	No
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:			

Original registr. number :	OK			Service manual :			
Cert. of reg. / Part 1:	OK	[x]		Cert. of conformity :	OK		
Cert. of reg. copy / Part 2:				Insurance certificate :			
Warning vest :	OK	[x]		Transport licence :			
Tax certificate :				Navigation CD/SD/DVD			
Fuel card :				Car radio :	OK	[x]	
Mobile phone kit :				Extinguisher :	OK	[x]	
				Warning triangle :	OK	[x]	
First aid kit :	OK	[x]		Oil level :	OK	[x]	
Jack, wheelspanner :				Filled up :	0		

Wheels and tyres: Summer tires

Wheel FL:	[x]	UNIROYAL	Tyre :	OK	[x]	2-4 /	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :	
Wheel RL :	[x]	UNIROYAL	Tyre :	OK	[x]	2-4 /	Rim :			/	Hubcap :	
Wheel FR :	[x]	UNIROYAL	Tyre :	[x]	OK	[x]	2-4 /	Rim :		/	Hubcap :	
Wheel RR :	[x]	UNIROYAL	Tyre :	OK	[x]	2-4 /	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :	
Wheel RES:	[x]		Tyre :	OK		/	Rim :			/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	205	50	R	17	Y
Rear tyre	205	50	R	17	Y

Remark :

Wheels and tyres:

Wheel FL:	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:	Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR WINDOW/LEFT	SCRATCH WITH PAINT DAMAGE			
		Repair paint - LI	New paint - E	Depr.	Total
3	0 LU =0.00 EUR	0 EUR		50 %	
		Repair paint - LI	New paint - E	Depr.	Total
3	25 LU =120.00 EUR	0 EUR		50 %	120.00 EUR
[x]	REAR DOOR/LEFT/CENTER	SCRATCH WITH PAINT DAMAGE +DEUK			
		Repair paint - LI	New paint - E	Depr.	Total
2	0 LU =0.00 EUR	318.35 EUR		50 %	318.35 EUR

Interior

[x]	SEAT FL	STAIN			
Number	Code	Description	Unit price	Depr.	Total
4	I 1 i-vab-rein-07	CLEANING (PER 15')	14.58 EUR		14.58 EUR

Others

RIM FRONT LEFT

Number	Code	Description	Unit price	Depr.	Total
1	I 1 i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

RIM REAR RIGHT

Number	Code	Description	Unit price	Depr.	Total
1	I 1 i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

Pieces

Number	Code	Description	Unit price	Depr.	Total
3	1 BACK WINDOW		250.00 EUR	50 %	250.00 EUR

1	2	3	4	5	6	7	8	9	10
190.00	318.35	370.00	14.58	0	0	0	0	0	0
190.00	159.18	185.00	14.58	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
204.58	688.35	0	892.93
HOG: 0	BG: 0		NA Deprec. 548.76
			0.00%
			TOTAL 548.76

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 06/07/2017 Hour : 11:57 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	