

BMEJDT

☒ EFFECTIVE ☐ NOT EXECUTED ☒ COLLECTION ☐ DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	153696 KM
File nr. :	1410244	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1FCO199 / TMBHT21Z4D2126424 /		yr of constructionr :	/
E-File nr. :		First registration :	24/05/2013
VFS-nr. :		Color :	BLACK
Make + Model :	SKODA / OCTAVIA	Fuel type :	DIESEL
Object nr. :		Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	KINEPOLIS GROUP NV (GROUP)	Co2:	109g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	OCTAVIA COMBI GTec Ambition DPF 105PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	
Variant car:	BREAK	Engine size:	1598
Gear box :	Manueel	Number of places:	5
Number of gears:	5	Number of doors:	5
HP:	105	kW:	77
Fisc HP		Imported vehicle:	No
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown

General condition:	
--------------------	--

Original registr. number :	OK			Service manual :	OK	[x]
Cert. of reg. / Part 1:				Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:	OK	[x]		Insurance certificate :		
Warning vest :	OK	[x]		Transport licence :		
Tax certificate :				Navigation CD/SD/DVD		
Fuel card :				Car radio :	OK	[x]
Mobile phone kit :				Extinguisher :	OK	[x]
				Warning triangle :	OK	[x]
First aid kit :	OK	[x]		Oil level :	OK	[x]
Jack, wheelspanner :	OK	[x]		Filled up :	0	

Wheels and tyres: Summer tires

Wheel FL :	[x]	CONTINENTAL	Tyre :	OK	[x]	1.6-2 /	Rim :		/	Hubcap :	
Wheel RL :	[x]	CONTINENTAL	Tyre :	OK	[x]	4-6 /	Rim :		/	Hubcap :	
Wheel FR :	[x]	CONTINENTAL	Tyre :	[x]	OK	[x]	1.6-2 /	Rim :	[x]	WHEEL SCRATCHED	/ Hubcap :
Wheel RR :	[x]	CONTINENTAL	Tyre :	OK	[x]	4-6 /	Rim :		/	Hubcap :	
Wheel RES:	[x]	ANDERE	Tyre :	OK	[x]	>6 /	Rim :		/	Hubcap :	

	[x]	Width	Height	Type	Rim	Index
Front tyre		205	55	R	16	H
Rear tyre		205	55	R	16	H

Remark :

Wheels and tyres:

Wheel FL:	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:	Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR DOOR/LEFT/FRONT	SCRATCH (WITHOUT PAINT DAMAGE)
[x]	REAR DOOR/RIGHT/REAR	SCRATCH (WITHOUT PAINT DAMAGE)
[x]	FRONT DOOR/LEFT/CENTER	SCRATCH (WITHOUT PAINT DAMAGE)
[x]	FRONT DOOR/RIGHT/REAR	SCRATCH (WITHOUT PAINT DAMAGE)

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR BUMPER/LEFT/LEFT	SCRATCH WITH PAINT DAMAGE			
		Repair paint - LI	New paint - E	Depr.	Total
1	0 LU =0.00 EUR	211.80 EUR		50 %	211.80 EUR

Interior

[x]	BOOT LID IN		CARVED			
	Number	Code	Description	Unit price	Depr.	Total
2	I 1	i-vab-intdash-01	PLASTICS REPAIR INTERIRO	110.64 EUR		110.64 EUR

Others

RIM FRONT RIGHT

Number	Code	Description	Unit price	Depr.	Total
3	I 1 i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

Pieces

Number	Code	Description	Unit price	Depr.	Total
1	1 REFLECTOR		20.00 EUR	50 %	20.00 EUR

1	2	3	4	5	6	7	8	9	10
231.80	110.64	95.00	0	0	0	0	0	0	0
115.90	110.64	95.00	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
205.64	231.80	0	437.44
HOG: 0	BG: 0		NA Deprec. 321.54
			0.00%
			TOTAL 321.54

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 04/07/2017 Hour : 08:56 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	