

BVSR2D

☒ EFFECTIVE    ☐ NOT EXECUTED    ☐ COLLECTION    ☐ DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: DIRTY [x] EXT: CLEAN [x]
Owner :		Mileage :	175797 KM
File nr. :	1417598	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1FCY736 / VF1KT1RG649219112 /		yr of constructionr :	/
E-File nr. :		First registration :	28/05/2013
VFS-nr. :		Color :	BLACK
Make + Model :	RENAULT / LAGUNA BREAK	Fuel type :	DIESEL
Object nr. :		Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	MAN ROLAND BENELUX NV	Co2:	112g/km
Driver :		Remote controls:	2
Covering :	TISSUE-LEATHER	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	LAGUNA BRE ECO2 Champion Sp.Ed.FAP 110PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:	BREAK	Engine size:	1461
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	110	kW:	81
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:			

<b>Original registr. number :</b>	OK		<b>Service manual :</b>	OK	[x]
<b>Cert. of reg. / Part 1:</b>			<b>Cert. of conformity :</b>	OK	
<b>Cert. of reg. copy / Part 2:</b>	OK	[x]	<b>Insurance certificate :</b>		
<b>Warning vest :</b>	OK	[x]	<b>Transport licence :</b>		
<b>Tax certificate :</b>			<b>Navigation CD/SD/DVD</b>	OK	[x]
<b>Fuel card :</b>			<b>Car radio :</b>	OK	[x]
<b>Mobile phone kit :</b>			<b>Extinguisher :</b>	OK	[x]
			<b>Warning triangle :</b>	OK	[x]
<b>First aid kit :</b>	OK	[x]	<b>Oil level :</b>	OK	[x]
<b>Jack, wheelspanner :</b>	OK	[x]	<b>Filled up :</b>	0	

## Wheels and tyres: Summer tires

<b>Wheel FL :</b>	[x]	BRIDGESTONE	<b>Tyre :</b>	OK	[x]	4-6 /	<b>Rim :</b>		/	<b>Hubcap :</b>			
<b>Wheel RL :</b>	[x]	MICHELIN	<b>Tyre :</b>	OK	[x]	2-4 /	<b>Rim :</b>	[x]	WHEEL SCRATCHED	/	<b>Hubcap :</b>		
<b>Wheel FR :</b>	[x]	BRIDGESTONE	<b>Tyre :</b>	[x]	OK	[x]	4-6 /	<b>Rim :</b>	[x]	WHEEL SCRATCHED	/	<b>Hubcap :</b>	
<b>Wheel RR :</b>	[x]	MICHELIN	<b>Tyre :</b>	OK	[x]	2-4 /	<b>Rim :</b>	[x]	WHEEL SCRATCHED	/	<b>Hubcap :</b>		
<b>Wheel RES:</b>	[x]	CONTINENTAL	<b>Tyre :</b>	OK	[x]	>6 /	<b>Rim :</b>		/	<b>Hubcap :</b>			

  

	[x]	<b>Width</b>	<b>Height</b>	<b>Type</b>	<b>Rim</b>	<b>Index</b>
<b>Front tyre</b>		215	50	R	17	W
<b>Rear tyre</b>		215	50	R	17	V

  

**Remark :**

### Wheels and tyres:

Wheel FL:	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:	Tyre :	OK	/	Rim :	/	Hubcap :

  

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

  

Remark :

## STATUS: ACCEPTABLE / USAGE DAMAGE

### Bodywork \& windows

[x]	REAR MUDGUARD/RIGHT/CENTER	DENT
[x]	THRESHOLD FRONT/LEFT/CENTER	SCRATCH WITH PAINT DAMAGE
[x]	WINDSCREEN/CENTER/RIGHT	CHIPS
[x]	FRONT DOOR/RIGHT/CENTER	SCRATCH WITH PAINT DAMAGE
[x]	FRONT THRESHOLD/RIGHT/CENTER	DENT
[x]	FRONT MUDGUARD/LEFT/FRONT	DENT
[x]	BONNET/CENTER/RIGHT/FRONT	CHIPS

### Interior

[x]	BOOT LID IN	SCRATCHED
-----	-------------	-----------

## STATUS: NOT ACCEPTABLE

### Bodywork \& windows

[x]	REAR BUMPER/RIGHT/CORNER	SCRATCH WITH PAINT DAMAGE			
		Repair paint - LI	New paint - E	Depr.	Total
2	0 LU =0.00 EUR	211.80 EUR		50 %	211.80 EUR
[x]	REAR DOOR/RIGHT/CENTER	DENT			
		Repair paint - LI	New paint - E	Depr.	Total
4	0 LU =0.00 EUR	318.35 EUR		50 %	318.35 EUR
[x]	FRONT BUMPER/RIGHT/CORNER	SCRATCH WITH PAINT DAMAGE			
		Repair paint - LI	New paint - E	Depr.	Total
1	0 LU =0.00 EUR	211.80 EUR		50 %	211.80 EUR

### Others

RIM FRONT RIGHT

Number	Code	Description	Unit price	Depr.	Total
3	I 1	i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR	95.00 EUR

1	2	3	4	5	6	7	8	9	10
211.80	211.80	95.00	318.35	0	0	0	0	0	0
105.90	105.90	95.00	159.18	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
95.00	741.95	0	836.95
HOG: 0	BG: 0		NA Deprec. 465.98
			0.00%
			TOTAL 465.98

[x] = Status Modification

Pictures : No

## CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

## Prices in EUR without VAT

Authorized by customer :  Remark authorized customer :  Date : 06/07/2017      Hour : 10:17 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	