

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	80929 KM
File nr. :	1418745	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1EMN781 / WAUZZZ8K0DA183923 /		yr of constructionr :	/
E-File nr. :		First registration :	23/01/2013
VFS-nr. :		Color :	GREY
Make + Model :	AUDI / A4	Fuel type :	DIESEL
Object nr. :	71942	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	ETS FRANCIS FLERON GMS SA	Co2:	116g/km
Driver :		Remote controls:	1
Covering :	LEATHER	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	A4 AVANT TDie 136PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:	BREAK	Engine size:	1968
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	136	kW:	100
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	
		Use:	Unknown

General condition:

Original registr. number : OK	Service manual : OK [x]
Cert. of reg. / Part 1:	Cert. of conformity : OK
Cert. of reg. copy / Part 2: OK [x]	Insurance certificate :
Warning vest :	Transport licence :
Tax certificate :	Navigation CD/SD/DVD
Fuel card :	Car radio : OK [x]
Mobile phone kit :	Extinguisher : OK [x]
First aid kit : OK [x]	Warning triangle : OK [x]
Jack, wheelspanner :	Oil level : OK [x]
	Filled up : 0

Wheels and tyres: Winter tires

Wheel FL: [x] CONTINENTAL Tyre : OK [x] 2-4/ Rim : / Hubcap :
Wheel RL : [x] CONTINENTAL Tyre : OK [x] 2-4/ Rim : / Hubcap :
Wheel FR : [x] CONTINENTAL Tyre : [x] OK [x] 2-4/ Rim : / Hubcap :
Wheel RR : [x] CONTINENTAL Tyre : OK [x] 2-4/ Rim : / Hubcap :
Wheel RES: [x] Tyre : OK / Rim : / Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	205	60	R	16	M+S
Rear tyre	205	60	R	16	M+S

Remark :

Wheels and tyres:

Wheel FL: Tyre : OK / Rim : / Hubcap :
Wheel RL : Tyre : OK / Rim : / Hubcap :
Wheel FR : Tyre : OK / Rim : / Hubcap :
Wheel RR : Tyre : OK / Rim : / Hubcap :
Wheel RES: Tyre : OK / Rim : / Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

- [x] REAR DOOR/RIGHT/REAR DENT
- [x] BONNET/CENTER/LEFT/FRONT CHIPS

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR BUMPER/RIGHT/RIGHT	SCRATCH WITH PAINT DAMAGE			
			Repair paint - LI	New paint - E	Depr.
					Total
4	0 LU =0.00 EUR		211.80 EUR		50 %
					211.80 EUR
[x]	WINDSCREEN/LEFT	SCRATCH WITH PAINT DAMAGE			
			Repair paint - LI	New paint - E	Depr.
					Total
3	25 LU =120.00 EUR		0 EUR		50 %
					120.00 EUR
[x]	BONNET/CENTER/LEFT	OTHER DAMAGES			ISOLATIE
			Repair paint - LI	New paint - E	Depr.
					Total
5	5 LU =24.00 EUR		0 EUR		50 %
					24.00 EUR
[x]	FRONT BUMPER/RIGHT/CORNER	SCRATCH WITH PAINT DAMAGE			
			Repair paint - LI	New paint - E	Depr.
					Total
2	0 LU =0.00 EUR		211.80 EUR		50 %
					211.80 EUR

Interior

- [x] FLOOR BOOT DIRTY

Number	Code	Description	Unit price	Depr.	Total
1	I 1	specifiek-per-kwartier-a-vab-rein-03	CLEANING INTERIOR	14.58 EUR	50 %
					14.58 EUR

Pieces

Number	Code	Description	Unit price	Depr.	Total
3	1	WIND SCREEN	367.20 EUR	50 %	367.20 EUR
Number	Code	Description	Unit price	Depr.	Total
5	1	ISOLATIE	50.00 EUR	50 %	50.00 EUR

1	2	3	4	5	6	7	8	9	10
14.58	211.80	487.20	211.80	74.00	0	0	0	0	0
7.29	105.90	243.60	105.90	37.00	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
14.58	984.80	0	999.38
HOG: 0	BG: 0		NA Deprec. 499.69
			0.00%
			TOTAL 499.69

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 18/07/2017 Hour : 08:22 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	