

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	159192 KM
File nr. :	1419958	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1FBE099 / WAUZZZ8V4DA077288 /		yr of constructionr :	/
E-File nr. :		First registration :	14/05/2013
VFS-nr. :		Color :	BLACK
Make + Model :	AUDI / A3	Fuel type :	DIESEL
Object nr. :		Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	SOA PEOPLE SA	Co2:	99g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :		Seats (minivan) :	0
Vehicle type :	A3 SB Attraction 105PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:		Engine size:	1598
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	105	kW:	77
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown

General condition:

Original registr. number : OK	Service manual : OK
Cert. of reg. / Part 1:	Cert. of conformity : OK
Cert. of reg. copy / Part 2: OK	Insurance certificate :
Warning vest : OK	Transport licence :
Tax certificate :	Navigation CD/SD/DVD OK
Fuel card :	Car radio : OK
Mobile phone kit :	Extinguisher : OK
First aid kit : OK	Warning triangle : OK
Jack, wheelspanner :	Oil level : OK [x]
	Filled up : 0

Wheels and tyres: Summer tires

Wheel FL: [x] PIRELLI Tyre : OK [x] 2-4/ Rim : [x] / Hubcap :
Wheel RL : [x] DUNLOP Tyre : OK >6/ Rim : / Hubcap :
Wheel FR : [x] PIRELLI Tyre : [x] OK [x] 2-4/ Rim : [x] WHEEL SCRATCHED / Hubcap :
Wheel RR : [x] DUNLOP Tyre : OK >6/ Rim : [x] WHEEL SCRATCHED / Hubcap :
Wheel RES: [x] ANDERE Tyre : OK / Rim : / Hubcap :

	Width	Height	Type	Rim	Index
Front tyre	205	55	R	16	W
Rear tyre	205	55	R	16	W

Remark : REP. KIT OK

Wheels and tyres:

Wheel FL: Tyre : OK / Rim : / Hubcap :
Wheel RL : Tyre : OK / Rim : / Hubcap :
Wheel FR : Tyre : OK / Rim : / Hubcap :
Wheel RR : Tyre : OK / Rim : / Hubcap :
Wheel RES: Tyre : OK / Rim : / Hubcap :

	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR MUDGUARD/LEFT/REAR	SCRATCH (WITHOUT PAINT DAMAGE)
[x]	REAR MUDGUARD/RIGHT/FRONT	DENT
[x]	REAR DOOR/RIGHT/CORNER/BELOW	CHIPS
[x]	ROOF STYLE/FRONT/RIGHT/CENTER	CHIPS
[x]	FRONT DOOR/RIGHT/REAR	DENT
[x]	BONNET/CENTER/LEFT/FRONT	CHIPS

Interior

	FLOOR BOOT	STAIN
[x]	BOOT LID IN	SCRATCHED

Accessories and others

	OUTSIDE MIRROR RIGHTHAND SIDE	SCRATCH (WITHOUT PAINT DAMAGE)
--	-------------------------------	--------------------------------

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR BUMPER /LEFT/CORNER	SCRATCH WITH PAINT DAMAGE	+DEUK IN HET MIDDEN			
		Repair paint - LI	New paint - E	Depr.	Total	
5	0 LU =0.00 EUR	169.44 EUR			169.44 EUR	
[x]	REAR WINDOW STYLE/LEFT/REAR	DENT				
		Repair paint - LI	New paint - E	Depr.	Total	
3	0 LU =0.00 EUR	246.56 EUR		50 %	246.56 EUR	
[x]	FRONT MUDGUARD/RIGHT/FRONT	SCRATCH WITH PAINT DAMAGE				
		Repair paint - LI	New paint - E	Depr.	Total	
4	0 LU =0.00 EUR	176.14 EUR		50 %	176.14 EUR	
[x]	FRONT BUMPER/RIGHT/CORNER	SCRATCH WITH PAINT DAMAGE				
		Repair paint - LI	New paint - E	Depr.	Total	
4	0 LU =0.00 EUR	169.44 EUR		50 %	169.44 EUR	
	Number	Code	Description	Unit price	Depr.	Total
4	I 1	i-vab-kunst-01	PLASTICS REPAIR	110.64 EUR		110.64 EUR

[x] WIND SCREEN/BELOW/RIGHT

WINDOW DAMAGE

Number	Code	Description	Unit price	Depr.	Total
2	I 1	i-vab-herstr-01	WINDOW REPAIR	58.80 EUR	58.80 EUR

Others

RIM FRONT RIGHT

Number	Code	Description	Unit price	Depr.	Total
1	I 1	i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR	95.00 EUR

1	2	3	4	5	6	7	8	9	10
95.00	58.80	246.56	456.22	169.44	0	0	0	0	0
95.00	58.80	123.28	283.43	169.44	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
264.44	761.58	0	1026.02
HOG: 0	BG: 1		NA Deprec. 729.95
			0.00%
			TOTAL 729.95

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark : CONTROLE OVVBH = ZIE VORIG BESTEK [x]		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 18/07/2017 Hour : 15:13 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	