

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: DIRTY [x] EXT: DIRTY [x]
Owner :		Mileage :	179326 KM
File nr. :	1423843	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
YH5239 / WAUZZZ8K3FN047037 /		yr of constructionr :	/
E-File nr. :		First registration :	22/06/2015
VFS-nr. :		Color :	BLACK
Make + Model :	AUDI / A4 AVANT	Fuel type :	DIESEL
Object nr. :	ONBEKEND	Fuel :	
Classification :	F	Environment Class:	
Customer company :	ONBEKEND	Co2:	g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :		Country registration :	LUXEMBOURG

VAT over the margin - car:		Metallic paint:	Yes
Variant car:	BERLINE	Engine size:	1968
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	4
HP:	136	kW:	100
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	
Due date vehicle inspection:		Extra set of tires:	
		Use:	Unknown

General condition:

Original registr. number :		Service manual :	OK	[x]
Cert. of reg. / Part 1:		Cert. of conformity :		
Cert. of reg. copy / Part 2:		Insurance certificate :		
Warning vest :	OK	[x]		
Tax certificate :		Transport licence :		
Fuel card :		Navigation CD/SD/DVD		
Mobile phone kit :		Car radio :		
First aid kit :	OK	[x]		
Jack, wheelspanner :	OK	[x]		
		Extinguisher :	OK	[x]
		Warning triangle :	OK	[x]
		Oil level :	OK	[x]
		Filled up :	0	

Wheels and tyres: Summer tires

Wheel FL:	[x]	MICHELIN	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :	
Wheel RL :	[x]	MICHELIN	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :	
Wheel FR :	[x]	MICHELIN	Tyre :	[x]	OK	[x]	2-4/	Rim :	/	Hubcap :
Wheel RR :	[x]	MICHELIN	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :	
Wheel RES:	[x]		Tyre :	OK	[x]	>6/	Rim :	/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	205	60	R	16	V
Rear tyre	205	60	R	16	V

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR BUMPER/CENTER/RIGHT	SCRATCH (WITHOUT PAINT DAMAGE)			
[x]	REAR MUDGUARD/RIGHT/FRONT	SCRATCH WITH PAINT DAMAGE			
[x]	FRONT THRESHOLD/LEFT/REAR	DENT			
[x]	FRONT DOOR/LEFT/REAR	SCRATCH WITH PAINT DAMAGE			
[x]	FRONT DOOR/RIGHT/CENTER	SCRATCH (WITHOUT PAINT DAMAGE)			
[x]	BONNET/CENTER/LEFT/FRONT	CHIPS	SLECHTE HERSTELLING		

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	FRONT MUDGUARD/RIGHT/CENTER	OTHER DAMAGES	SLECHTE HERSTELLING		
-----	-----------------------------	---------------	---------------------	--	--

Number	Code	Description	Unit price	Depr.	Total
0	0				

[x]	FRONT BUMPER/RIGHT	OTHER DAMAGES	SLECHTE HERSTELLING		
-----	--------------------	---------------	---------------------	--	--

Number	Code	Description	Unit price	Depr.	Total
0	0				

Others

CLEANLINESS INTERIOR

Number	Code	Description	Unit price	Depr.	Total
1	I 4	personenwagen-a-vab-rein-02	CLEANING INTERIOR	11.47 EUR	45.88 EUR

1	2	3	4	5	6	7	8	9	10
45.88	0	0	0	0	0	0	0	0	0
45.88	0	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
45.88	0	0	45.88
HOG: 0	BG: 0		NA Deprec. 45.88
			0.00%
			TOTAL 45.88

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 26/07/2017 Hour : 15:18 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	