

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	144938 KM
File nr. :	1420578	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1EXG577 / WBAFW11050C714456 /		yr of constructionr :	/
E-File nr. :		First registration :	12/04/2013
VFS-nr. :		Color :	GREY
Make + Model :	BMW / 5	Fuel type :	DIESEL
Object nr. :	69065	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	FLUXYS BELGIUM NV	Co2:	125g/km
Driver :		Remote controls:	2
Covering :	LEATHER	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	5 BER 520d Start/Stop 163PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:	BERLINE	Engine size:	1995
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	4
HP:	163	kW:	120
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown

General condition:

Original registr. number :	OK	Service manual :	
Cert. of reg. / Part 1:		Cert. of conformity :	OK
Cert. of reg. copy / Part 2:	OK [x]	Insurance certificate :	
Warning vest :	OK [x]	Transport licence :	
Tax certificate :	[x]	Navigation CD/SD/DVD	
Fuel card :		Car radio :	OK [x]
Mobile phone kit :		Extinguisher :	OK [x]
First aid kit :	OK [x]	Warning triangle :	OK [x]
Jack, wheelspanner :	OK [x]	Oil level :	OK [x]
		Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	[x]	BRIDGESTONE	Tyre :	OK [x]	2-4/	Rim :	/	Hubcap :
Wheel RL :	[x]	BRIDGESTONE	Tyre :	OK [x]	2-4/	Rim :	/	Hubcap :
Wheel FR :	[x]	BRIDGESTONE	Tyre :	[x] OK [x]	2-4/	Rim :	[x] WHEEL SCRATCHED	Hubcap :
Wheel RR :	[x]	BRIDGESTONE	Tyre :	OK [x]	2-4/	Rim :	/	Hubcap :
Wheel RES:	[x]		Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	225	55	R	17	W
Rear tyre	225	55	R	17	W

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x] FRONT BUMPER/RIGHT

SCRATCH WITH PAINT DAMAGE

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x] REAR BUMPER/CENTER/LEFT

OTHER DAMAGES

SLECHTE HERSTELLING

Number	Code	Description	Unit price	Depr.	Total
0	0				

1	2	3	4	5	6	7	8	9	10
0	0	0	0	0	0	0	0	0	0
0	0	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
0	0	0	0
HOG: 0	BG: 2		NA Deprec. 0
			0.00%
			TOTAL 0

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 20/07/2017 Hour : 16:29 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	