

COKFI7

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	182718 KM
File nr. :	1421326	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1FID438 / WF0LXXGCBLDR07945 /		yr of constructionr :	/
E-File nr. :		First registration :	04/07/2013
VFS-nr. :		Color :	WHITE
Make + Model :	FORD / FOCUS	Fuel type :	DIESEL
Object nr. :	37998	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	FABORY CENTRES BELGIUM NV	Co2:	88g/km
Driver :		Remote controls:	1
Covering :	TISSUE	Number keys :	1 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	FOCUS CLIP. EConetic Trend 88g 105PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:	BREAK	Engine size:	1560
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	105	kW:	77
Fisc HP		Imported vehicle:	No
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown

General condition:

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:		Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :	
Warning vest :	OK	[x]	Transport licence :	
Tax certificate :			Navigation CD/SD/DVD	
Fuel card :			Car radio :	OK [x]
Mobile phone kit :			Extinguisher :	OK [x]
First aid kit :	OK	[x]	Warning triangle :	OK [x]
Jack, wheelspanner :			Oil level :	OK [x]
			Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :	Tyre :	OK	/	Rim :	/	Hubcap : [x] SCRATCHED
Wheel RR :	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:	Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	205	55	R	16	H
Rear tyre	205	55	R	16	H

Remark :

Wheels and tyres:

Wheel FL:	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :	Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:	Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]		Repair paint - LI	New paint - E	Depr.	Total
	FRONT DOOR/LEFT/REAR		SCRATCH WITH PAINT DAMAGE		
2	0 LU =0.00 EUR	318.35 EUR		50 %	318.35 EUR

Others

		Repair paint - LI	New paint - E	Depr.	Total
	HUB CAP FR				
1	0 LU =0.00 EUR			50 %	

Pieces

Number	Code	Description	Unit price	Depr.	Total
1	1	WHEEL CAP	30.00 EUR	50 %	30.00 EUR

1	2	3	4	5	6	7	8	9	10
30.00	318.35	0	0	0	0	0	0	0	0
15.00	159.18	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
0	348.35	0	348.35
HOG: 0	BG: 0		NA Deprec. 174.18
			0.00%
			TOTAL 174.18

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 26/07/2017 Hour : 07:09 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	