

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: DIRTY [x] EXT: CLEAN [x]
Owner :		Mileage :	145993 KM
File nr. :	1420898	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1DNR374 / VF7UA9HR8CJ614248 /		yr of constructionr :	/
E-File nr. :		First registration :	02/07/2012
VFS-nr. :		Color :	GREY
Make + Model :	CITROEN / C4 PICASSO	Fuel type :	DIESEL
Object nr. :	8050	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	G4S SECURE SOLUTIONS NV BE	Co2:	135g/km
Driver :		Remote controls:	1
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	7 [x]
Vehicle type :	GR.C4 PICASSO 7pl.Business FAP 112PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:	MONOVOLUME	Engine size:	1560
Gear box :	Manueel	Number of places:	7
Number of gears:	6	Number of doors:	5
HP:	112	kW:	82
Fisc HP		Imported vehicle:	No
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:			

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:		Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :	
Warning vest :	OK	[x]	Transport licence :	
Tax certificate :			Navigation CD/SD/DVD	
Fuel card :			Car radio :	OK [x]
Mobile phone kit :			Extinguisher :	OK [x]
First aid kit :	OK	[x]	Warning triangle :	OK [x]
Jack, wheelspanner :			Oil level :	OK [x]
			Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	[x]	MICHELIN	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :	
Wheel RL :	[x]	MICHELIN	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :	
Wheel FR :	[x]	MICHELIN	Tyre :	[x]	OK	[x]	2-4/	Rim :	/	Hubcap :
Wheel RR :	[x]	MICHELIN	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :	
Wheel RES:	[x]		Tyre :	OK	/		Rim :	/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	215	55	R	16	H
Rear tyre	215	55	R	16	H

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR BUMPER/CENTER/LEFT		SCRATCH WITH PAINT DAMAGE		
		Repair paint - LI	New paint - E	Depr.	Total
3	0 LU =0.00 EUR	211.80 EUR		50 %	211.80 EUR

[x]	FRONT BUMPER/RIGHT/CORNER		SCRATCH WITH PAINT DAMAGE		
		Repair paint - LI	New paint - E	Depr.	Total
2	0 LU =0.00 EUR	211.80 EUR		50 %	211.80 EUR

Interior

[x]	SEAT FL		CUT / TORN			
	Number	Code	Description	Unit price	Depr.	Total
4	I 1	i-vab-intvlr-01	VELOURS REPAIR (MAX 3CM LENGTH OR DIAMATER)	64.32 EUR		64.32 EUR

Others

CLEANLINESS INTERIOR

	Number	Code	Description	Unit price	Depr.	Total
1	I 4	specifiek-per-kwartier-a-vab-rein-03	CLEANING INTERIOR	14.58 EUR		58.32 EUR

1	2	3	4	5	6	7	8	9	10
58.32	211.80	211.80	64.32	0	0	0	0	0	0
58.32	105.90	105.90	64.32	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
122.64	423.60	0	546.24
HOG: 0	BG: 0		NA Deprec. 334.44
			0.00%
			TOTAL 334.44

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 24/07/2017 Hour : 11:21 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	