

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: DIRTY [x]
Owner :		Mileage :	117463 KM
File nr. :	1421004	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1CRZ384 / VF7UA9HR8CJ521200 /		yr of constructionr :	/
E-File nr. :		First registration :	14/02/2012
VFS-nr. :		Color :	GREY
Make + Model :	CITROEN / C4 PICASSO	Fuel type :	DIESEL
Object nr. :		Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	CBC BANQUE SA	Co2:	135g/km
Driver :		Remote controls:	1
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	7 [x]
Vehicle type :	GR.C4 PICASSO Bus.GPS FAP 112PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:	MONOVOLUME	Engine size:	1560
Gear box :	Manueel	Number of places:	7
Number of gears:	6	Number of doors:	5
HP:	112	kW:	82
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:	ZETEL VL = VAST		

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:		Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :	
Warning vest :		Transport licence :		
Tax certificate :		Navigation CD/SD/DVD		
Fuel card :	OK	[x]	Car radio :	
Mobile phone kit :		Extinguisher :	OK	[x]
First aid kit :	OK	[x]	Warning triangle :	OK
Jack, wheelspanner :		Oil level :	OK	[x]
		Filled up :	0	

Wheels and tyres: Summer tires

Wheel FL:	[x]	BRIDGESTONE	Tyre :	OK	[x]	4-6/	Rim :	/	Hubcap :
Wheel RL :	[x]	BRIDGESTONE	Tyre :	OK	[x]	>6/	Rim :	[x]	WHEEL SCRATCHED
Wheel FR :	[x]	BRIDGESTONE	Tyre :	[x]	OK	[x]	4-6/	Rim :	/
Wheel RR :	[x]	BRIDGESTONE	Tyre :	OK	[x]	>6/	Rim :	[x]	WHEEL SCRATCHED
Wheel RES:	[x]	ANDERE	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	215	55	R	16	W
Rear tyre	215	55	R	16	W

Remark : VELGEN OVBH = VUIL

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR DOOR/RIGHT/REAR	DENT
[x]	REAR DOOR/RIGHT/CORNER/BELOW	SCRATCH WITH PAINT DAMAGE
[x]	FRONT DOOR/RIGHT/REAR	DENT
[x]	FRONT MUDGUARD/LEFT/FRONT	SCRATCH (WITHOUT PAINT DAMAGE)
[x]	BONNET/CENTER/LEFT/FRONT	CHIPS

Interior

[x]	BOOT LID IN	SCRATCHED
-----	-------------	-----------

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR BUMPER/SIDE/LEFTCENTER	SCRATCH WITH PAINT DAMAGE	REEDS AANGEG.
		Repair paint - LI	New paint - E
		Depr.	Total
5	0 LU =0.00 EUR	211.80 EUR	50 % 211.80 EUR
[x]	REAR MUDGUARD/LEFT/FRONT	DENT	REEDS AANGEG.
		Repair paint - LI	New paint - E
		Depr.	Total
5	20 LU =96.00 EUR	308.20 EUR	50 % 404.20 EUR
[x]	REAR WINDOW STYLE/CENTER/LEFT/UP	SCRATCH WITH PAINT DAMAGE	
		Repair paint - LI	New paint - E
		Depr.	Total
3	0 LU =0.00 EUR	308.20 EUR	50 % 308.20 EUR
[x]	REAR DOOR/LEFT/CORNER/BELOW	DENT	REEDS AANGEG.
		Repair paint - LI	New paint - E
		Depr.	Total
5	10 LU =48.00 EUR	318.35 EUR	50 % 366.35 EUR
[x]	ROOF/FRONT/CENTER/RIGHT	DENT	"HAGELSCHADE"
		Repair paint - LI	New paint - E
		Depr.	Total
6	I 2 i-vab-uitd-03	BEAT OUT DENT (HAIL DAMAGE)	97.80 EUR 195.60 EUR
[x]	FRONT BUMPER/RIGHT/CORNER	SCRATCH WITH PAINT DAMAGE	MEERDERE KRASSEN
		Repair paint - LI	New paint - E
		Depr.	Total
4	0 LU =0.00 EUR	211.80 EUR	50 % 211.80 EUR

Interior

[x] SEAT FL

OTHER DAMAGES

Number	Code	Description	Unit price	Depr.	Total
1	I 2	i-vab-ander-01	REPAIR (PER 15')	18.74 EUR	37.48 EUR

Others

CLEANLINESS EXTERIOR

Number	Code	Description	Unit price	Depr.	Total
2	I 1	mono-jeep-kl.bestelw-a-vab-reex-04	CLEANING EXTERIOR	13.20 EUR	13.20 EUR

1	2	3	4	5	6	7	8	9	10
37.48	13.20	308.20	211.80	982.35	195.60	0	0	0	0
37.48	13.20	154.10	105.90	491.18	195.60	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
246.28	1502.35	0	1748.63
HOG: 0	BG: 0		NA Deprec. 997.46
			0.00%
			TOTAL 997.46

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

UNDER CONDITION - VEHICLE VERY DIRTY

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark : NAVI OK [x]		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 25/07/2017 Hour : 09:27 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	