

C1HV38

EFFECTIVE     NOT EXECUTED     COLLECTION     DELIVERY

[x] = Status Modification

<b>Commissionar :</b>	KBC REMARKETING	<b>Cleanliness :</b>	INT: CLEAN [x] EXT: CLEAN [x]
<b>Owner :</b>		<b>Mileage :</b>	112141 KM
<b>File nr. :</b>	1422074	<b>Mileage start / arrival:</b>	0 / 0
<b>Reg number / Chassis / Ref :</b>		<b>Mileag ref. service :</b>	0
CC6892 / 3C4PFACY6ET314265 /		<b>yr of constructionr :</b>	/
<b>E-File nr. :</b>		<b>First registration :</b>	26/02/2015
<b>VFS-nr. :</b>		<b>Color :</b>	BLACK
<b>Make + Model :</b>	FIAT / FREEMONT	<b>Fuel type :</b>	DIESEL
<b>Object nr. :</b>	ONBEKEND	<b>Fuel :</b>	
<b>Classification :</b>		<b>Environment Class:</b>	
<b>Customer company :</b>	ONBEKEND	<b>Co2:</b>	g/km
<b>Driver :</b>		<b>Remote controls:</b>	2
<b>Covering :</b>	LEATHER	<b>Number keys :</b>	3 [x]
<b>Vehicle kind :</b>	VEHICLE	<b>Seats (minivan) :</b>	7 [x]
<b>Vehicle type :</b>		<b>Country registration :</b>	LUXEMBOURG

<b>VAT over the margin - car:</b>		<b>Metallic paint:</b>	Yes
<b>Variant car:</b>	MONOVOLUME	<b>Engine size:</b>	1956
<b>Gear box :</b>	Manueel	<b>Number of places:</b>	7
<b>Number of gears:</b>	6	<b>Number of doors:</b>	5
<b>HP:</b>	136	<b>kW:</b>	100
<b>Fisc HP</b>		<b>Imported vehicle:</b>	
<b>Animals transported:</b>		<b>Smoked in vehicle:</b>	
<b>Due date vehicle inspection:</b>		<b>Extra set of tires:</b>	
		<b>Use:</b>	Unknown
<b>General condition:</b>			

Original registr. number :		Service manual :	
Cert. of reg. / Part 1:		Cert. of conformity :	
Cert. of reg. copy / Part 2:		Insurance certificate :	
Warning vest :	OK [x]	Transport licence :	
Tax certificate :		Navigation CD/SD/DVD	
Fuel card :		Car radio :	
Mobile phone kit :		Extinguisher :	OK [x]
		Warning triangle :	OK [x]
First aid kit :	OK [x]	Oil level :	OK [x]
Jack, wheelspanner :	OK [x]	Filled up :	0

## Wheels and tyres: Summer tires

Wheel FL:	[x]	PIRELLI	Tyre :	OK [x]	2-4/	Rim :	/	Hubcap :	
Wheel RL :	[x]	PIRELLI	Tyre :	OK [x]	2-4/	Rim :	/	Hubcap :	
Wheel FR :	[x]	PIRELLI	Tyre :	[x] OK [x]	2-4/	Rim :	/	Hubcap :	
Wheel RR :	[x]	PIRELLI	Tyre :	OK [x]	2-4/	Rim :	/	Hubcap :	
Wheel RES:	[x]		Tyre :	OK [x]	>6/	Rim :	/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	225	55	R	19	V
Rear tyre	225	55	R	19	V

Remark :

## Wheels and tyres:

Wheel FL:			Tyre :	OK /	Rim :	/	Hubcap :	
Wheel RL :			Tyre :	OK /	Rim :	/	Hubcap :	
Wheel FR :			Tyre :	OK /	Rim :	/	Hubcap :	
Wheel RR :			Tyre :	OK /	Rim :	/	Hubcap :	
Wheel RES:			Tyre :	OK /	Rim :	/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

## STATUS: ACCEPTABLE / USAGE DAMAGE

### Bodywork \& windows

[x]	REAR DOOR/LEFT/CORNER/BELOW	SCRATCH WITH PAINT DAMAGE
[x]	REAR DOOR/LEFT/FRONT	DENT
[x]	ROOF/CENTER/LEFT	DENT
[x]	REAR DOOR/RIGHT/FRONT	DENT
[x]	FRONT DOOR/LEFT/REAR	SCRATCH WITH PAINT DAMAGE
[x]	FRONT DOOR/LEFT/CENTER	DENT
[x]	BONNET/CENTER/RIGHT/FRONT	CHIPS
[x]	FRONT BUMPER/CENTER/LEFT	CHIPS

### Accessories and others

[x]	OUTSIDE MIRROR RIGHTHAND SIDE	SCRATCH WITH PAINT DAMAGE
-----	-------------------------------	---------------------------

## STATUS: NOT ACCEPTABLE

### Bodywork \& windows

[x]	REAR BUMPER/CENTER/LEFT	SCRATCH WITH PAINT DAMAGE					
		<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>		
3	0 LU =0.00 EUR	211.80 EUR		50 %	211.80 EUR		
[x]	WINDSCREEN/CENTER/LEFT	WINDOW DAMAGE					
		<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>		
2	25 LU =120.00 EUR	0 EUR		50 %	120.00 EUR		
[x]	FRONT DOOR/RIGHT/REAR	SCRATCH WITH PAINT DAMAGE					
		<b>Number</b>	<b>Code</b>	<b>Description</b>	<b>Unit price</b>	<b>Depr.</b>	<b>Total</b>
4	I 1	i-vab-sp-01		SPOTREPAIR	115.56 EUR		115.56 EUR
[x]	FRONT MUDGUARD/RIGHT/CENTER	SCRATCH WITH PAINT DAMAGE					
		<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>		
5	0 LU =0.00 EUR	220.18 EUR		50 %	220.18 EUR		

## Interior

[x]	CENTER CONSOLE	MISSING/INCOMPLETE			
		<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>
1	0 LU =0.00 EUR	0 EUR		50 %	

## Accessories and others

[x]	OUTSIDE MIRROR LEFTHAND SIDE	BROKEN / CRACKED			
		<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>
6	5 LU =24.00 EUR	0 EUR		50 %	24.00 EUR

## Pieces

Number	Code	Description	Unit price	Depr.	Total
2	1	WIND SCREEN	367.20 EUR	50 %	367.20 EUR
6	1	MIRROR	120.00 EUR	50 %	120.00 EUR
1	1	VERSNELINGSPOOK	75.00 EUR	50 %	75.00 EUR

1	2	3	4	5	6	7	8	9	10
75.00	487.20	211.80	115.56	220.18	144.00	0	0	0	0
37.50	243.60	105.90	115.56	110.09	72.00	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
115.56	1138.18	0	<b>1253.74</b>
HOG: 0	BG: 0		NA Deprec. 684.65
			0.00%
			<b>TOTAL 684.65</b>

[x] = Status Modification

Pictures : No

## CIRCUMSTANCES

NORMAL CONCLUSION

<b>Extra Time :</b> 0 min	<b>Waiting time :</b> 0 min <b>Reason :</b>	<b>Towing time :</b> 0 min <b>Reason :</b>
<b>NOT EXECUTED :</b> No		
<b>Reason :</b>		
<b>Remark :</b>		

## Prices in EUR without VAT

<b>Authorized by customer :</b>  <b>Remark authorized customer :</b>  <b>Date :</b> 24/07/2017 <b>Hour :</b> 10:57 <b>Company :</b> Executed by VAB Fleet Services <b>E-Mail :</b> @	Executed by VAB Fleet Services
Signature authorized by customer 	