

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: DIRTY [x] EXT: DIRTY [x]
Owner :		Mileage :	137609 KM
File nr. :	1421097	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1FDE055 / WF0SXXGBWSDB31766 /		yr of constructionr :	/
E-File nr. :		First registration :	29/05/2013
VFS-nr. :		Color :	BEIGE
Make + Model :	FORD / S-MAX	Fuel type :	DIESEL
Object nr. :	54434	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	Vesuvius Group sa	Co2:	139g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	7 [x]
Vehicle type :	S-MAX Econetic Trend St&St DPF 115PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:	MONOVOLUME	Engine size:	1560
Gear box :	Manueel	Number of places:	7
Number of gears:	6	Number of doors:	5
HP:	116	kW:	85
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	
Due date vehicle inspection:		Extra set of tires:	
		Use:	Unknown

General condition:

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:		Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :	
Warning vest :	OK	[x]	Transport licence :	
Tax certificate :			Navigation CD/SD/DVD	
Fuel card :			Car radio :	
Mobile phone kit :			Extinguisher :	OK [x]
First aid kit :	OK	[x]	Warning triangle :	OK [x]
Jack, wheelspanner :			Oil level :	OK [x]
			Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	[x]	UNIROYAL	Tyre :	OK	[x]	4-6/	Rim :	/	Hubcap :
Wheel RL :	[x]	UNIROYAL	Tyre :	OK	[x]	4-6/	Rim :	/	Hubcap :
Wheel FR :	[x]	UNIROYAL	Tyre :	[x]	OK	[x]	4-6/	Rim :	[x] WHEEL SCRATCHED / Hubcap :
Wheel RR :	[x]	UNIROYAL	Tyre :	OK	[x]	4-6/	Rim :	/	Hubcap :
Wheel RES:	[x]		Tyre :	OK	/		Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	215	60	R	16	H
Rear tyre	215	60	R	16	H

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR MUDGUARD/RIGHT/CENTER	DENT		
[x]	REAR DOOR/LEFT/CENTER	DENT	X2	
[x]	REAR DOOR/RIGHT/FRONT	SCRATCH (WITHOUT PAINT DAMAGE)		
[x]	FRONT DOOR/LEFT/REAR	SCRATCH WITH PAINT DAMAGE		
[x]	FRONT BUMPER/CENTER/RIGHT	WINDOW DAMAGE		

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR BUMPER/CENTER/RIGHT	HOLE/CRACK/TORN				
		Repair paint - LI	New paint - E	Depr.	Total	
3	15 LU =72.00 EUR	0 EUR		50 %	72.00 EUR	
[x]	WINDSCREEN/CENTER/RIGHT	WINDOW DAMAGE				
	Number	Code	Description	Unit price	Depr.	Total
2	11	i-vab-herstr-01	WINDOW REPAIR	58.80 EUR		58.80 EUR
[x]	FRONT MUDGUARD/LEFT/REAR	DENT				
		Repair paint - LI	New paint - E	Depr.	Total	
4	15 LU =72.00 EUR	220.18 EUR		50 %	292.18 EUR	
[x]	BONNET/CENTER/RIGHT/FRONT	HOLE/CRACK/TORN				
		Repair paint - LI	New paint - E	Depr.	Total	
6	5 LU =24.00 EUR	0 EUR		50 %	24.00 EUR	

Interior

[x]	BOOT LID IN	CARVED			
		Repair paint - LI	New paint - E	Depr.	Total
1	5 LU =24.00 EUR	0 EUR		50 %	24.00 EUR

Others

CLEANLINESS INTERIOR

	Number	Code	Description	Unit price	Depr.	Total
1	I 5	personenwagen-a-vab-rein-02	CLEANING INTERIOR	11.47 EUR		57.35 EUR

RIM FRONT RIGHT

Number	Code	Description	Unit price	Depr.	Total
5	I 1	i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR	95.00 EUR

Pieces

Number	Code	Description	Unit price	Depr.	Total
1	1	BEKLEDDING KOFFER	90.00 EUR	50 %	90.00 EUR

Number	Code	Description	Unit price	Depr.	Total
3	1	REAR BUMPER	343.20 EUR	50 %	343.20 EUR

Number	Code	Description	Unit price	Depr.	Total
6	1	BEKLEDING MOTORKAP	50.00 EUR	50 %	50.00 EUR

1	2	3	4	5	6	7	8	9	10
171.35	58.80	415.20	292.18	95.00	74.00	0	0	0	0
114.35	58.80	207.60	146.09	95.00	37.00	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
211.15	895.38	0	1106.53
HOG: 0	BG: 0		NA Deprec. 658.84
			0.00%
			TOTAL 658.84

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 24/07/2017 Hour : 11:32 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	