

EFFECTIVE     NOT EXECUTED     COLLECTION     DELIVERY

[x] = Status Modification

<b>Commissionar :</b>	KBC REMARKETING	<b>Cleanliness :</b>	INT: CLEAN [x] EXT: CLEAN [x]
<b>Owner :</b>		<b>Mileage :</b>	172133 KM
<b>File nr. :</b>	1421050	<b>Mileage start / arrival:</b>	0 / 0
<b>Reg number / Chassis / Ref :</b>		<b>Mileag ref. service :</b>	0
1DUB198 / WF0SXXGBWSCE43053 /		<b>yr of constructionr :</b>	/
<b>E-File nr. :</b>		<b>First registration :</b>	28/08/2012
<b>VFS-nr. :</b>		<b>Color :</b>	BLACK
<b>Make + Model :</b>	FORD / S-MAX	<b>Fuel type :</b>	DIESEL
<b>Object nr. :</b>		<b>Fuel :</b>	
<b>Classification :</b>		<b>Environment Class:</b>	EURO 5
<b>Customer company :</b>	ACERTA SOC. SECRETARIAAT VZW	<b>Co2:</b>	139g/km
<b>Driver :</b>		<b>Remote controls:</b>	1
<b>Covering :</b>	LEATHER	<b>Number keys :</b>	1 [x]
<b>Vehicle kind :</b>		<b>Seats (minivan) :</b>	0
<b>Vehicle type :</b>	S-MAX Econetic Titanium St&St DPF 115PK	<b>Country registration :</b>	BELGIUM

<b>VAT over the margin - car:</b>	No	<b>Metallic paint:</b>	Yes
<b>Variant car:</b>		<b>Engine size:</b>	1560
<b>Gear box :</b>	Manueel	<b>Number of places:</b>	5
<b>Number of gears:</b>	6	<b>Number of doors:</b>	5
<b>HP:</b>	116	<b>kW:</b>	85
<b>Fisc HP</b>		<b>Imported vehicle:</b>	No
<b>Animals transported:</b>	No	<b>Smoked in vehicle:</b>	No
<b>Due date vehicle inspection:</b>		<b>Extra set of tires:</b>	No
		<b>Use:</b>	Unknown

**General condition:**

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:		Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :	
Warning vest :	OK	[x]	Transport licence :	
Tax certificate :			Navigation CD/SD/DVD	
Fuel card :			Car radio :	OK [x]
Mobile phone kit :			Extinguisher :	OK [x]
First aid kit :	OK	[x]	Warning triangle :	OK [x]
Jack, wheelspanner :			Oil level :	
			Filled up :	0

## Wheels and tyres: Summer tires

Wheel FL:	[x]	MICHELIN	Tyre :	OK	[x]	2-4/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :	
Wheel RL :	[x]	MICHELIN	Tyre :	OK	[x]	2-4/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :	
Wheel FR :	[x]	MICHELIN	Tyre :	[x]	OK	[x]	2-4/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :
Wheel RR :	[x]	MICHELIN	Tyre :	OK	[x]	2-4/	Rim :			/	Hubcap :	
Wheel RES:	[x]	ANDERE	Tyre :	OK		/	Rim :			/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	235	45	R	18	W
Rear tyre	235	45	R	18	W

Remark :

## Wheels and tyres:

Wheel FL:			Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RL :			Tyre :	OK	/	Rim :		/	Hubcap :
Wheel FR :			Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RR :			Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RES:			Tyre :	OK	/	Rim :		/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

## STATUS: ACCEPTABLE / USAGE DAMAGE

### Bodywork \& windows

[x]	REAR MUDGUARD/LEFT/REAR	DENT	
[x]	REAR MUDGUARD/LEFT/CENTER	DENT	
[x]	REAR MUDGUARD/LEFT/FRONT	SCRATCH WITH PAINT DAMAGE	
[x]	REAR DOOR/LEFT/REAR	DENT	
[x]	REAR THRESHOLD/LEFT/REAR	SCRATCH WITH PAINT DAMAGE	
[x]	REAR DOOR/RIGHT/FRONT	DENT	
[x]	FRONT DOOR/LEFT/REAR	SCRATCH WITH PAINT DAMAGE	RAND
[x]	FRONT DOOR/RIGHT/REAR	SCRATCH (WITHOUT PAINT DAMAGE)	
[x]	FRONT BUMPER/RIGHT/SIDE	SCRATCH (WITHOUT PAINT DAMAGE)	
[x]	ROOF/CENTER/LEFT	SCRATCH (WITHOUT PAINT DAMAGE)	

## STATUS: NOT ACCEPTABLE

### Bodywork \& windows

[x]	REAR BUMPER/CENTER/LEFT	SCRATCH WITH PAINT DAMAGE	AANGIFTE OK	
		<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>
				<b>Total</b>
2	10 LU =48.00 EUR	0 EUR		50 %
				48.00 EUR
[x]	REAR DOOR/RIGHT/RIGHT	DENT	AANGIFTE OK	
		<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>
				<b>Total</b>
3	0 LU =0.00 EUR	301.68 EUR		50 %
				301.68 EUR
[x]	REAR BUMPER/SIDE/RIGHT/CENTER	SCRATCH WITH PAINT DAMAGE	AANGIFTE OK	
		<b>Number</b>	<b>Code</b>	<b>Description</b>
				<b>Unit price</b>
				<b>Depr.</b>
				<b>Total</b>
2	I 1	i-vab-sp-01	SPOTREPAIR	115.56 EUR
				115.56 EUR
[x]	REAR DOOR/LEFT/CENTER	DENT		
		<b>Number</b>	<b>Code</b>	<b>Description</b>
				<b>Unit price</b>
				<b>Depr.</b>
				<b>Total</b>
1	I 1	i-vab-uitd-01	BEAT OUT DENT	63.00 EUR
				63.00 EUR

[x]	BONNET/CENTER/LEFT	OTHER DAMAGES	ISOLATIE MK	
	Repair paint - LI	New paint - E	Depr.	Total
4	5 LU =24.00 EUR	0 EUR	50 %	24.00 EUR

### Pieces

Number	Code	Description	Unit price	Depr.	Total
4	1	ISOLATIE	25.00 EUR	50 %	25.00 EUR
Number	Code	Description	Unit price	Depr.	Total
2	1	BUMPERSPOILER	150.00 EUR	50 %	150.00 EUR

1	2	3	4	5	6	7	8	9	10
63.00	313.56	301.68	49.00	0	0	0	0	0	0
63.00	214.56	150.84	24.50	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
178.56	548.68	0	<b>727.24</b>
HOG: 0	BG: 0		NA Deprec. 452.90
			0.00%
			<b>TOTAL 452.90</b>

[x] = Status Modification

Pictures : No

## CIRCUMSTANCES

UNDER CONDITION - VEHICLE WET

<b>Extra Time :</b> 0 min	<b>Waiting time :</b> 0 min <b>Reason :</b>	<b>Towing time :</b> 0 min <b>Reason :</b>
<b>NOT EXECUTED :</b> No		
<b>Reason :</b>		
<b>Remark :</b>		

## Prices in EUR without VAT

<p><b>Authorized by customer :</b> I KNOW THE STATE OF THE VEHICLE AND I AGREE WITH THE REPORT AND ITS ATTACHMENTS;</p> <p><b>Remark authorized customer :</b> TWEEDE SLEUTEL VIA FLEET</p> <p><b>Date :</b> 20/07/2017      <b>Hour :</b> 11:57</p> <p><b>Company :</b></p> <p><b>Executed by VAB Fleet Services</b></p> <p><b>E-Mail :</b> @</p>	<p>Executed by VAB Fleet Services</p>
<p>Signature authorized by customer</p> 	