

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	125589 KM
File nr. :	1421757	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1DPO244 / WDF63960513755732 /		yr of constructionr :	/
E-File nr. :		First registration :	16/07/2012
VFS-nr. :		Color :	GREY
Make + Model :	MERCEDES / VITO	Fuel type :	DIESEL
Object nr. :	39675	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	LMB RACING BVBA	Co2:	219g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	TRUCK, LORRY	Seats (minivan) :	0
Vehicle type :	VITO 116 B/F2C LWB A3 Mixto 163PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:	BESTELWAGEN	Engine size:	2143
Gear box :	Automaat algemeen	Number of places:	5
Number of gears:		Number of doors:	5
HP:	163	kW:	120
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:			

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:		Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :	
Warning vest :	OK	[x]	Transport licence :	
Tax certificate :			Navigation CD/SD/DVD	
Fuel card :			Car radio :	OK [x]
Mobile phone kit :			Extinguisher :	OK [x]
First aid kit :	OK	[x]	Warning triangle :	OK [x]
Jack, wheelspanner :	OK	[x]	Oil level :	OK [x]
			Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	[x]	GOODYEAR	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :	
Wheel RL :	[x]	GOODYEAR	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :	
Wheel FR :	[x]	GOODYEAR	Tyre :	[x]	OK	[x]	2-4/	Rim :	/	Hubcap :
Wheel RR :	[x]	GOODYEAR	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :	
Wheel RES:	[x]		Tyre :	OK		/	Rim :	/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	205	65	R	16	T
Rear tyre	205	65	R	16	T

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x] REAR BUMPER/CENTER/RIGHT DENT

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x] REAR MUDGUARD/LEFT/REAR OTHER DAMAGES

	Repair paint - LI	New paint - E	Depr.	Total
2 5 LU =24.00 EUR	0 EUR		50 %	24.00 EUR

[x] FRONT BUMPER/RIGHT DENT

	Repair paint - LI	New paint - E	Depr.	Total
1 15 LU =72.00 EUR	0 EUR		50 %	72.00 EUR

Pieces

Number	Code	Description	Unit price	Depr.	Total
1	1	FRONT BUMPER	302.40 EUR	50 %	302.40 EUR
Number	Code	Description	Unit price	Depr.	Total
2	1	MAGNEET	40.00 EUR	50 %	40.00 EUR

1	2	3	4	5	6	7	8	9	10
374.40	64.00	0	0	0	0	0	0	0	0
187.20	32.00	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
0	438.40	0	438.40
HOG: 0	BG: 3		NA Deprec. 219.20
			0.00%
			TOTAL 219.20

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 25/07/2017 Hour : 11:09 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	