

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	156184 KM
File nr. :	1422773	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1DPF624 / W0LPE9EL6C2116477 /		yr of constructionr :	/
E-File nr. :		First registration :	12/07/2012
VFS-nr. :		Color :	BLACK
Make + Model :	OPEL / ZAFIRA TOURER	Fuel type :	DIESEL
Object nr. :	52579	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	DOLCE LA HULPE SA	Co2:	137g/km
Driver :		Remote controls:	1
Covering :	TISSUE-LEATHER	Number keys :	1 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	ZAFIRA TOURER Cosmo 110PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:		Engine size:	1956
Gear box :	Manueel	Number of places:	5
Number of gears:	6	Number of doors:	5
HP:	110	kW:	81
Fisc HP		Imported vehicle:	No
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown

General condition:

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:		Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :	
Warning vest :	OK	[x]	Transport licence :	
Tax certificate :			Navigation CD/SD/DVD	
Fuel card :			Car radio :	OK [x]
Mobile phone kit :			Extinguisher :	OK [x]
First aid kit :	OK	[x]	Warning triangle :	OK [x]
Jack, wheelspanner :			Oil level :	OK [x]
			Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	[x]	MICHELIN	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :
Wheel RL :	[x]	CONTINENTAL	Tyre :	OK	[x]	4-6/	Rim :	/	Hubcap :
Wheel FR :	[x]	MICHELIN	Tyre :	[x]	OK	[x]	2-4/	Rim :	[x] WHEEL SCRATCHED / Hubcap :
Wheel RR :	[x]	CONTINENTAL	Tyre :	OK	[x]	4-6/	Rim :	/	Hubcap :
Wheel RES:	[x]		Tyre :	OK	/		Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	225	50	R	17	W
Rear tyre	225	50	R	17	W

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: NOT ACCEPTABLE

Bodywork \& windows

		Repair paint - LI	New paint - E	Depr.	Total
[x]	REAR BUMPER/CENTER/LEFT		SCRATCH WITH PAINT DAMAGE		
2	0 LU =0.00 EUR	211.80 EUR		50 %	211.80 EUR
[x]	REAR DOOR/RIGHT/FRONT		SCRATCH WITH PAINT DAMAGE		
3	0 LU =0.00 EUR	318.35 EUR		50 %	318.35 EUR
[x]	FRONT DOOR/LEFT/FRONT		DENT		
1	0 LU =0.00 EUR	0 EUR		50 %	
1	30 LU =144.00 EUR	0 EUR	435.72 EUR	50 %	579.72 EUR
[x]	FRONT DOOR/RIGHT/REAR		SCRATCH WITH PAINT DAMAGE		
3	0 LU =0.00 EUR	318.35 EUR		50 %	318.35 EUR
[x]	FRONT THRESHOLD/RIGHT/REAR		SCRATCH WITH PAINT DAMAGE		
3	0 LU =0.00 EUR	310.50 EUR		50 %	310.50 EUR

Others

RIM FRONT RIGHT

Number	Code	Description	Unit price	Depr.	Total
4	I 1 i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

Pieces

Number	Code	Description	Unit price	Depr.	Total
1	1 DOOR FL		502.80 EUR	50 %	502.80 EUR

1	2	3	4	5	6	7	8	9	10
1082.52	211.80	947.20	95.00	0	0	0	0	0	0
541.26	105.90	473.60	95.00	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
95.00	2241.52	0	2336.52
HOG: 0	BG: 0		NA Deprec. 1215.76
			0.00%
			TOTAL 1215.76

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 26/07/2017 Hour : 13:37 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	