

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: DIRTY [x] EXT: CLEAN [x]
Owner :		Mileage :	149900 KM
File nr. :	1423323	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1EKK690 / W0LPD6EA4D1047022 /		yr of constructionr :	/
E-File nr. :		First registration :	07/01/2013
VFS-nr. :		Color :	GREY
Make + Model :	OPEL / ASTRA	Fuel type :	DIESEL
Object nr. :	46543	Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	ALTRAN SA	Co2:	104g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :	ASTRA BER ecoFLEX Enjoy S&S 95PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:		Engine size:	1248
Gear box :	Onbekend	Number of places:	5
Number of gears:	5	Number of doors:	5
HP:	95	kW:	70
Fisc HP		Imported vehicle:	No
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown

General condition:

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:		Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :	
Warning vest :	OK	[x]	Transport licence :	
Tax certificate :			Navigation CD/SD/DVD	
Fuel card :			Car radio :	OK [x]
Mobile phone kit :			Extinguisher :	OK [x]
First aid kit :	OK	[x]	Warning triangle :	OK [x]
Jack, wheelspanner :			Oil level :	OK [x]
			Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	[x]	CONTINENTAL	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :	
Wheel RL :	[x]	CONTINENTAL	Tyre :	OK	[x]	>6/	Rim :	/	Hubcap :	
Wheel FR :	[x]	CONTINENTAL	Tyre :	[x]	OK	[x]	2-4/	Rim :	/	Hubcap :
Wheel RR :	[x]	CONTINENTAL	Tyre :	OK	[x]	>6/	Rim :	/	Hubcap :	
Wheel RES:	[x]		Tyre :	OK		/	Rim :	/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	215	60	R	16	V
Rear tyre	215	60	R	16	V

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]			Repair paint - LI	New paint - E	Depr.	Total
	REAR BUMPER/RIGHT/RIGHT	SCRATCH WITH PAINT DAMAGE				
2	0 LU =0.00 EUR		211.80 EUR		50 %	211.80 EUR
[x]	REAR DOOR/RIGHT/RIGHT	SCRATCH WITH PAINT DAMAGE				
1	0 LU =0.00 EUR		301.68 EUR		50 %	301.68 EUR
[x]	FRONT DOOR/RIGHT/CENTER	SCRATCH WITH PAINT DAMAGE				
3	0 LU =0.00 EUR		318.35 EUR		50 %	318.35 EUR

Interior

[x]			Repair paint - LI	New paint - E	Depr.	Total
	BACK SHELF	OTHER DAMAGES				
4	0 LU =0.00 EUR		0 EUR		50 %	

Others

CLEANLINESS INTERIOR

Number	Code	Description	Unit price	Depr.	Total
5	I 2	specifiek-per-kwartier-a-vab-rein-03 CLEANING INTERIOR	14.58 EUR		29.16 EUR

Pieces

Number	Code	Description	Unit price	Depr.	Total
4	1	OPHANGKOORD	5.00 EUR	50 %	5.00 EUR

1	2	3	4	5	6	7	8	9	10
301.68	211.80	318.35	5.00	29.16	0	0	0	0	0
150.84	105.90	159.18	2.50	29.16	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
29.16	836.83	0	865.99
HOG: 0	BG: 0		NA Deprec. 447.58
			0.00%
			TOTAL 447.58

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 26/07/2017 Hour : 12:50 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	