

EFFECTIVE     NOT EXECUTED                       COLLECTION                       DELIVERY

[x] = Status Modification

<b>Commissionar :</b>	KBC REMARKETING	<b>Cleanliness :</b>	INT: DIRTY [x] EXT: CLEAN [x]
<b>Owner :</b>		<b>Mileage :</b>	54842 KM
<b>File nr. :</b>	1421318	<b>Mileage start / arrival:</b>	0 / 0
<b>Reg number / Chassis / Ref :</b>		<b>Mileag ref. service :</b>	0
1BEE702 / WF05XXTTF5BD68483 /		<b>yr of constructionr :</b>	/
<b>E-File nr. :</b>		<b>First registration :</b>	11/05/2011
<b>VFS-nr. :</b>		<b>Color :</b>	
<b>Make + Model :</b>	FORD / TRANSIT	<b>Fuel type :</b>	DIESEL
<b>Object nr. :</b>	46115	<b>Fuel :</b>	
<b>Classification :</b>		<b>Environment Class:</b>	EURO 4
<b>Customer company :</b>	GEMEENTE ETTERBEEK	<b>Co2:</b>	222g/km
<b>Driver :</b>		<b>Remote controls:</b>	1
<b>Covering :</b>	IMITATION LEATHER	<b>Number keys :</b>	2 [x]
<b>Vehicle kind :</b>	TRUCK, LORRY	<b>Seats (minivan) :</b>	0
<b>Vehicle type :</b>	TRANSIT 280M B/F2C MWB Ambiente DPF 85PK	<b>Country registration :</b>	BELGIUM

<b>VAT over the margin - car:</b>	No	<b>Metallic paint:</b>	Yes
<b>Variant car:</b>	BESTELWAGEN	<b>Engine size:</b>	2198
<b>Gear box :</b>	Manueel	<b>Number of places:</b>	6
<b>Number of gears:</b>	5	<b>Number of doors:</b>	5
<b>HP:</b>	86	<b>kW:</b>	63
<b>Fisc HP</b>		<b>Imported vehicle:</b>	No
<b>Animals transported:</b>	No	<b>Smoked in vehicle:</b>	No
<b>Due date vehicle inspection:</b>		<b>Extra set of tires:</b>	No
		<b>Use:</b>	Unknown

**General condition:**

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:		Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :	
Warning vest :	OK	[x]	Transport licence :	
Tax certificate :			Navigation CD/SD/DVD	
Fuel card :			Car radio :	OK [x]
Mobile phone kit :			Extinguisher :	OK [x]
First aid kit :	OK	[x]	Warning triangle :	OK [x]
Jack, wheelspanner :			Oil level :	OK [x]
			Filled up :	0

## Wheels and tyres: Summer tires

Wheel FL:	[x]	PIRELLI	Tyre :	OK	[x]	>6/	Rim :	/	Hubcap :		
Wheel RL :	[x]	CONTINENTAL	Tyre :	OK	[x]	>6/	Rim :	/	Hubcap :		
Wheel FR :	[x]	PIRELLI	Tyre :	[x]	OK	[x]	>6/	Rim :	/	Hubcap :	[x] MISSING/INCOMPLETE
Wheel RR :	[x]	CONTINENTAL	Tyre :	OK	[x]	>6/	Rim :	/	Hubcap :		
Wheel RES:	[x]		Tyre :	OK		/	Rim :	/	Hubcap :		

[x]	Width	Height	Type	Rim	Index
Front tyre	195	70	R	15	
Rear tyre	195	70	R	15	

Remark :

## Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

## STATUS: NOT ACCEPTABLE

### Bodywork \& windows

[x]	REAR BUMPER /LEFT/CORNER		SCRATCH WITH PAINT DAMAGE			
	<b>Number</b>	<b>Code</b>	<b>Description</b>	<b>Unit price</b>	<b>Depr.</b>	<b>Total</b>
8	I 1	i-vab-kunst-01	PLASTICS REPAIR	110.64 EUR		110.64 EUR
[x]	REAR DOOR/RIGHT/RIGHT		SCRATCH WITH PAINT DAMAGE			
			<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>
9	0 LU =0.00 EUR		226.26 EUR		50 %	226.26 EUR
[x]	REAR BUMPER/RIGHT/CORNER		SCRATCH WITH PAINT DAMAGE			
	<b>Number</b>	<b>Code</b>	<b>Description</b>	<b>Unit price</b>	<b>Depr.</b>	<b>Total</b>
0	0					
[x]	REAR MUDGUARD/LEFT/REAR		DENT			
			<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>
7	0 LU =0.00 EUR		231.15 EUR		50 %	231.15 EUR
[x]	REAR MUDGUARD/RIGHT/REAR		SCRATCH WITH PAINT DAMAGE		+DEUK	
			<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>
10	0 LU =0.00 EUR		231.15 EUR		50 %	231.15 EUR
[x]	REAR DOOR/LEFT/CENTER		SCRATCH WITH PAINT DAMAGE			
			<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>
6	0 LU =0.00 EUR		238.76 EUR		50 %	238.76 EUR
[x]	REAR DOOR/RIGHT/CENTER		SCRATCH WITH PAINT DAMAGE		+DEUK	
			<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>
10	0 LU =0.00 EUR		238.76 EUR		50 %	238.76 EUR
[x]	FRONT DOOR/LEFT/REAR		SCRATCH WITH PAINT DAMAGE			
			<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>
5	0 LU =0.00 EUR		238.76 EUR		50 %	238.76 EUR
[x]	FRONT THRESHOLD/LEFT/FRONT		SCRATCH WITH PAINT DAMAGE			
			<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>
5	0 LU =0.00 EUR		232.88 EUR		50 %	232.88 EUR

[x]	FRONT DOOR/RIGHT/CENTER		SCRATCH WITH PAINT DAMAGE	+DEUK		
		<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>	
10	0 LU =0.00 EUR	238.76 EUR		50 %	238.76 EUR	
[x]	FRONT MUDGUARD/LEFT/FRONT		DENT			
		<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>	
4	0 LU =0.00 EUR	165.13 EUR		50 %	165.13 EUR	
[x]	FRONT MUDGUARD/RIGHT/FRONT		SCRATCH WITH PAINT DAMAGE			
		<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>	
3	0 LU =0.00 EUR	165.13 EUR		50 %	165.13 EUR	
[x]	FRONT BUMPER/LEFT/CORNER		SCRATCH WITH PAINT DAMAGE			
	<b>Number Code</b>	<b>Description</b>	<b>Unit price</b>	<b>Depr.</b>	<b>Total</b>	
0	0					
[x]	FRONT BUMPER/RIGHT/SIDE		SCRATCH WITH PAINT DAMAGE			
	<b>Number Code</b>	<b>Description</b>	<b>Unit price</b>	<b>Depr.</b>	<b>Total</b>	
3	I 1 i-vab-kunst-01	PLASTICS REPAIR	110.64 EUR		110.64 EUR	
[x]	REAR DOOR/LEFT/LEFT		SCRATCH WITH PAINT DAMAGE			
		<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>	
9	0 LU =0.00 EUR	226.26 EUR		50 %	226.26 EUR	

## Interior

[x]	BOOT LID IN		OTHER DAMAGES			
		<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>	
10	0 LU =0.00 EUR	0 EUR		50 %		
		<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>	
10	10 LU =48.00 EUR	0 EUR		50 %	48.00 EUR	

## Accessories and others

[x]	OUTSIDE MIRROR RIGHTHAND SIDE		SCRATCH WITH PAINT DAMAGE			
		<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>	
10	0 LU =0.00 EUR	0 EUR		50 %		
		<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>	
10	5 LU =24.00 EUR	0 EUR		50 %	24.00 EUR	

## Others

### CLEANLINESS INTERIOR

Number	Code	Description	Unit price	Depr.	Total
1	I 6	bestelwagen-cabine-a-vab-rein-05	CLEANING INTERIOR	11.47 EUR	68.82 EUR
Number	Code	Description	Unit price	Depr.	Total
1	I 3	bestelwagen-laadruimte-a-vab-rein-06	CLEANING INTERIOR	23.41 EUR	70.23 EUR

### HUB CAP FR

	Repair paint - LI	New paint - E	Depr.	Total
2	0 LU =0.00 EUR		50 %	

## Pieces

Number	Code	Description	Unit price	Depr.	Total
2	1	WHEEL CAP	22.50 EUR	50 %	22.50 EUR
Number	Code	Description	Unit price	Depr.	Total
10	1	MIRROR COVER	90.00 EUR	50 %	90.00 EUR
Number	Code	Description	Unit price	Depr.	Total
10	1	AFFDEKPLAAT	30.00 EUR	50 %	30.00 EUR

1	2	3	4	5	6	7	8	9	10
139.05	22.50	275.77	165.13	471.64	238.76	231.15	110.64	452.52	900.67
139.05	11.25	193.20	82.56	235.82	119.38	115.58	110.64	226.26	450.34

INNOVATIVE	TRADITIONAL	GENERAL	
360.33	2647.50	0	<b>3007.83</b>
HOG: 0	BG: 3		NA Deprec. 1684.08
			0.00%
			<b>TOTAL 1684.08</b>

[x] = Status Modification

Pictures : No

## CIRCUMSTANCES

NORMAL CONCLUSION

<b>Extra Time :</b> 0 min	<b>Waiting time :</b> 0 min <b>Reason :</b>	<b>Towing time :</b> 0 min <b>Reason :</b>
<b>NOT EXECUTED :</b> No		
<b>Reason :</b>		
<b>Remark :</b>		

## Prices in EUR without VAT

<b>Authorized by customer :</b>  <b>Remark authorized customer :</b>  <b>Date :</b> 25/07/2017 <b>Hour :</b> 13:41 <b>Company :</b> Executed by VAB Fleet Services <b>E-Mail :</b> @	Executed by VAB Fleet Services
Signature authorized by customer  	