

EFFECTIVE     NOT EXECUTED                       COLLECTION                       DELIVERY

[x] = Status Modification

<b>Commissionar :</b>	KBC REMARKETING	<b>Cleanliness :</b>	INT: DIRTY [x] EXT: CLEAN [x]
<b>Owner :</b>		<b>Mileage :</b>	194485 KM
<b>File nr. :</b>	1421791	<b>Mileage start / arrival:</b>	0 / 0
<b>Reg number / Chassis / Ref :</b>		<b>Mileag ref. service :</b>	0
1HJV562 / WOLF7W1A2EV641010 /		<b>yr of constructionr :</b>	/
<b>E-File nr. :</b>		<b>First registration :</b>	05/08/2014
<b>VFS-nr. :</b>		<b>Color :</b>	GREY
<b>Make + Model :</b>	OPEL / VIVARO	<b>Fuel type :</b>	DIESEL
<b>Object nr. :</b>	60547	<b>Fuel :</b>	
<b>Classification :</b>		<b>Environment Class:</b>	EURO 5
<b>Customer company :</b>	Novellini Diffusion Benelux bv	<b>Co2:</b>	204g/km
<b>Driver :</b>		<b>Remote controls:</b>	2
<b>Covering :</b>	TISSUE	<b>Number keys :</b>	2 [x]
<b>Vehicle kind :</b>	TRUCK, LORRY	<b>Seats (minivan) :</b>	0
<b>Vehicle type :</b>		<b>Country registration :</b>	BELGIUM

<b>VAT over the margin - car:</b>		<b>Metallic paint:</b>	Yes
<b>Variant car:</b>	BESTELWAGEN	<b>Engine size:</b>	1995
<b>Gear box :</b>	Manueel	<b>Number of places:</b>	3
<b>Number of gears:</b>	6	<b>Number of doors:</b>	5
<b>HP:</b>	114	<b>kW:</b>	84
<b>Fisc HP</b>		<b>Imported vehicle:</b>	No
<b>Animals transported:</b>	No	<b>Smoked in vehicle:</b>	No
<b>Due date vehicle inspection:</b>		<b>Extra set of tires:</b>	No
		<b>Use:</b>	Unknown
<b>General condition:</b>			

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:	OK	[x]	Cert. of conformity :	OK
Cert. of reg. copy / Part 2:		Insurance certificate :		
Warning vest :	OK	[x]	Transport licence :	
Tax certificate :		Navigation CD/SD/DVD		
Fuel card :		Car radio :	OK	[x]
Mobile phone kit :		Extinguisher :	OK	[x]
First aid kit :	OK	[x]	Warning triangle :	OK
Jack, wheelspanner :		Oil level :	OK	[x]
		Filled up :	0	

## Wheels and tyres: Summer tires

Wheel FL:	[x]	UNIROYAL	Tyre :	OK	[x]	>6/	Rim :	/	Hubcap :	[x]	MISSING/INCOMPLETE	
Wheel RL :	[x]	UNIROYAL	Tyre :	OK	[x]	>6/	Rim :	/	Hubcap :	[x]	SCRATCHED	
Wheel FR :	[x]	UNIROYAL	Tyre :	[x]	OK	[x]	>6/	Rim :	/	Hubcap :	[x]	MISSING/INCOMPLETE
Wheel RR :	[x]	UNIROYAL	Tyre :	OK	[x]	>6/	Rim :	/	Hubcap :	[x]	SCRATCHED	
Wheel RES:	[x]		Tyre :	OK		/	Rim :	/	Hubcap :			

[x]	Width	Height	Type	Rim	Index
Front tyre	205	65	R	16	
Rear tyre	205	65	R	16	

Remark :

## Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

## STATUS: ACCEPTABLE / USAGE DAMAGE

### Bodywork \& windows

- [x] REAR DOOR/LEFT/CENTER DENT
- [x] FRONT MUDGUARD/RIGHT/FRONT SCRATCH WITH PAINT DAMAGE

## STATUS: NOT ACCEPTABLE

### Bodywork \& windows

[x]	REAR DOOR/RIGHT/RIGHT	SCRATCH WITH PAINT DAMAGE			
			<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>
					<b>Total</b>
5	0 LU =0.00 EUR		226.26 EUR		50 %
					226.26 EUR
[x]	REAR DOOR/RIGHT/CENTER	DENT			DEUR BESCHERMING
			<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>
					<b>Total</b>
4	0 LU =0.00 EUR		238.76 EUR		50 %
					238.76 EUR
[x]	FRONT BUMPER/RIGHT/SIDE	SCRATCH WITH PAINT DAMAGE			
	<b>Number</b>	<b>Code</b>	<b>Description</b>	<b>Unit price</b>	<b>Depr.</b>
					<b>Total</b>
3	I 1	i-vab-kunst-01	PLASTICS REPAIR	110.64 EUR	
					110.64 EUR

### Others

CLEANLINESS INTERIOR

Number	Code	Description	Unit price	Depr.	Total
1	I 2	specifiek-per-kwartier-a-vab-rein-03	CLEANING INTERIOR	14.58 EUR	
					29.16 EUR

HUB CAP FL

			<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>
2	0 LU =0.00 EUR				50 %	

HUB CAP REAR L

			<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>
2	0 LU =0.00 EUR				50 %	

HUB CAP REAR RIGHT

			<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>
2	0 LU =0.00 EUR				50 %	

HUB CAP FR

	Repair paint - LI	New paint - E	Depr.	Total
2 0 LU =0.00 EUR			50 %	

**Pieces**

Number	Code	Description	Unit price	Depr.	Total
2	1	WHEEL CAP	22.50 EUR	50 %	22.50 EUR
2	1	WHEEL CAP	22.50 EUR	50 %	22.50 EUR
2	1	WHEEL CAP	22.50 EUR	50 %	22.50 EUR
2	1	WHEEL CAP	22.50 EUR	50 %	22.50 EUR
4	1	SIDE PROTECTION	10.80 EUR	50 %	10.80 EUR

1	2	3	4	5	6	7	8	9	10
29.16	90.00	110.64	249.56	226.26	0	0	0	0	0
29.16	45.00	110.64	124.78	113.13	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
139.80	565.82	0	<b>705.62</b>
HOG: 0	BG: 3		NA Deprec. 422.71
			0.00%
			<b>TOTAL 422.71</b>

[x] = Status Modification

Pictures : No

## CIRCUMSTANCES

NORMAL CONCLUSION

<b>Extra Time :</b> 0 min	<b>Waiting time :</b> 0 min <b>Reason :</b>	<b>Towing time :</b> 0 min <b>Reason :</b>
<b>NOT EXECUTED :</b> No		
<b>Reason :</b>		
<b>Remark :</b>		

## Prices in EUR without VAT

<b>Authorized by customer :</b>  <b>Remark authorized customer :</b>  <b>Date :</b> 26/07/2017 <b>Hour :</b> 07:43 <b>Company :</b> Executed by VAB Fleet Services <b>E-Mail :</b> @	Executed by VAB Fleet Services
Signature authorized by customer  	