

COUDTH

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: DIRTY [x] EXT: CLEAN [x]
Owner :		Mileage :	110734 KM
File nr. :	1421546	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1FKD828 / VF17R040H48464213 /		yr of constructionr :	/
E-File nr. :		First registration :	24/07/2013
VFS-nr. :		Color :	BLACK
Make + Model :	RENAULT / CLIO BREAK	Fuel type :	DIESEL
Object nr. :		Fuel :	
Classification :		Environment Class:	EURO 5
Customer company :	EGEMIN NV	Co2:	95g/km
Driver :		Remote controls:	
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :		Seats (minivan) :	0
Vehicle type :	CLIO IV BRE Expression 75PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:	BREAK	Engine size:	1461
Gear box :	Manueel	Number of places:	5
Number of gears:	5	Number of doors:	5
HP:	75	kW:	55
Fisc HP		Imported vehicle:	
Animals transported:	Yes	Smoked in vehicle:	
Due date vehicle inspection:		Extra set of tires:	
		Use:	Unknown

General condition:

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:		Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :	
Warning vest :	OK	[x]	Transport licence :	
Tax certificate :			Navigation CD/SD/DVD	
Fuel card :			Car radio :	OK [x]
Mobile phone kit :			Extinguisher :	OK [x]
First aid kit :	OK	[x]	Warning triangle :	OK [x]
Jack, wheelspanner :	OK	[x]	Oil level :	OK [x]
			Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	[x]	BRIDGESTONE	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :		
Wheel RL :	[x]	BRIDGESTONE	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :	[x] SCRATCHED	
Wheel FR :	[x]	BRIDGESTONE	Tyre :	[x]	OK	[x]	2-4/	Rim :	/	Hubcap :	[x] SCRATCHED
Wheel RR :	[x]	BRIDGESTONE	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :	[x] SCRATCHED	
Wheel RES:	[x]		Tyre :	OK	/		Rim :	/	Hubcap :		

[x]	Width	Height	Type	Rim	Index
Front tyre	185	65	R	15	T
Rear tyre	185	65	R	15	T

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

- [x] REAR DOOR/LEFT/CENTER SCRATCH (WITHOUT PAINT DAMAGE)
- [x] FRONT DOOR/LEFT/CENTER SCRATCH (WITHOUT PAINT DAMAGE)
- [x] FRONT MUDGUARD/LEFT/FRONT SCRATCH (WITHOUT PAINT DAMAGE)
- [x] FRONT MUDGUARD/RIGHT/CENTER SCRATCH (WITHOUT PAINT DAMAGE)

STATUS: NOT ACCEPTABLE

Bodywork \& windows

- [x] REAR BUMPER/LEFT/LEFT SCRATCH WITH PAINT DAMAGE

Number	Code	Description	Unit price	Depr.	Total
6	I 1 i-vab-kunst-01	PLASTICS REPAIR	110.64 EUR		110.64 EUR
6	I 1 i-vab-sp-01	SPOTREPAIR	115.56 EUR		115.56 EUR

- [x] REAR MUDGUARD/LEFT/FRONT DENT

Number	Code	Description	Unit price	Depr.	Total
5	I 1 i-vab-uitd-01	BEAT OUT DENT	63.00 EUR		63.00 EUR
5	I 1 i-vab-uitd-02	BEAT OUT DENT SUPPL	19.80 EUR		19.80 EUR

- [x] REAR MUDGUARD/RIGHT/REAR DENT

	Repair paint - LI	New paint - E	Depr.	Total
7	0 LU =0.00 EUR	322.81 EUR	50 %	322.81 EUR

- [x] REAR DOOR/RIGHT/REAR DENT

Number	Code	Description	Unit price	Depr.	Total
8	I 1 i-vab-uitd-01	BEAT OUT DENT	63.00 EUR		63.00 EUR
8	I 1 i-vab-uitd-02	BEAT OUT DENT SUPPL	19.80 EUR		19.80 EUR
8	I 1 i-vab-uitd-02	BEAT OUT DENT SUPPL	19.80 EUR		19.80 EUR

[x]	ROOF /FRONT/LEFT/CENTER	OTHER DAMAGES			
		Repair paint - LI	New paint - E	Depr.	Total
4	0 LU =0.00 EUR	385.20 EUR			385.20 EUR

[x]	FRONT DOOR/RIGHT/CENTER	DENT			
	Number Code	Description	Unit price	Depr.	Total
9	I 1 i-vab-uitd-01	BEAT OUT DENT	63.00 EUR		63.00 EUR
9	I 1 i-vab-uitd-02	BEAT OUT DENT SUPPL	19.80 EUR		19.80 EUR

[x]	BONNET/CENTER/RIGHT	DENT			
		Repair paint - LI	New paint - E	Depr.	Total
3	0 LU =0.00 EUR	232.06 EUR			232.06 EUR

[x]	FRONT BUMPER/RIGHT	SCRATCH WITH PAINT DAMAGE			
		Repair paint - LI	New paint - E	Depr.	Total
2	0 LU =0.00 EUR	169.44 EUR		50 %	169.44 EUR

Others

CLEANLINESS INTERIOR

	Number Code	Description	Unit price	Depr.	Total
1	I 4 specifiek-per-kwartier-a-vab-rein-03	CLEANING INTERIOR	14.58 EUR		58.32 EUR

HUB CAP REAR L

		Repair paint - LI	New paint - E	Depr.	Total
10	0 LU =0.00 EUR				

HUB CAP REAR RIGHT

		Repair paint - LI	New paint - E	Depr.	Total
10	0 LU =0.00 EUR			50 %	

HUB CAP FR

		Repair paint - LI	New paint - E	Depr.	Total
10	0 LU =0.00 EUR			50 %	

Pieces

Number	Code	Description	Unit price	Depr.	Total
10	1	WHEEL CAP	24.00 EUR		24.00 EUR
Number	Code	Description	Unit price	Depr.	Total
10	1	WHEEL CAP	24.00 EUR	50 %	24.00 EUR
Number	Code	Description	Unit price	Depr.	Total
10	1	WHEEL CAP	24.00 EUR	50 %	24.00 EUR

1	2	3	4	5	6	7	8	9	10
58.32	169.44	232.06	385.20	82.80	226.20	322.81	102.60	82.80	72.00
58.32	84.72	232.06	385.20	82.80	226.20	161.40	102.60	82.80	48.00

INNOVATIVE	TRADITIONAL	GENERAL	
552.72	1181.51	0	1734.23
HOG: 0	BG: 1		NA Deprec. 1464.10
			0.00%
			TOTAL 1464.10

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

UNDER CONDITION - VEHICLE WET

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 24/07/2017 Hour : 16:28 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	