

EFFECTIVE     NOT EXECUTED     COLLECTION     DELIVERY

[x] = Status Modification

<b>Commissionar :</b>	KBC REMARKETING	<b>Cleanliness :</b>	INT: CLEAN [x] EXT: CLEAN [x]
<b>Owner :</b>		<b>Mileage :</b>	121119 KM
<b>File nr. :</b>	1422929	<b>Mileage start / arrival:</b>	0 / 0
<b>Reg number / Chassis / Ref :</b>		<b>Mileag ref. service :</b>	0
1FAH588 / VF1JZ14A648371831 /		<b>yr of constructionr :</b>	/
<b>E-File nr. :</b>		<b>First registration :</b>	06/05/2013
<b>VFS-nr. :</b>		<b>Color :</b>	SILVER
<b>Make + Model :</b>	RENAULT / SCENIC	<b>Fuel type :</b>	DIESEL
<b>Object nr. :</b>		<b>Fuel :</b>	
<b>Classification :</b>	N	<b>Environment Class:</b>	EURO 5
<b>Customer company :</b>	RTL Belgium sa	<b>Co2:</b>	105g/km
<b>Driver :</b>		<b>Remote controls:</b>	2
<b>Covering :</b>	TISSUE	<b>Number keys :</b>	2 [x]
<b>Vehicle kind :</b>	VEHICLE	<b>Seats (minivan) :</b>	0
<b>Vehicle type :</b>		<b>Country registration :</b>	BELGIUM

<b>VAT over the margin - car:</b>		<b>Metallic paint:</b>	Yes
<b>Variant car:</b>		<b>Engine size:</b>	1461
<b>Gear box :</b>	Manueel	<b>Number of places:</b>	5
<b>Number of gears:</b>	6	<b>Number of doors:</b>	5
<b>HP:</b>	110	<b>kW:</b>	81
<b>Fisc HP</b>		<b>Imported vehicle:</b>	
<b>Animals transported:</b>	No	<b>Smoked in vehicle:</b>	No
<b>Due date vehicle inspection:</b>		<b>Extra set of tires:</b>	No
		<b>Use:</b>	Unknown
<b>General condition:</b>			

Original registr. number :	OK	Service manual :	
Cert. of reg. / Part 1:		Cert. of conformity :	OK
Cert. of reg. copy / Part 2:	OK [x]	Insurance certificate :	
Warning vest :	OK [x]	Transport licence :	
Tax certificate :		Navigation CD/SD/DVD	OK [x]
Fuel card :		Car radio :	OK [x]
Mobile phone kit :		Extinguisher :	OK [x]
First aid kit :	OK [x]	Warning triangle :	OK [x]
Jack, wheelspanner :	OK [x]	Oil level :	OK [x]
		Filled up :	0

## Wheels and tyres: Summer tires

Wheel FL:	[x]	MICHELIN	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :	[x]	SCRATCHED	
Wheel RL :	[x]	MICHELIN	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :	[x]	SCRATCHED	
Wheel FR :	[x]	MICHELIN	Tyre :	[x]	OK	[x]	2-4/	Rim :	/	Hubcap :	[x]	SCRATCHED
Wheel RR :	[x]	MICHELIN	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :	[x]	SCRATCHED	
Wheel RES:	[x]		Tyre :	OK		/	Rim :	/	Hubcap :			

  

[x]	Width	Height	Type	Rim	Index
Front tyre	205	60	R	16	H
Rear tyre	205	60	R	16	H

Remark :

## Wheels and tyres:

Wheel FL:			Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RL :			Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel FR :			Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RR :			Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RES:			Tyre :	OK	/	Rim :	/	Hubcap :	

  

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

## STATUS: ACCEPTABLE / USAGE DAMAGE

### Bodywork \& windows

[x] REAR DOOR/RIGHT/FRONT DENT

[x] BONNET/CENTER/LEFT DENT

## STATUS: NOT ACCEPTABLE

### Bodywork \& windows

[x] REAR BUMPER/LEFT/LEFT SCRATCH WITH PAINT DAMAGE

	Repair paint - LI	New paint - E	Depr.	Total
3 0 LU =0.00 EUR	211.80 EUR		50 %	211.80 EUR

[x] FRONT DOOR/LEFT/REAR DENT

Number	Code	Description	Unit price	Depr.	Total
2	I 1 i-vab-uitd-01	BEAT OUT DENT	63.00 EUR		63.00 EUR

[x] FRONT DOOR/RIGHT/REAR DENT

Number	Code	Description	Unit price	Depr.	Total
4	I 1 i-vab-uitd-01	BEAT OUT DENT	63.00 EUR		63.00 EUR

### Interior

[x] DASHBORD CARVED

Number	Code	Description	Unit price	Depr.	Total
1	I 1 i-vab-intdash-01	PLASTICS REPAIR INTERIRO	110.64 EUR		110.64 EUR

[x] CENTER CONSOLE CARVED

Number	Code	Description	Unit price	Depr.	Total
1	I 1 i-vab-intdash-01	PLASTICS REPAIR INTERIRO	110.64 EUR		110.64 EUR

### Others

HUB CAP FL

	Repair paint - LI	New paint - E	Depr.	Total
5 0 LU =0.00 EUR			50 %	

HUB CAP FR

	Repair paint - LI	New paint - E	Depr.	Total
5 0 LU =0.00 EUR			50 %	

<b>Pieces</b>
---------------

Number	Code	Description	Unit price	Depr.	Total
5	1	WHEEL CAP	30.00 EUR	50 %	30.00 EUR
Number	Code	Description	Unit price	Depr.	Total
5	1	WHEEL CAP	30.00 EUR	50 %	30.00 EUR

1	2	3	4	5	6	7	8	9	10
221.28	63.00	211.80	63.00	60.00	0	0	0	0	0
221.28	63.00	105.90	63.00	30.00	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
347.28	271.80	0	<b>619.08</b>
HOG: 0	BG: 0		NA Deprec. 483.18
			0.00%
			<b>TOTAL 483.18</b>

[x] = Status Modification

Pictures : No

## CIRCUMSTANCES

NORMAL CONCLUSION

<b>Extra Time :</b> 0 min	<b>Waiting time :</b> 0 min <b>Reason :</b>	<b>Towing time :</b> 0 min <b>Reason :</b>
<b>NOT EXECUTED :</b> No		
<b>Reason :</b>		
<b>Remark :</b>		

## Prices in EUR without VAT

<b>Authorized by customer :</b>  <b>Remark authorized customer :</b>  <b>Date :</b> 27/07/2017 <b>Hour :</b> 14:09 <b>Company :</b> Executed by VAB Fleet Services <b>E-Mail :</b> @	Executed by VAB Fleet Services
Signature authorized by customer 	