

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: DIRTY [x] EXT: DIRTY [x]
Owner :		Mileage :	154787 KM
File nr. :	1423838	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
BH7329 / VF3LB9HPAES069097 /		yr of constructionr :	/
E-File nr. :		First registration :	05/05/2014
VFS-nr. :		Color :	BLACK
Make + Model :	PEUGEOT / 308	Fuel type :	DIESEL
Object nr. :	ONBEKEND	Fuel :	
Classification :		Environment Class:	
Customer company :	ONBEKEND	Co2:	g/km
Driver :		Remote controls:	1
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	0
Vehicle type :		Country registration :	LUXEMBOURG

VAT over the margin - car:		Metallic paint:	Yes
Variant car:		Engine size:	1560
Gear box :	Manueel	Number of places:	5
Number of gears:	5	Number of doors:	5
HP:	92	kW:	68
Fisc HP		Imported vehicle:	
Animals transported:		Smoked in vehicle:	
Due date vehicle inspection:		Extra set of tires:	
		Use:	Unknown
General condition:			

Original registr. number :		Service manual :	
Cert. of reg. / Part 1:		Cert. of conformity :	
Cert. of reg. copy / Part 2:		Insurance certificate :	
Warning vest :	OK [x]	Transport licence :	
Tax certificate :		Navigation CD/SD/DVD	
Fuel card :		Car radio :	
Mobile phone kit :		Extinguisher :	OK [x]
		Warning triangle :	OK [x]
First aid kit :	OK [x]	Oil level :	OK [x]
Jack, wheelspanner :	OK [x]	Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	[x]	MICHELIN	Tyre :	OK [x]	2-4/	Rim :	/	Hubcap :	
Wheel RL :	[x]	MICHELIN	Tyre :	OK [x]	2-4/	Rim :	/	Hubcap :	
Wheel FR :	[x]	MICHELIN	Tyre :	[x] OK [x]	2-4/	Rim :	[x] WHEEL SCRATCHED	Hubcap :	
Wheel RR :	[x]	MICHELIN	Tyre :	OK [x]	2-4/	Rim :	/	Hubcap :	
Wheel RES:	[x]		Tyre :	OK [x]	>6/	Rim :	/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	205	55	R	16	W
Rear tyre	205	55	R	16	W

Remark :

Wheels and tyres:

Wheel FL:			Tyre :	OK /	Rim :	/	Hubcap :	
Wheel RL :			Tyre :	OK /	Rim :	/	Hubcap :	
Wheel FR :			Tyre :	OK /	Rim :	/	Hubcap :	
Wheel RR :			Tyre :	OK /	Rim :	/	Hubcap :	
Wheel RES:			Tyre :	OK /	Rim :	/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x]	REAR DOOR/CENTER/LEFT	SCRATCH (WITHOUT PAINT DAMAGE)
[x]	ROOF/CENTER/RIGHT	SCRATCH (WITHOUT PAINT DAMAGE)
[x]	REAR DOOR/RIGHT/FRONT	DENT
[x]	FRONT DOOR/LEFT/REAR	SCRATCH WITH PAINT DAMAGE
[x]	BONNET/CENTER/LEFT/FRONT	CHIPS
[x]	FRONT BUMPER/CENTER/RIGHT	CHIPS

Interior

[x]	DOOR IN REAR RIGHT	CARVED
-----	--------------------	--------

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR BUMPER/CENTER/LEFT	SCRATCH WITH PAINT DAMAGE			
		Repair paint - LI	New paint - E	Depr.	Total
3	0 LU =0.00 EUR	211.80 EUR		50 %	211.80 EUR
[x]	REAR MUDGUARD/LEFT/CENTER	DENT			
	Number Code	Description	Unit price	Depr.	Total
2	I 1 i-vab-uitd-01	BEAT OUT DENT	63.00 EUR		63.00 EUR
[x]	FRONT DOOR/RIGHT/CENTER	SCRATCH WITH PAINT DAMAGE		X2 DEUKEN	
		Repair paint - LI	New paint - E	Depr.	Total
4	15 LU =72.00 EUR	318.35 EUR		50 %	390.35 EUR

Others

CLEANLINESS INTERIOR

	Number Code	Description	Unit price	Depr.	Total
1	I 4 personenwagen-a-vab-rein-02	CLEANING INTERIOR	11.47 EUR		45.88 EUR

RIM FRONT RIGHT

	Number Code	Description	Unit price	Depr.	Total
5	I 1 i-vab-herstalu-02	REPAIR ALLOY WHEEL	95.00 EUR		95.00 EUR

1	2	3	4	5	6	7	8	9	10
45.88	63.00	211.80	390.35	95.00	0	0	0	0	0
45.88	63.00	105.90	195.18	95.00	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
203.88	602.15	0	806.03
HOG: 0	BG: 0		NA Deprec. 504.96
			0.00%
			TOTAL 504.96

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 26/07/2017 Hour : 15:42 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	