

C14RKN

EFFECTIVE     NOT EXECUTED                       COLLECTION                       DELIVERY

[x] = Status Modification

<b>Commissionar :</b>	KBC REMARKETING	<b>Cleanliness :</b>	INT: DIRTY [x] EXT: CLEAN [x]
<b>Owner :</b>		<b>Mileage :</b>	81066 KM
<b>File nr. :</b>	1421816	<b>Mileage start / arrival:</b>	0 / 0
<b>Reg number / Chassis / Ref :</b>		<b>Mileag ref. service :</b>	0
1ARJ438 / VF1FW1AB545018325 /		<b>yr of constructionr :</b>	/
<b>E-File nr. :</b>		<b>First registration :</b>	09/03/2011
<b>VFS-nr. :</b>		<b>Color :</b>	WHITE
<b>Make + Model :</b>	RENAULT / KANGOO EXPRESS	<b>Fuel type :</b>	DIESEL
<b>Object nr. :</b>	47822	<b>Fuel :</b>	
<b>Classification :</b>		<b>Environment Class:</b>	EURO 4
<b>Customer company :</b>	DALKIA SA<ID>2229924</ID>	<b>Co2:</b>	140g/km
<b>Driver :</b>		<b>Remote controls:</b>	1
<b>Covering :</b>	TISSUE	<b>Number keys :</b>	1 [x]
<b>Vehicle kind :</b>	-	<b>Seats (minivan) :</b>	0
<b>Vehicle type :</b>	KANGOO Expr. Gr.Confort 68PK	<b>Country registration :</b>	BELGIUM

<b>VAT over the margin - car:</b>	No	<b>Metallic paint:</b>	Yes
<b>Variant car:</b>	BESTELWAGEN	<b>Engine size:</b>	1461
<b>Gear box :</b>	Manueel	<b>Number of places:</b>	2
<b>Number of gears:</b>	5	<b>Number of doors:</b>	5
<b>HP:</b>	68	<b>kW:</b>	50
<b>Fisc HP</b>		<b>Imported vehicle:</b>	No
<b>Animals transported:</b>	No	<b>Smoked in vehicle:</b>	No
<b>Due date vehicle inspection:</b>		<b>Extra set of tires:</b>	No
		<b>Use:</b>	Unknown

**General condition:**

Original registr. number :	OK	Service manual :	OK	[x]
Cert. of reg. / Part 1:		Cert. of conformity :	OK	
Cert. of reg. copy / Part 2:	OK	[x]	Insurance certificate :	
Warning vest :	OK	[x]	Transport licence :	
Tax certificate :			Navigation CD/SD/DVD	
Fuel card :			Car radio :	OK [x]
Mobile phone kit :			Extinguisher :	OK [x]
First aid kit :	OK	[x]	Warning triangle :	OK [x]
Jack, wheelspanner :			Oil level :	OK [x]
			Filled up :	0

## Wheels and tyres: Summer tires

Wheel FL:	[x]	GOODYEAR	Tyre :	OK	[x]	>6/	Rim :	/	Hubcap :	
Wheel RL :	[x]	GOODYEAR	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :	
Wheel FR :	[x]	GOODYEAR	Tyre :	[x]	OK	[x]	>6/	Rim :	/	Hubcap :
Wheel RR :	[x]	GOODYEAR	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :	
Wheel RES:	[x]		Tyre :	OK		/	Rim :	/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	195	65	R	15	
Rear tyre	195	65	R	15	

Remark :

## Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

## STATUS: NOT ACCEPTABLE

### Bodywork \& windows

[x]	REAR BUMPER/CENTER/LEFT		DENT			
	<b>Number</b>	<b>Code</b>	<b>Description</b>	<b>Unit price</b>	<b>Depr.</b>	<b>Total</b>
4	I 1	i-vab-kunst-01	PLASTICS REPAIR	110.64 EUR		110.64 EUR
[x]	REAR MUDGUARD/RIGHT/FRONT		SCRATCH WITH PAINT DAMAGE			
			<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>
5	0 LU =0.00 EUR		231.15 EUR		50 %	231.15 EUR
[x]	REAR DOOR/RIGHT/REAR		DENT			
			<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>
5	0 LU =0.00 EUR		0 EUR		50 %	
			<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>
5	80 LU =384.00 EUR		0 EUR	326.78 EUR	50 %	710.78 EUR
[x]	ROOF/FRONT/CENTER/RIGHT		SCRATCH WITH PAINT DAMAGE		+DEUK	
			<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>
8	0 LU =0.00 EUR		361.13 EUR		50 %	361.13 EUR
[x]	WINDSCREEN/CENTER/LEFT		SCRATCH WITH PAINT DAMAGE			
			<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>
2	0 LU =0.00 EUR		0 EUR		50 %	
			<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>
2	25 LU =120.00 EUR		0 EUR		50 %	120.00 EUR
[x]	WINDOW STYLE FRONT DOOR/RIGHT/REAR		DENT			
	<b>Number</b>	<b>Code</b>	<b>Description</b>	<b>Unit price</b>	<b>Depr.</b>	<b>Total</b>
0	0					
[x]	FRONT DOOR/RIGHT/REAR		DENT			
			<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>
6	0 LU =0.00 EUR		238.76 EUR		50 %	238.76 EUR
[x]	FRONT DOOR/RIGHT/FRONT		SCRATCH WITH PAINT DAMAGE		+DEUK	
	<b>Number</b>	<b>Code</b>	<b>Description</b>	<b>Unit price</b>	<b>Depr.</b>	<b>Total</b>
0	0					

[x]	FRONT MUDGUARD/RIGHT/CENTER		SCRATCH WITH PAINT DAMAGE		
		<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>
7	0 LU =0.00 EUR	165.13 EUR		50 %	165.13 EUR

## Interior

[x]	SEAT FL		HOLE			
	<b>Number</b>	<b>Code</b>	<b>Description</b>	<b>Unit price</b>	<b>Depr.</b>	<b>Total</b>
9	I 1	i-vab-intvnl-01	VINYL REPAIR	82.20 EUR		82.20 EUR

## Accessories and others

[x]	OUTSIDE MIRROR LEFTHAND SIDE		SCRATCH WITH PAINT DAMAGE		
		<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>
3	0 LU =0.00 EUR	0 EUR		50 %	

[x]	OUTSIDE MIRROR RIGHTHAND SIDE		SCRATCH WITH PAINT DAMAGE		
		<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>
3	0 LU =0.00 EUR	0 EUR		50 %	

## Others

CLEANLINESS INTERIOR

	<b>Number</b>	<b>Code</b>	<b>Description</b>	<b>Unit price</b>	<b>Depr.</b>	<b>Total</b>
1	I 4	specifiek-per-kwartier-a-vab-rein-03	CLEANING INTERIOR	14.58 EUR		58.32 EUR

## Pieces

	<b>Number</b>	<b>Code</b>	<b>Description</b>	<b>Unit price</b>	<b>Depr.</b>	<b>Total</b>
2	1		WIND SCREEN	275.40 EUR	50 %	275.40 EUR
	<b>Number</b>	<b>Code</b>	<b>Description</b>	<b>Unit price</b>	<b>Depr.</b>	<b>Total</b>
3	1		MIRROR COVER	90.00 EUR	50 %	90.00 EUR
	<b>Number</b>	<b>Code</b>	<b>Description</b>	<b>Unit price</b>	<b>Depr.</b>	<b>Total</b>
3	1		MIRROR COVER	90.00 EUR	50 %	90.00 EUR
	<b>Number</b>	<b>Code</b>	<b>Description</b>	<b>Unit price</b>	<b>Depr.</b>	<b>Total</b>
5	1		DOOR REAR RIGHT	275.40 EUR	50 %	275.40 EUR

<b>1</b>	<b>2</b>	<b>3</b>	<b>4</b>	<b>5</b>	<b>6</b>	<b>7</b>	<b>8</b>	<b>9</b>	<b>10</b>
58.32	395.40	180.00	110.64	1217.33	238.76	165.13	361.13	82.20	0
58.32	197.70	90.00	110.64	608.66	119.38	82.56	180.56	82.20	0

INNOVATIVE	TRADITIONAL	GENERAL	
251.16	2557.75	0	<b>2808.91</b>
HOG: 0	BG: 3		NA Deprec. 1530.04
			0.00%
			<b>TOTAL 1530.04</b>

[x] = Status Modification

Pictures : No

## CIRCUMSTANCES

NORMAL CONCLUSION

<b>Extra Time :</b> 0 min	<b>Waiting time :</b> 0 min <b>Reason :</b>	<b>Towing time :</b> 0 min <b>Reason :</b>
<b>NOT EXECUTED :</b> No		
<b>Reason :</b>		
<b>Remark :</b>		

## Prices in EUR without VAT

<b>Authorized by customer :</b>  <b>Remark authorized customer :</b>  <b>Date :</b> 26/07/2017 <b>Hour :</b> 09:42 <b>Company :</b> Executed by VAB Fleet Services <b>E-Mail :</b> @	Executed by VAB Fleet Services
Signature authorized by customer  	