

C3TRWO

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: CLEAN [x] EXT: CLEAN [x]
Owner :		Mileage :	134859 KM
File nr. :	1423831	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
AT7553 / VF30ERHE8DS127628 /		yr of constructionr :	/
E-File nr. :		First registration :	10/07/2013
VFS-nr. :		Color :	SILVER
Make + Model :	PEUGEOT / 5008	Fuel type :	DIESEL
Object nr. :		Fuel :	
Classification :		Environment Class:	
Customer company :	Orange Business Luxembourg SA	Co2:	g/km
Driver :		Remote controls:	2
Covering :	LEATHER	Number keys :	2 [x]
Vehicle kind :	VEHICLE	Seats (minivan) :	7 [x]
Vehicle type :	5008 Allure FAP 150PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	Yes
Variant car:	MONOVOLUME	Engine size:	1997
Gear box :	Manueel	Number of places:	7
Number of gears:	6	Number of doors:	5
HP:	150	kW:	110
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown

General condition:

Original registr. number :		Service manual :	
Cert. of reg. / Part 1:		Cert. of conformity :	
Cert. of reg. copy / Part 2:		Insurance certificate :	
Warning vest :	OK [x]	Transport licence :	
Tax certificate :		Navigation CD/SD/DVD	OK [x]
Fuel card :		Car radio :	OK [x]
Mobile phone kit :		Extinguisher :	OK [x]
First aid kit :	OK [x]	Warning triangle :	OK [x]
Jack, wheelspanner :	OK [x]	Oil level :	OK [x]
		Filled up :	0

Wheels and tyres: Winter tires

Wheel FL:	[x]	MICHELIN	Tyre :	OK	[x]	2-4/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :	
Wheel RL :	[x]	MICHELIN	Tyre :	OK	[x]	2-4/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :	
Wheel FR :	[x]	MICHELIN	Tyre :	[x]	OK	[x]	2-4/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :
Wheel RR :	[x]	MICHELIN	Tyre :	OK	[x]	2-4/	Rim :	[x]	WHEEL SCRATCHED	/	Hubcap :	
Wheel RES:	[x]		Tyre :	OK		/	Rim :			/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	215	50	R	17	M+S
Rear tyre	215	50	R	17	M+S

Remark :

Wheels and tyres:

Wheel FL:		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RL :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel FR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RR :		Tyre :	OK	/	Rim :		/	Hubcap :
Wheel RES:		Tyre :	OK	/	Rim :		/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

- [x] FRONT DOOR/LEFT/CENTER SCRATCH WITH PAINT DAMAGE
- [x] FRONT BUMPER/CENTER/LEFT SCRATCH WITH PAINT DAMAGE

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x]	REAR DOOR/RIGHT/FRONT		DENT		
		Repair paint - LI	New paint - E	Depr.	Total
1	0 LU =0.00 EUR	318.35 EUR		50 %	318.35 EUR

Interior

[x]	BOOT LID IN		CARVED			
	Number	Code	Description	Unit price	Depr.	Total
0	0					

1	2	3	4	5	6	7	8	9	10
318.35	0	0	0	0	0	0	0	0	0
159.18	0	0	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
0	318.35	0	318.35
HOG: 0	BG: 0		NA Deprec. 159.18
			0.00%
			TOTAL 159.18

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 26/07/2017 Hour : 15:52 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	