

EFFECTIVE NOT EXECUTED COLLECTION DELIVERY

[x] = Status Modification

Commissionar :	KBC REMARKETING	Cleanliness :	INT: DIRTY [x] EXT: CLEAN [x]
Owner :		Mileage :	125224 KM
File nr. :	1422767	Mileage start / arrival:	0 / 0
Reg number / Chassis / Ref :		Mileag ref. service :	0
1BID538 / VF1FW1AB545018328 /		yr of constructionr :	/
E-File nr. :		First registration :	07/06/2011
VFS-nr. :		Color :	WHITE
Make + Model :	RENAULT / KANGOO EXPRESS	Fuel type :	DIESEL
Object nr. :	47822	Fuel :	
Classification :		Environment Class:	EURO 4
Customer company :	DALKIA SA<ID>2229924</ID>	Co2:	140g/km
Driver :		Remote controls:	2
Covering :	TISSUE	Number keys :	2 [x]
Vehicle kind :	TRUCK, LORRY	Seats (minivan) :	0
Vehicle type :	KANGOO Expr. Gr.Confort 68PK	Country registration :	BELGIUM

VAT over the margin - car:	No	Metallic paint:	
Variant car:	BESTELWAGEN	Engine size:	1461
Gear box :	Manueel	Number of places:	5
Number of gears:	5	Number of doors:	5
HP:	68	kW:	50
Fisc HP		Imported vehicle:	
Animals transported:	No	Smoked in vehicle:	No
Due date vehicle inspection:		Extra set of tires:	No
		Use:	Unknown
General condition:			

Original registr. number :	OK	Service manual :	[x]
Cert. of reg. / Part 1:		Cert. of conformity :	OK
Cert. of reg. copy / Part 2:	OK [x]	Insurance certificate :	
Warning vest :	OK [x]	Transport licence :	
Tax certificate :		Navigation CD/SD/DVD	
Fuel card :		Car radio :	OK [x]
Mobile phone kit :		Extinguisher :	OK [x]
First aid kit :	OK [x]	Warning triangle :	OK [x]
Jack, wheelspanner :	OK [x]	Oil level :	OK [x]
		Filled up :	0

Wheels and tyres: Summer tires

Wheel FL:	[x]	UNIROYAL	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :	
Wheel RL :	[x]	UNIROYAL	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :	
Wheel FR :	[x]	UNIROYAL	Tyre :	[x]	OK	[x]	2-4/	Rim :	/	Hubcap :
Wheel RR :	[x]	UNIROYAL	Tyre :	OK	[x]	2-4/	Rim :	/	Hubcap :	
Wheel RES:	[x]		Tyre :	OK		/	Rim :	/	Hubcap :	

[x]	Width	Height	Type	Rim	Index
Front tyre	195	65	R	15	T
Rear tyre	195	65	R	15	T

Remark :

Wheels and tyres:

Wheel FL:			Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RL :			Tyre :	OK	/	Rim :	/	Hubcap :
Wheel FR :			Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RR :			Tyre :	OK	/	Rim :	/	Hubcap :
Wheel RES:			Tyre :	OK	/	Rim :	/	Hubcap :

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

STATUS: ACCEPTABLE / USAGE DAMAGE

Bodywork \& windows

[x] REAR MUDGUARD/CENTER/LEFT DENT

Interior

[x] FLOOR FL CUT / TORN

Accessories and others

[x] VEH COVERED WITH STICKERS STICKER(S)

STATUS: NOT ACCEPTABLE

Bodywork \& windows

[x] REAR MUDGUARD/LEFT/CENTER DENT

	Repair paint - LI	New paint - E	Depr.	Total
2 0 LU =0.00 EUR	231.15 EUR		50 %	231.15 EUR

[x] BONNET/CENTER/RIGHT/FRONT DENT

	Repair paint - LI	New paint - E	Depr.	Total
3 0 LU =0.00 EUR	217.56 EUR		50 %	217.56 EUR

Interior

[x] SEAT FL CUT / TORN

	Repair paint - LI	New paint - E	Depr.	Total
1 25 LU =120.00 EUR	0 EUR		50 %	120.00 EUR

[x] ROOF UPHOLSTERY OTHER DAMAGES

Number	Code	Description	Unit price	Depr.	Total
1	I 2	i-vab-ander-01	REPAIR (PER 15')	18.74 EUR	37.48 EUR

Pieces

Number	Code	Description	Unit price	Depr.	Total
1	1	SEAT UPHOLSTERY TISSUE	90.00 EUR	50 %	90.00 EUR

1	2	3	4	5	6	7	8	9	10
247.48	231.15	217.56	0	0	0	0	0	0	0
142.48	115.58	108.78	0	0	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
37.48	658.71	0	696.19
HOG: 0	BG: 3		NA Deprec. 366.84
			0.00%
			TOTAL 366.84

[x] = Status Modification

Pictures : No

CIRCUMSTANCES

NORMAL CONCLUSION

Extra Time : 0 min	Waiting time : 0 min Reason :	Towing time : 0 min Reason :
NOT EXECUTED : No		
Reason :		
Remark :		

Prices in EUR without VAT

Authorized by customer : Remark authorized customer : Date : 26/07/2017 Hour : 09:49 Company : Executed by VAB Fleet Services E-Mail : @	Executed by VAB Fleet Services
Signature authorized by customer 	