

EFFECTIVE     NOT EXECUTED                       COLLECTION                       DELIVERY

[x] = Status Modification

<b>Commissionar :</b>	KBC REMARKETING	<b>Cleanliness :</b>	INT: CLEAN [x] EXT: CLEAN [x]
<b>Owner :</b>		<b>Mileage :</b>	113942 KM
<b>File nr. :</b>	1422245	<b>Mileage start / arrival:</b>	0 / 0
<b>Reg number / Chassis / Ref :</b>		<b>Mileag ref. service :</b>	0
1GXC612 / VF1KZ140650816399 /		<b>yr of constructionr :</b>	/
<b>E-File nr. :</b>		<b>First registration :</b>	23/05/2014
<b>VFS-nr. :</b>		<b>Color :</b>	BLACK
<b>Make + Model :</b>	RENAULT / MEGANE BREAK	<b>Fuel type :</b>	DIESEL
<b>Object nr. :</b>	53509	<b>Fuel :</b>	
<b>Classification :</b>	B	<b>Environment Class:</b>	EURO 5
<b>Customer company :</b>	ERICSSON NETWORK SERVICES BV	<b>Co2:</b>	90g/km
<b>Driver :</b>		<b>Remote controls:</b>	2
<b>Covering :</b>	TISSUE	<b>Number keys :</b>	2 [x]
<b>Vehicle kind :</b>	VEHICLE	<b>Seats (minivan) :</b>	0
<b>Vehicle type :</b>		<b>Country registration :</b>	BELGIUM

<b>VAT over the margin - car:</b>		<b>Metallic paint:</b>	Yes
<b>Variant car:</b>	BREAK	<b>Engine size:</b>	1461
<b>Gear box :</b>	Manueel	<b>Number of places:</b>	5
<b>Number of gears:</b>	6	<b>Number of doors:</b>	5
<b>HP:</b>	110	<b>kW:</b>	81
<b>Fisc HP</b>		<b>Imported vehicle:</b>	
<b>Animals transported:</b>	No	<b>Smoked in vehicle:</b>	No
<b>Due date vehicle inspection:</b>		<b>Extra set of tires:</b>	No
		<b>Use:</b>	Unknown

**General condition:**

Original registr. number :	OK	Service manual :	
Cert. of reg. / Part 1:	OK [x]	Cert. of conformity :	OK
Cert. of reg. copy / Part 2:		Insurance certificate :	
Warning vest :	OK [x]	Transport licence :	
Tax certificate :		Navigation CD/SD/DVD	OK [x]
Fuel card :		Car radio :	OK [x]
Mobile phone kit :		Extinguisher :	OK [x]
First aid kit :	OK [x]	Warning triangle :	OK [x]
Jack, wheelspanner :	OK [x]	Oil level :	OK [x]
		Filled up :	0

## Wheels and tyres: Winter tires

Wheel FL:	[x]	MICHELIN	Tyre :	OK [x]	2-4/	Rim :	/	Hubcap :	[x]	SCRATCHED	
Wheel RL :	[x]	MICHELIN	Tyre :	OK [x]	2-4/	Rim :	/	Hubcap :	[x]	SCRATCHED	
Wheel FR :	[x]	MICHELIN	Tyre :	[x]	OK [x]	2-4/	Rim :	/	Hubcap :	[x]	SCRATCHED
Wheel RR :	[x]	MICHELIN	Tyre :	OK [x]	2-4/	Rim :	/	Hubcap :	[x]	SCRATCHED	
Wheel RES:	[x]		Tyre :	OK	/	Rim :	/	Hubcap :			

  

[x]	Width	Height	Type	Rim	Index
Front tyre	205	55	R	16	M+S
Rear tyre	205	55	R	16	M+S

Remark :

## Wheels and tyres:

Wheel FL:			Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RL :			Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel FR :			Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RR :			Tyre :	OK	/	Rim :	/	Hubcap :	
Wheel RES:			Tyre :	OK	/	Rim :	/	Hubcap :	

  

[x]	Width	Height	Type	Rim	Index
Front tyre	0	0	R	0	
Rear tyre	0	0	R	0	

Remark :

## STATUS: ACCEPTABLE / USAGE DAMAGE

### Bodywork \& windows

- [x] REAR MUDGUARD/LEFT/FRONT SCRATCH WITH PAINT DAMAGE
- [x] REAR DOOR/LEFT/REAR SCRATCH (WITHOUT PAINT DAMAGE)

### Interior

- [x] DASHBORD CARVED

## STATUS: NOT ACCEPTABLE

### Bodywork \& windows

[x]	REAR WINDOW/LEFT		SCRATCH WITH PAINT DAMAGE					
		<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>			
4	25 LU =120.00 EUR	0 EUR		50 %	120.00 EUR			
[x]	REAR MUDGUARD/RIGHT/CENTER		SCRATCH WITH PAINT DAMAGE					
		<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>			
3	0 LU =0.00 EUR	308.20 EUR		50 %	308.20 EUR			
[x]	ROOF/CENTER/LEFT		OTHER DAMAGES			CHEMISCHE INWERKING		
		<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>			
2	0 LU =0.00 EUR	481.50 EUR		50 %	481.50 EUR			
[x]	BONNET/CENTER/RIGHT		OTHER DAMAGES			CHEMISCHE INWERKING		
		<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>			
2	0 LU =0.00 EUR	290.08 EUR		50 %	290.08 EUR			
[x]	LIGHTS/RIGHT/FRONT		HOLE/CRACK/TORN					
		<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>			
1	5 LU =24.00 EUR	0 EUR		50 %	24.00 EUR			

### Others

	HUB CAP FL							
		<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>			
5	0 LU =0.00 EUR			50 %				
	HUB CAP FR							
		<b>Repair paint - LI</b>	<b>New paint - E</b>	<b>Depr.</b>	<b>Total</b>			
5	0 LU =0.00 EUR			50 %				

**Pieces**

Number	Code	Description	Unit price	Depr.	Total
1	1	DRL	30.00 EUR	50 %	30.00 EUR
Number	Code	Description	Unit price	Depr.	Total
4	1	BACK WINDOW	250.00 EUR	50 %	250.00 EUR
Number	Code	Description	Unit price	Depr.	Total
5	1	WHEEL CAP	30.00 EUR	50 %	30.00 EUR
Number	Code	Description	Unit price	Depr.	Total
5	1	WHEEL CAP	30.00 EUR	50 %	30.00 EUR

1	2	3	4	5	6	7	8	9	10
54.00	771.58	308.20	370.00	60.00	0	0	0	0	0
27.00	385.79	154.10	185.00	30.00	0	0	0	0	0

INNOVATIVE	TRADITIONAL	GENERAL	
0	1563.78	0	<b>1563.78</b>
HOG: 0	BG: 0		NA Deprec. 781.89
			0.00%
			<b>TOTAL 781.89</b>

[x] = Status Modification

Pictures : No

## CIRCUMSTANCES

NORMAL CONCLUSION

<b>Extra Time :</b> 0 min	<b>Waiting time :</b> 0 min <b>Reason :</b>	<b>Towing time :</b> 0 min <b>Reason :</b>
<b>NOT EXECUTED :</b> No		
<b>Reason :</b>		
<b>Remark :</b>		

## Prices in EUR without VAT

<b>Authorized by customer :</b>  <b>Remark authorized customer :</b>  <b>Date :</b> 26/07/2017 <b>Hour :</b> 12:38 <b>Company :</b> Executed by VAB Fleet Services <b>E-Mail :</b> @	Executed by VAB Fleet Services
Signature authorized by customer 	